

Douglas County Surveyor's Record of
Government Corners Renewed

T 21 T.S. R 10 R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 91851

89
1/4 Corner for Sections 15 and 22.
Found - 24" original corner tree. Found 1" iron pipe with 2 1/2" brass cap on SW side of tree, properly marked. (1918)
16" D. fir, partially knocked over, bears S.50°E., 15.8 ft. healed scar.
Set - 2 1/2" x 30" alum. pipe as reference monument, 24" in the ground bears S.45°W., 4.0 ft. from corner tree, with 3 1/4" brass cap mkd. "US Dep of Agri-Forest Service RM T21S R10W 1/4 S15 S22 N.45°E 4.0 ft. RLS 1651 1983 Unlawful to Disturb".
New BTs - 12" alder bears N.62°E., 57.0 ft. bark scribed "1/4 S15 BT".
14" hemlock bears S.17°W., 24.1 ft. blazed and scribed "1/4 S22 BT".

90
Section corner for Secs. 14 and 23 only.
Found - 2" rusted pipe and concrete stem with 1919 GLO brass cap, broken off alongside pipe, properly marked.
14" hemlock bears N.57°E., 8.7 ft. healed face.
34" D. fir bears S.33°E., 10.8 ft. healed face.
Set - At location of GLO pipe, set 2 1/2" x 30" alum. pipe 24" in the ground with 3 1/4" alum. cap mkd. "US Dep of Agri-Forest Service T21S R10W S14 S23 RLS 1651 1983 Unlawful to Disturb".

91
Witness corner for Section corner, Secs. 15 and 22 only.
Found - 60" cedar bears N.44°E., 38.9 ft. to face, healed face. (1879)
60" cedar bears N.56°W., 33.0 ft. to face, healed face. (1919)
Corner position falls in a recent active slide area.
Set - Witness corner 52.35 ft. west of corner on line.
Set - 2 1/2" x 30" alum. pipe, 24" in the ground with 3 1/4" alum. cap mkd. "US Dep of Agri-Forest Service T21S R10W WC S15 S22 RLS 1651 1983 Unlawful to Disturb".
New BTs - 18" hemlock bears N.50°W., 27.6 ft. scribed "WC T21S R10W S15 BT"
24" hemlock bears S.32°E., 41.0 ft. faced and scribed "WC T21S R10W S22 BT".

92
1/4 Corner for Sections 21 and 22.
Found - 24" big leaf maple bears N.45°W., 26.4 ft. healed face.
30" fir, blowdown, healed face. Root hole bears N.14°E., 26.4 ft.
Set - 2 1/2" x 30" alum. pipe, 24" in the ground, with 3 1/4" alum. cap marked "US Dep of Agri-Forest Service T21S R10W 1/4 S21 S22 1983 RLS 1651 Unlawful to Disturb".
New BT - 14" hemlock bears N.40°E., 47.6 ft. faced and scribed "1/4 S22 BT".

93
West 1/4 Corner for Section 23 only.
Set - 2 1/2" x 30" alum. pipe, 27" in the ground, with 3" alum. cap mkd. "US Dep of Agri-Fores Service T21S R10W 1/4 S23 RLS 1651 1983 Unlawful to Disturb".
New BTs - 24" hemlock bears S.52°E., 6.1 ft. faced and scribed "1/4 S23 BT".
42" hemlock bears N.14°E., 20.5 ft. faced and scribed "1/4 S23 BT".

94
East 1/4 Corner for Section 22 only.
Found - 2" pipe filled with concrete badly rusted. Brass cap broken off and gone. (1919)
64" D. fir bears S.76°E., 40.9 ft. healed face.
10" chittam wood, blown down, bears S.87°E., 5.0 ft. +, rotted face.
Set - At location of broken pipe, set 2 1/2" x 30" alum. pipe, 26" in the ground, with 3" alum. cap mkd. "US Dep of Agri-Forest Service T21S R10W 1/4 S22 RLS 1651 1983 Unlawful to Disturb"
New BT - 10" hemlock bears S.40°W., 23.8 ft. faced and scribed "1/4 S22 BT".

Herman A. Pieske, RLS #1651
For: Siuslaw National Forest USDA
December 1983
M 95 - 80 A & B

FOOK
12/19/1 ROBERTS
M 114-28
C.S. 43/138