

**Douglas County Surveyor's Record of
Government Corners Renewed**

T. 21 S. T.S. R. 10 W. R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

95

Tom McCullough, LS#650
Timberland/McCullough
P.O. Box 668
Albany, OR 97321
1970
C.S. 58/290

Closing Corner for Secs. 10, 15, & 14.
Found - No monuments found.
BTs - 14" maple bears S.25°W., 40.8-ft. w/face grown over.
24" cedar bears N.22°W., 22.4-ft. w/face chopped out & scribing visible. These two BTs set in 1918.
Set - 2" x 30" I.P. w/Brass Cap mkd: "T21S R10W 10, 15, 14, 1970 650"
Set two fence posts w/signs + 5-ft. north, facing west.
+ 5-ft. west facing north.
Above information obtained March, 1984.
NOTE - See (USFS) C.S. file #62/15, & M 95-80 A & B for corner found reports showing the bearing of the maple as S.40°W.

3/84

96

Ronald E. Stuntzner,
PLS #1342
For: International
Paper Co.
February 3, 1984
M 96 - 23

*SEE INSERT FOR
MORE INFO.*

Section Corner for Secs. 6, & 7, and Secs. 1, & 12 of T.21-11.
Set - 3/4" x 30" I.R. w/2" aluminum cap stamped PLS 1342 and as prescribed, from bearing tree and ridge calls:
Fnd. - Dist. to creek to the north was 14.92ch. 1866 survey dist. was 15.0 ch. & 1891 survey 15.2 ch.
Dist. to ridge to the east was 3.06 ch. 1919 survey dist. was 3.00 ch.
Dist. to ridge to the south was 1.50 ch. 1891 survey dist. was 1.50 ch. & 1919 survey was 3.32 ch.
- The two 28" cedars recorded in 1891 survey as bearing S.1/2°E., & S.1/2°W., 66-lks., have grown together forming a 48" cedar, bearing S.1°E., 43.6-ft. (66-lks.). The face is closed.
36" cedar snag w/face 44.2-ft. (67-lks.) S.81°E. The 1891 call was a 10" cedar N.81°E., 67-lks.
Note - Coner is on the north face of a hill at the top of a slide area.

2/84

97

Herman A. Pleske L.S. 1651
For U.S. Forest Service Cooked Wassen Cadastral
Survey Siuslaw National Forest
August 1984
M 97 - 33 A & B

Section corner for Secs. 8, 9, 16 and 17
Found - GLO iron pipe with 1918 brass cap broken off and stone alongside
16" Maple bears N.73°E., 8.0 ft. (Rec. N.61°E., 8.6 ft.) 1919 BT.
24" fir bears S.69°E., 27.4 ft. (Rec. S.71°E., 27.7 ft.) 1919 BT.
28" fir bears S.58°W., 21.8 ft. scribed "S17 BT". Ren. #69
20" fir bears N.13°W., 42.5 ft. scribed "S8 BT". Ren. #69
Set - 2 1/2" x 30" alum. pipe, 20" in the ground with 3 1/4" alum. cap mkd. "US Dep of Agri-Forest Service T21S R10W S8 S9 S17 S16 RLS 1651 1983 Unlawful to disturb". Buried iron pipe and stone alongside.

98

1/4 Corner for Sec. 17 only (EAST)
Found - 1919 GLO iron pipe and brass cap. B.C. broken off and laying alongside stub of pipe.
18" D. fir bears N.69°W., 30.4 ft. (Orig. BT, Rec. 29.7) with healed face.
14" D. fir snag bears S.79°W., 26.4 ft. (Orig. BT., Rec. S.81°W., 26.4 ft.) No marks remaining.
Set - 2 1/2" x 30" alum. pipe, 24" in the ground with 3 1/4" alum. cap mkd. "US Dep of Agri-Forest Service T21S R10W 1/4 S17 RLS 1651 1983 Unlawful to Disturb". Set alongside remains of corner set by GLO.
New BTs - 38" D. fir bears S.3°W., 29.1 ft. scribed "1/4 S17 BT".

99

1/4 Corner for Sec. 16 only. (WEST)
Found - 1" iron pipe with cap broken off. (1919 survey)
24" cedar bears N.86°E., 7.5 ft. (Orig. 18", Rec. 6.6 ft.)
Fragmentary marks visible on partially healed face. (Rec. S.86°E)
42" D. fir bears S.51°W., 12.5 ft. (Orig. 36") with healed face.
Set - 2 1/2" x 30" alum. pipe, 24" in the ground, at remains of broken 1919 GLO corner, with 3 1/4" alum. cap mkd. "Depof Agri-Forest Service T21S R10W 1/4 S16 RLS 1651 1983 Unlawful to Disturb"
Buried 1" iron pipe alongside.

T. 21 R 10

Addendum: Sec. Corner for Secs. 6 and 7; and 1 & 12 of T21-11

I scribe:

- 10" D. fir, N.40°E., 40.9 ft.
- 9" Cedar, S.89°E., 47.9 ft.
- 12" alder S.45°E., 10.5 ft.
- Double 28" cedar, S.1°E., 43.6 ft.

96

This info. added 12/13/84 - T.H.