

Douglas County Surveyor's Record of
Government Corners Renewed

T 21 T. S. R 11 R. W. W. M.

FOUR-CHAPMAN CO., EUGENE, ORE. 97401

106

Section Corner for Secs. 9, 10, 16 and 15

Found - A 3/4" I.P. (no record) 6" above ground next to two squared wooden posts.

An OBT, 36" now 78" Cedar bears N.60°W., 49.5 ft. with a chopped open blaze and rotted out center.

A 48" now 57" Fir stump bears N.23°E., 51.8 ft. (Rec. 50.8 ft. good to orig. face), with a double well healed blaze. Ren. #8

A 60" Cedar stump bears N.67°W., 70.6 ft. badly rotted.

Set - A 1" x 36" I.P. over 3/4" I.P. (driven 2.0 ft. below ground) with a brass cap set 6" above ground and marked "Douglas County Surveyor" 1978
T 21 S R 11 W
S 9 S 10
S 16 S 15

I set squared wooden posts up and down hill on a steep NW slope.

New BT's- A 18" Maple bears S.77°E., 78.2 ft. double blaze. and mark "T21S R11W S15 CS BT"

A 12" leaning Maple bears S.15°W., 51.0 ft. double blaze and mark "T21S R11W S16 CS BT".

A 19" leaning I. Cedar bears N.21 1/2°W., 41.0 ft. @-31°=35.1 ft. (meas. to center at ground). double blaze and mark "T21S R11W S9 CS BT".

A 20" I. Cedar bears N.19 1/2°E., 40.4 ft. @-11°=39.7 ft., double blaze and mark "T21S R11W S10 CS BT".

Note: Corner is 0.6 mile East of Abbott House up private rd. then 300 ft. South up canyon and 100 ft. up a NW slope.

3/8/78

107

Section Corner for 8, 9, 17 and 16.

Found - A 1 1/2" I.P. with a steel plug set 4 ft. above ground marked "8|9 in a 24" dia. mound of stone. Ren. # 5.
17|16"

Orig. 30" now 27" rotted Fir stump bears N.70°W., 23.9 ft. @ +33°=20.0 ft. (Rec. N.75°W., 23.1 ft.) with scribing "BT".

A 24" Fir stump bears N.23°E., 10.1 ft. (Rec. N.30°E., 9.2 ft.).

A 30" now 37" Fir stump bears S.55°W., 16.5 ft. (Rec. 15.8 ft.) with visible scribing "S17 BT".

A 10" now 17" Fir snag, 12 ft. tall, bears S.41°W., 16.5 ft. with a chopped open, rotted blaze. Ren. #5

A 36" now 39" D. Fir bears S.15°W., 80.9 ft. (Recs. S.11°30'W., 79.6 ft.) with a well healed single blaze. Ren. #23

A 24" Fir snag, 18 ft. high, bears S.22°E., (Rec. S.26°E.) 107.4 ft. with scribing "11 W S16 CS BT" in a partly healed double blaze.

A 10" now 11" Alder is down and has a rooted face, orig. position bears approx. N.70°W., 5.5 ft. Ren. #34

Set - Reset 1 1/2" I.P. on West edge of brass cap with plug 3 ft. above ground. At corner point I SET a 1" x 36" I.P. with a brass cap set at ground level mkd: "Douglas County Surveyor" 1978
T 21 S R 11 W
S 8 S 9
S 17 S 16

New BT's-A 18" Maple bears S.68 1/2°E., 36.5 ft. @-34°=30.3 ft. I double blaze and scribe "T21S R11W S16 CS BT"

A 20" Alder bears N.13°W., 52.7 ft. I bark scribe "T21S R11W S8 CS BT"

Corner is on a -35° South East slope.

3/22/78

108

Center 1/4 Section 5.

Set - A 1" x 30" I.P. with brass cap set flush with ground and marked "Douglas County Surveyor" 1978
T 21 S R 11 W
C 1/4
S 5

BT's - A 14" Cedar bears S.14°W., 12.4 ft. I double blaze and scribe "C 1/4 CS BT"

A 10" Cedar bears S.58°E., 11.2 ft. I double blaze and scribe "C 1/4 S5 CS BT".

Corner is on a North slope, about 120 ft. from creek bottom.

4/24/78

R. B. Kimberling
P. L. Earle
Doug. Co. Surveyors
Office
March 8, 1978
C.S. 59/46

R. B. Kimberling
F.C. Silagy
Doug. Co. Surveyors
Office
March 1978
C.S. 59/46

R. B. Kimberling
P. L. Earle
Doug. Co. Surveyors
Office
April 24, 1978
C.S. 59/46