

Douglas County Surveyor's Record of
Government Corners Renewed

T. 21 T. S. R. 11 R.W.W.M.

138

Sec. corner for Sec's. 2, 3, and Sec's. 34, 35 of T.20-R.11.
Set - Brass Cap marked T20S R11W WM S34 S35 S2 S3 T21S RLS 430 1981.
BT's- 26" W. Red Cedar, I scribed T20S R11W S35 BT, bears
N.89 1/2 °E., 146.0-ft.
28" Spruce, I scribe T21S R11W S2 BT, bears S.41°E., 136.6-ft.
12" Alder, I bark scribed T21S R11W S3 BT, bears S.70°W.,
27.4-ft.
18" Alder, I bark scribed T20S R11W S34 BT, bears N.59°W.,
85.3-ft.
County Monument "S-7" bears N.75°33'26.8"W., 996.92-ft.
Steel fence post along side the set B.C.

7/81

139

1/4 corner for Sec. 2, and Sec. 35 of T.20-R.11.
Set - Brass Cap marked T20S R11W WM 1/4 S35 S2 T21S RLS 430 1981.
I reset the fd 3/4" I.P. along side. Renewal # 31.
Fnd - 56" W. Red Cedar (Orig. BT), with scribes visible, bears
S.10°W., 12.0-ft.
24" W. Red Cedar, with scribes visible, bears N.58°E., 34.5-ft.

7/81

140

1/4 corner for Sec. 3, and Sec. 34 of T.20-R.11.
Set - Brass Cap marked T20S R11W WM 1/4 S34 S3 T21S RLS 430 1981.
BT's- 14" Spruce, I scribed 1/4 S3 BT, bears ~~S.23°W., 6.2 ft.~~
76" W. Red Cedar, I scribed 1/4 S34 BT, bears N.79°W., 69.8-ft.
~~72.2 ft.~~

7/81

141

Witness corner for 1/4 corner of Sec's. 2, & 3.
Set - Brass Cap marked Witness corner T21S R11W WM East 181.46ft.
to 1/4 S3 S2 RLS 430 1981.
BT's- 18" Cedar, I scribed W.C. 1/4 S3 BT, bears South, 21.9-ft.
8" Cedar, I scribed W.C. 1/4 S3 BT, bears N.29°W., 10.1-ft.

7/81

142

Sec. corner for Sec's. 2, 3, 10, & 11.
Set - Brass Cap marked T21S R11W WM S2 S3 S10 S11 RLS 430 1981.
BT's- 10" D. Fir, I scribed T21S R11W S11 BT bears S.63°E., 46.0-ft.
12" D. Fir, I scribed T21S R11W S2 BT bears N.24°E., 11.5-ft.
24" D. Fir, I scribed T21S R11W S10 BT bears S.63°W., 66.6-ft.
No tree near, in Sec. 3.

7/81

143

1/4 corner for Sec's. 2, & 11.
Set - 5/8" I.Rod in sandstone.
BT's- 10" D. Fir, I scribed 1/4 S11 BT, bears S.62°W., 58.5-ft.
10" D. Fir, I scribed 1/4 S11 BT, bears N.37°E., 79.2-ft.

*NOTE Corner falls in the bottom of a steep draw.

7/81

144

1/4 corner for Sec's. 10, & 11.
Found- 24" x 12" x 6" Sandstone.
Set - Brass Cap marked T21S R11W WM 1/4 S10 S11 RLS 430 1981
Fnd - 30" W. Red Cedar (Orig. BT), marked face visible-no scribes,
bears N.3 1/2°W., 24.4-ft.
36" W. Red Cedar stump (Orig. BT), marked face vis.-no scribes,
bears S.63°E., 54.0-ft. (REC S.71°E., 55.4-ft.).
*NOTE- Original sandstone reset alongside.
New BT's 12" D. Fir, I scribed 1/4 S10 BT, bears West, 93.1-ft.
8" W. Red Cedar, I scribed 1/4 S11 BT, bears N12°E., 84.0-ft.

7/81

145

Sec. corner for Sec's. 1, 2, 11, & 12.
Found - 12" x 10" x 5" stone.
BT's - 44" D. Fir snag (Orig. BT), with rotten face, bears N.25°E.,
19.8-ft.

FD OK
12/90 M111-47

Bruce A. Shaner RLS #430
For: Moore Mill & Lumber Co.
RM 3 - 48
March - July, 1981

Changes per
B. Shaner
2/20/82

FD OK 11/90
M111-10

REC NO. #219