

**Douglas County Surveyor's Record of
Government Corners Renewed**

T. 21 S. T. S. R. 11 W. R. W. W. M.

ROSE CHAPMAN CO. EUGENE, ORE. 97401

- CONTINUED FROM PREVIOUS PAGE -

Bruce A Shaner
RLS #430
For: Moore Mill &
Lumber Co.
RM 3 - 48
Mar. - July 1981

Set - Brass cap in place of stone mkd. "T21S R11W.W.M. S1,S2,S11 145
S12 RLS #430, 1981"
New BT's - 36" D. Fir, I scribed T21S R11W S2 BT, bears N.32 1/2 °W.,
21.0-ft.
14" W. Red Cedar, I scribed T21S R11W S1 BT, bears
N.61°E., 21.0-ft.
30" W. Red Cedar, I scribed T21S R11W S12 BT, bears
S.14°E., 30.1-ft.
26" Hemlock, I scribed T21S R11W S11 BT, bears S.45°W., 4.6-ft.

*NOTE - Reset the stone alongside B.C.
*NOTE - Corner is at the intersection of EW and NS very old blazed
lines, timber cutting lines.
*NOTE - Haines tag is at corner as well as cruiser mark "SR".

7/81

Donald L. Peel
RLS #752
August 17, 1981
C.S. 58 / 229

South 1/4 corner for Sec. 29. 14.
Pd.BT's - 63" Fir (orig.42"), bark scribed, scribing visible, cruiser's
mark on tree.
24" rotted Fir stub, N.40°W., 79-ft. (slope dist...not horiz),
no marks visible, pretty well rotted away.
Set - Brass Cap on 2 1/2 " Iron Pipe, marked: T21S R11W 1/4 S29
PLS 752 1981.
BT's - 29" Fir, N.27°E., 32.2-ft.
63" Fir, S.14°E., 33.0-ft.(orig. BT).

8/17/81

Ernesto Alvarado, USFS
Deputy Douglas County
Surveyors Office
Carol Dickison and
Colin Long, witnesses
Oct. 2, 1981
C.S. 61/29

Sec. cor. to Sec's. 33, & 34, and Sec's. 3 & 4 of T.22-11. 147
Found - 18" x 18" x 6" sandstone with "x" on top, set by Ren.# 19.
BT's - 34" D. Fir bears N.39°E., 14.3-ft. w/healed face. Ren.# 19.
47" D. Fir bears S.82°W., 57.7-ft. w/healed face. Ren.# 19.
S.E. Cherry BT is uprooted w/part of scribing visible. Ren.#19
43" D. Fir bears N.21°W., 20.5-ft. Face was chopped out app.
48 years ago. All heartwood is rotten (powder). No scribing
found. Traces of axe marks found. Tree has dead top. (Cut
out, found the upper bevel part of blaze).
Set - 2 1/2 " B. C. on 1" I.P., 30" long w/flanged bottom, stamped:
Douglas County Surveyor's Office T21S R11W S33 S34 T22S
R11W S4 S3 1981 .
New BT's- 6" D. Fir bears S46°E., 25.2-ft. "x" scribed at breast height,
lower blaze scribed CS BT.
Location- Go East along Hwy. #38 approx. 4.6-mi. from Reedsport to Alder-
wood Farm. Walk West on road South of creek (So. edge of
pasture), approx. 600' to location poster on Alder on South
side of road. From poster, go S.10°W., 500-ft. to corner.

10/2/81

CONDITION REPORT ONLY

1/4 corner common to Sec's. 29, & 28.
Found - Original corner tree: 44" rotten D. Fir stump. #162 148
Brass Cap on 1 1/4 " I.P., set by M-70-74... S. 497.
bears S88°E., 4.0-ft. from tree, mkd: 1/4 S29 S28 1978
3/4" I.P. set by M34-30... PLS 239, next to cap.
BT's - 13" D. Fir bears N.68°E., 13.0-ft., scribing visible.
24" D. Fir bears S.9°W., 16.5-ft., scribing visible.
50" D. Fir stump bears S.3°E., 324.0-ft.
Note - Location: Travel along Rd.#41, 1.1-miles past Otter Slough
to location poster on Alder on West side of road; then go
West 400-ft., then South 445-ft. to corner, which lies 30-ft.
West of ridge top.

10/13/81

Ernesto Alvarado, USFS
Deputy Douglas County
Surveyors Office
Colin Long, witness
Oct. 13, 1981
C.S. 61 / 29

1/4 Corner for Secs. 8 and 9 149
Found - 1967 County brass cap properly marked being 1 foot above
ground. Ren. #48
A 4" Alder, now 9" bears N.25°E., 42.2 ft. with visible scribe
"BT" in a double blaze.
A 5" Hemlock now a 14" Hemlock in a group of four from an old
stump bears N.8°W., 103.3 ft. with well healed double blaze.
The remains of an old fir stump bears N.28°E., 9.0 ft.
This stump called in Ren. #48
No original BT's found.

Karen Reed, Doug. Co.
Surveyors Off. Deputy
John Powell, A. Smith
Feb. 22, 1982
C.S. 61/30