

**Douglas County Surveyor's Record of  
Government Corners Renewed**

T 21

T. S.

R 11

R. W. W. M.

KURE, CHAPMAN CO., EUGENE, ORE. 97501

199

Richard Hintz LS 497  
For: International  
Paper Company &  
Butler Creek Farm  
10/84 M 97 - 55

Center 1/4 Corner for Section 31  
Set - 1 1/4" x 36" iron pipe with brass cap stamped PLS 497.  
BTs - 24" fir bears N.0°30'E., 21.8 ft. scribed C 1/4 S31 BT.  
22" Cedar bears N.56°45'W., 22.3 ft. scribed C 1/4 S31 BT.

10/84

200

Herman Pieske LS 1651  
AA Surveying Company  
For: U.S. Forest Serv.  
November 1984  
M 97 = 76 A & B

1/4 Corner for Section 1; and Section 6 of T.21-10  
Set - At proper position, 2 1/2" x 30" alum. pipe, 28" in the ground,  
with 3 1/4" alum. cap mkd. "USDA Forest Service T21S R10W  
R11W 1/4 S1 S6 1984 RLS 1651 Unlawful to Disturb"  
New BTs - 36" hemlock bears N.19°E., 84.8 ft. scribed "1/4 S6 BT". in double  
double blaze.  
27" cedar bears N.57°E., 67.2 ft. scribed "1/4 S6 BT" in double  
blaze.  
32" cedar bears N.1°W., 48.6 ft. scribed "1/4 S1 BT".

201

1/4 Corner for Section 12; and Section 7 of T.21-10  
Set - 2 1/2" x 30" alum. pipe 22" in the ground with 24" diam. mound  
of stone, with 3 1/4" alu. cap mkd. "USDA Forest Service T21S  
R10W 1/4 R11W S12 S7 1984 RLS 1651 Unlawful to Disturb".  
New BTs- 29" D. fir bears S.81°E., 204.6 ft. scribed "1/4 S7 BT"  
7" cedar bears S.34°W., 60.4 ft. scribed "1/4 S12 BT"  
Reference Monument:  
2 1/2" x 30" alum. pipe 26" in the ground, with 3 1/4" alum. cap  
mkd. "USDA Forest Service T21S R10W S7 RM N.19°40'W 50.85 ft.  
1984 RLS 1651 Unlawful to disturb", bears S.19°40'E., 50.85 ft.

202

Section corner for Secs. 12 and 13; and Secs. 7 & 18 of T.21-10  
Found - Original 60" cedar corner tree, now down. See Ren. #165  
Set - 5/8" x 30" iron rod with plastic cap mkd "AA Surveying Service Inc.  
in root wad at corner.  
Found - 49" cedar (orig) bears S.35°W., 34.3 ft. healed blaze.  
New BTs- 10" alder bears S.32°20'E., 19.5 ft. bark scribed "T21S R10W  
S18 BT"  
8" alder bears N.20°30'E., 21.4 ft. bark scribed "T21S R10W S12 BT"  
17" alder bears N.47°W., 19.2 ft. bark scribed "T21S R11W S12 BT"  
Reference Monument set:  
2 1/2" x 30" alum. pipe with 3 1/4" alum. cap mkd. "USDA Forest  
Service T21S RM R11W N4°E 27.9 ft. S13 RLS 1651 1983 Unlawful  
to Disturb".

203

West 1/4 Corner for Section 18 only, T21-10  
Found - 1 1/2" I.P. with brass cap broken off. (1919 GLO)  
Set - 2 1/2" x 30" alum. pipe 5" above ground with 2 ft. mound of stone  
with 3 1/4" alum. cap mkd. "USDA Forest Service T21S R10W 1/4  
R11W S18 RLS 1651 1984 Unlawful to Disturb". Buried brass  
cap and pipe alongside.  
BTs found-32" cedar bears S.23°E., 5.3 ft. healed face.  
24" hemlock bears N.62°E., 19.8 ft. healed blaze.

204

East 1/4 Corner for Section 13 only.  
Found - 1 1/2" I.P. with 1919 GLO brass cap.  
12" hemlock bears S.70°W., 7.8 ft. visible scribe "S" in  
partially healed face.  
14" hemlock bears N.2 1/2°W., 31.7 ft. chopped open face visible  
"BT".  
Fir snag, now badly rotted, bears N.65°W., 4.0 ft.  
Set - 2 1/2" x 30" alum. pipe 3" above ground, with mound of stone with  
3 1/4" alum. cap mkd "USDA Forest Service T21S R10W R11W 1/4 S13  
RLS 1651 1984 Unlawful to Disturb".

205

Section corner for Sections 18 and 19 only of T21-10  
Found 1919 GLO brass cap properly marked.  
60" D. fir bears N.27°E., 50.2 ft. healed face.  
30" hemlock bears S.75°E., 13.9 ft. healed face (Rec. S.83°E.)  
Set - 2 1/2" x 30" alum. pipe flush in 18" mound of stone with 3 1/4" alu  
cap mkd. "USDA Forest Service T21S R10W R11W S18 S19 RLS 1651 1984

Herman Pieske, RLS 1651  
AA Surveying Service  
For: U.S. Forest Service  
November 1984  
M 97 - 77 A & B

RE-RENEWED REGISTER NO. # 216