

Douglas County Surveyor's Record of
Government Corners Renewed

T. 21 S. T. S. R. 11 W. R.W.W.M.

KERR-CHAPMAN CO. EUGENE, ORE. 97101

RE-RENEWED, SEE CORNER NO. 51
Township Corner

S36	S31
S1	S6

 T20S 25
R11 W R10 W T21S

Set Corner from old Witness Tree in Section 6, Maple.
Set - 2" x 4" Galv. Iron Pipe, mkd. new trees as follows:
4" Fir bears S.77°15'E. 65 lks.
10" Maple S.27°W. 17 lks.
20" Maple bears N.14°W. 23 lks.
No trees near in Section 31.

H.L. Eppstein
Wit: Frank
Cain &
W. Dailey
Jan. 25,
1929.

Ren. Cor. Vol. 1
Pg. 7

1/2 Corner between Sec. 2, T21-11W. & Sec. 35, T20-11W. 26
Set a Chittam Post 4" x 4" x 3 1/2' by Orig. BT. to Witness
Cedar 12" S.18°W. 18 lks., decayed but marks plain other
BT's. destroyed.

Marked New Bearing Trees:
Fir 10" bears S.82°W. 17 links.
Fir 16" bears N.46°W. 18 links.

H.L. Eppstein, Co. Surv.
Wit: F. Cain &
Harry Henderson
Jan. 24, 1929

Ren. Cor. Vol. 1
Pg. 7

Meander Corner on left bank Smith River Sec. 3, T21-11 & Sec. 34, T20-11W. 27
A Plow Share marks corner.
Mkd: An Alder 10" bears S.15°E. 85 links.

1/2 Corner common to Sec. 34, T21-11W. & Sec. 3, T22-11W. 28
Orig. - Post (missing, fd. 1 1/4" I.P. with cap, in place) from which:
12" Spruce bears N.34 1/2°W. 36 lks.; now badly rotted uproot.
30" Spruce bears S.31 1/2°E. 72 lks.; now 60", orig. face
grown over (see rest. by Hootman below).

Rewitnessed by W. Hootman (no record found) from which a: #195
See Ren. No. 18

60" (orig. 30") Spruce bears S.31 1/2°E. 72 lks.; scribes BT 1/2 S3
T22 399 visible in new face 5 or 6 years old.
24" Dbl. Spruce bears N.68°E. 15.9 ft.; scribes 1/2 S34 T21 visible.

Note: added scribes RS359 on 24" Spruce.

4 x 4 Elliott survey post 6 in. West of corner pipe.

Ore. State Forestry Dept. metal location poster on Orig. 30" Spruce

Arnold G. Gibson
Ore. St. Bd. of Forestry
Jan. 16, 1964
C.S. File No. 51/260
Map File M 27 - 28

FD, OK
2/21/79
C. S. 51-11
See C. S. 51-11

Sec. Corner to Secs. 3 & 4, T21-11W. & Secs. 33 & 34, T20-11W. 29
Found - 48" Fir S.55°W. 19.8 ft. (from old face) Prev. opened,
good scribing visible on old face "B". Upper scar visible.
Fir, uprooted & down, N.55°W. 32.0 ft., both scars visible.
48" Fir Stump S.25°E. 11.9 ft., no scars visible, probably #92
cut too low. No trace of N. E. BT.

Set - Brass Cap at Cor. Mkd: County Surveyor's T20S R11W S 33 | S 34
Office, 1964 T21S R11W S 4 | S 3

New BT's: 9" Hemlock S.58°E. 27.4 ft. Mkd: T21S R11W S3 CS BT.
48" D. Fir S.55°W. 19.8 ft. (to face) Mkd: T21S R11W S4 CS BT.
34" D. Fir N.17°W. 50.0 ft. Mkd: T20S R11W S33 CS BT. This
BT. is on top of ridge.

Wilo E. Godfrey, Deputy Co. Surveyor
Wm. Stoffel and Mike Stone
September 1964
C. S. File No. 53/66

Section Corner to Secs. 5 & 4, T21-11W. & Secs. 32 & 33, T20-11W. 30
Found - 58" Old Fir Stump N.75°E. 28.4 ft., cut open & fd. good
scribing "S" & "11W".

No trace of Corner Tree or any other BT's.

Set - Brass Cap at Cor. Mkd: County Surveyor's T20S R11W S 32 | S 33
Office, 1964 T21S R11W S 5 | S 4

New BT's: 7" Hemlock S.33°E. 19.7 ft. Mkd: T21S R11W S4 CS BT.
16" Hemlock S.85°W. 30.8 ft. Mkd: T21S R11W S5 CS BT.
18" D. Fir N.58°W. 30.3 ft. Mkd: T20S R11W S32 CS BT.
11" Hemlock N.62°E. 20.3 ft. Mkd: T20S R11W S 33 CS BT.

Note - Corner is approx. 250 ft. south of centerline of new logging road.

Mach 67 - E. O. K. V.R.I.