

Douglas County Surveyor's Record of
Government Corners Renewed

T. 21 S. T. S. R. 11 W. R.W.W.M.

KOKE, CHAPMAN CO., EUGENE, ORE. 21881

60

Sec. Cor. to Secs. 18 & 19, T21-11W. & Secs. 13 & 24, T21-12W.
Found - 2" Iron Pipe at Corner, 12" above ground, See Ren. #32 #116
16" D. Fir, now 16", S. 8° W. 8.4 ft. shows pitched over scribng.
14" D. Fir, now 14", S. 60° E. 24.7 ft. shows pitched over scribng.
13" D. Fir, now 13", N. 77° E. 27.2 ft., shows pitched over scribng.
New BT: 12" Hemlock N. 67° W. 26.4 ft. scribed T21S R12W S13 CS BT.

3/27/70

61

1/2 Corner to Sec. 18, T21-11W. and Sec. 13, T21-12W.

This corner set from survey as follows:

Set - Brass Cap at Prorated distance Mkd: R T 21 S R
County Surveyor's Office 12W S 13 S 18 11W
1970

New BT's: 38" D. Fir N. 80° W. 62.20 ft. scribed "1/2 S13 CS BT".

12" Spruce S. 82° E. 29.3 ft. scribed "1/2 S18 CS BT".

Found - 2" I. Pipe S. 3° W. 48.22 ft. from 1/2 Corner, See. C.S. 40/169. - Ren. #9

Note - Creek bears West 25.0 feet.

4/27/70

62

Section Corner to Secs. 30 & 31, T21-11W. and
Secs. 25 & 36, T21-12W.

Found - Orig. 30" D. Fir, now down, N. 36° E. 59.4 ft., found bark
scribe "2" and other marks.

Cedar, down in draw, possible BT.

No trace of other bearing trees.

Set - Brass Cap at Cor. Mkd: County Surveyor's R T 21 S R
Office 12 S 25 S 30 11
1971 W S 36 S 31 W

New BT's: 6" Spruce N. 55° W. 36.8 ft., scribed "S25 CS BT".

22" D. Fir North 32.3 ft. scribed T21S R12W S25 CS BT".

38" Spruce N. 48° E. 45.5 ft. scribed "T21S R11W S30 CS BT".

No trees to the south.

This corner lies about 12 ft. north of ravine, running E - W.

2/9/71

Section Corner to Secs. 31 & 32, T21-11W and
Secs. 5 & 6, T22-11W.

FD OK PER ST. Hwy
MAP (0-1)
FILED 6/87

63

This corner set from survey.

Set - Brass Cap at Cor. Mkd: County Surveyor's T 21 S R
Office, 1971 T 22 S R11W S 31 S 32
S 6 S 5

Also set Steel Fence Post alongside Brass Cap.

This corner lies in large field south of Highway #38.

7/9/71

Reference Monument 1 for Sec. Corner 31 & 32, T21-11W and
Secs. 5 & 6, T22-11W.

64

Set - Brass Cap on Township Line 414.35 ft. west of section corner
and said cap is flush with ground on highway shoulder mkd:

County Surveyor's Office T 21 S R 11 W

1971 FD OK PER ST. Hwy. RM 1 S 31
MAP (0-1) 6-87 S 6

T 22 S

This cap lies on south edge of highway 7.0 ft. south & 9.0 ft.

East of edge of pavement.

5/8" I. Rod West 70.0 feet

5/8" I. Rod North 50.7 feet.

65

Witness Corner to 1/2 Corner to Section 36 only, T21-12W.

This corner set from survey and lies approx. 6 ft. south of driveway.

Wit. Cor. 250.24 feet North of 1/2 Corner.

Set - Brass Cap at Cor. Mkd: County Surveyor's R T 21 S R
Office 12 S 36 1/2 11
1971 W S 6 W

Bearing Tree and Bearing Objects:

17" Maple N. 82° E. 67.0 ft. scribed "W. C. CS BT".

5/8" I. Rod N. 78 1/2° W. 68.5 feet.

5/8" I. Rod S. 89° W. 34.7 feet.

James W. Byron, Co. Surveyor
John M. Powell & W. Penley
April 1, 1970
C.S. File No. 54/110

JOHN M. Powell
W. Penley & J. Heritage
C.S. File No. 54/1

MARCH 71

James W. Byron, County Surveyor
John M. Powell & Crew
For Douglas County Feb. - June, 1971
C.S. 56/5 Map N 42 - 27