

Douglas County Surveyor's Record of  
Government Corners Renewed

T. 21 S. T. S. R. 11 W. R.W.W.M.

James W. Byron, County Surveyor - J. M. Powell & Crew  
For: Douglas County  
Feb. through June, 1971  
C. S. File No. 56/5 Map M 42 - 27

1/4 Corner to Section 31 only, T. 21 S. R. 11 W.  
This corner set from survey & lies 100 ft. (approx.) north of Ump. River.  
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1971  
R T 21 S R  
12 1/4 S 31 11  
W W

New BT's: 24" Spruce S. 22° W. 4.6 ft. mkd: "1/4 S CS BT".  
30" Spruce S. 20° E. 20.0 ft. mkd: "1/4 S31 CS BT".

66

1/4 Corner to Sec. 36, T21-11W. and Sec. 1, T22S-11W.  
Corner set from survey, and lies on top of very steep drop-off to the  
westerly bank of Umpqua River.  
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1971  
T21S R12W 1/4 S 36  
T22S S 1

Set Steel fence post alongside B. C.  
Bearing Tree: 18" Hemlock S. 76° W. 81.8 feet scribed "1/4 S 1 CS BT".  
6/10/71

67

1/4 Corner to Sec. 32, T21-11W. and Sec. 5, T22-11W.  
This corner set from survey.  
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1971  
T21S R11W 1/4 S 32  
T22S S 5

Set Steel Fence Post alongside Brass Cap.  
7/9/71

68

Section Corner to Secs. 32 & 33, T21-11W. & Secs. 5 & 4, T22-11W.  
This corner set from survey.  
Set Brass Cap at Cor. Mkd: County Surveyor's Office, 1971  
T21S R11W S 32 | S 33  
T22S S 5 | S 4

Also set steel fence post alongside Brass Cap.  
Bearing Tree: Large Spruce S. 4° W. 356.5 ft. mkd: "T22S R11W. 4 CS BT".

69

Sec. Cor. to Secs. 1 & 12 only, T22-12W.  
This corner set from survey and lies in bottom of ravine, running N & S.  
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1971  
R T 22 S R  
12 S 1 | S 6 11  
W S 12 | W

Bearing Trees: 10" Maple West 41.5 ft. scribed "T22S R12W S 1 CSBT".  
10" D.Fir N.77 1/2° E. 24.0 ft. scribed T22S R11W S 6 CS BT".  
? D.Fir S.40° W. 60.2 ft. scribed T22S R12W CS BT".  
6/8/71

70

1/4 Corner to Section 33, T21-11W. & Sec. 4, T22-11W.  
This corner set from survey and lies on steep ridge top, ridge  
running N & S. Also creek bears East approx. 195.0 ft.  
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1971  
T21S R11W 1/4 S 33  
T22S S 4

Also set steel fence post alongside B. C.  
Bearing Objects: 5/8" Iron Rod N.89° W. 42.7 feet  
5/8" Iron Rod N.89° E. 9.3 feet.  
6/8/71

71

Hintz, R.J.  
For: Brandon  
C. S. File  
No.  
55/310

1/4 Corner to Sections 9 and 16.  
Set - 1" I. R. 6" below the surface of the ground.  
Found - 40" Fir Stump bears S.60°30'E. 334.0 ft. (1926 BT)  
See Ren. #8-A  
Power Pole 10 - 8 bears S.73° E. 7.0 ft., place metal tag  
15 on pole.  
8/73

72

Wilford Haines  
for Cone Lbr.  
August 1974  
C.S. M 54 - 33

Center 1/4 for Section 23.  
Set - 5/8" Steel rod temp. C 1/4 S. 23.  
1/4 Corner for Secs. 23 and 26.  
Found - Location poster N.06° E., 194.0 ft. No bearing or  
dist. on poster.  
Set - 5/8" Steel rod temp. 1/4 S 23 and 26.

73

74

Ind. 1972

FD OK PER HINTZ  
M106-29448 JUNE 1983