

**Douglas County Surveyor's Record of
Government Corners Renewed**

T 21 T. S. R 11 R. W. W. M.

ROSE CHAPMAN SQ. BUREAU ONE KIRBY

91

G. L. Langlitz
Larry E. Monrean
P. Earle - S. Flause
Doug. Co. Surveyors
C.S. 59/32
3/30/77

1/4 Corner for Sec. 6 and 5
Set - At 1/4 Corner as determined by Douglas County Surveyors Office 1977 survey (CS File 59/32): SET a 1" x 30" I.P. with brass cap attached 27" in the ground. Stamped: "Douglas County Surveyor" T21S R11W 1977 1/4 S 6 S 5
BT's - A 11" Spruce bears N.88°E., 45.7 ft. Tree double blazed and scribed "1/4 S5 CS BT".
A Fir 16" bears N.27°W., 51.3 ft. Tree double blaze and scribed "1/4 S6 CS BT".

3/30/77

92

Sec. Cor. for Secs. 4 and 3; and 33 and 34 of T20-11
Found - 1964 Doug. Co. Surveyors brass cap set 12" above ground on 1" pipe properly marked. Ren. #29
A Fir, uprooted and down, approx. 54" bears N.55°W., 31.0 ft. Both scars visible.
A Fir stump, 48" now 42" bears S.25°E., 12.8 ft. (Rec. 11.9 ft.)
A Fir, 48" now 50" bears S.55°W., 19.8 ft. to well healed blaze, 20.8 ft. to opened blaze with visible "B" scribe mark.
A Hemlock, 9" now 16" bears S.58°E., 26.4 ft. (Rec. 27.4 ft.) with well healed double blaze.
A D. Fir snag 36" now 34" bears N.17°W., 50.0 ft. double blazed, partial healed with trace scribing visible.
No monument set.
New BT - A 11" Hemlock measured below fork bears N.1°E., 29.7 ft. double blazed and marked T20S R11W S34 CS BT.

6/16/77

93

1/4 Corner for Sec. 4 and Sec. 33 of T20-11.
Found - A 1" Iron pipe at 1/4 corner as proportioned by Stuntzner per Ren. #55.
A 32" D. Fir bears N.50°W., 1.8 ft. tree bark scribed "S 33 1/4".
A 42" D. Fir now 52" bears N.82°E., 9.5 ft. Tree has unhealed blaze - scribed "S 33 1/4".
Set - A 1" x 30" I. Pipe with brass cap attached at 1/4 corner as determined by Stuntzner, cap stamped "Douglas Co. Surveyor"
1/4 T 20 S
S 33 R11W
S 4
1977
Set - 1" I. Pipe along easterly edge of cap.
New BT - A 48" D. Fir bears S. 4 1/2°W., 88.4 ft. Tree double blazed and scribed "1/4 S4 CS BT".
Corner lies at NE corner of stand of timber.

6/15/77

94

Section Corner for Secs. 4, 3, 9 and 10.
Found - 3/4" I. Pipe 14" above ground firmly set. Ren. #41
Orig. BT now 16" Fir (called for 30") bears S.25°E., 11.9 ft. Previously open blaze BT visible painted over.
No other orig. BTs found.
A 14" now 16" Spruce bears S.24°E., 38.9 ft. (Rec. 37.5 ft.) partially healed blaze R11 S3 S B visible.
A 20" now 26" D. Fir bears S.23°E., 17.7 ft. well healed blaze.
A 28" now 30" Maple bears S.56°W., 38.5 ft. (Rec. 42.6 ft.) partially healed blaze 21 R11 CS visible.
A 52" now 60" D. Fir bears N.70°W., 24.5 ft. well healed blaze.
A stump 48" bears S.86°W., 15.2 ft. no scribe found.
Set - 1" I.P. 30" long with brass cap attached mkd. Douglas County Surveyor
T 21 S R 11 W
S 4 | S 3
S 9 | S 10
1977

6/21/77

G. Langlitz
R. Kimberling
June 16, 1977

Douglas County Surveyors Office
C.S. 59/34

*Fd. ok 5/25/77
S. ALVARADO
C.S. 41/6*

Larry E. Monrean
Karen Cheney
Steve J. Flause
June 15, 1977

*Fd. ok 5/25/77
S. ALVARADO
C.S. 41/6*

L. E. Monrean
Peter L. Earle
Douglas Co. Surveyors Office
June 21, 1977
C.S. 59/34