

Douglas County Surveyor's Record of  
Government Corners Renewed

T 21

T. S.

R 11

R.W.W.M.

WEEKS-CHAPMAN CO., EUREKA, CALIF. 95501

87

Section Corner for Secs. 6, 5, 7 and 8.

Found - Badly decayed stump of orig. corner tree.  
1967 D.C.S.O. brass cap; bears West 1.3 ft. from center of orig.  
corner tree stump. Ren. #40

Note: Bearings and distances recorded below are from the D.C.S.O.  
brass cap, not the orig. corner tree stump.

Found - Orig. 10" now 26" Cedar bears N.17 1/2°E., 14.9 ft. 1967 re-  
scribe on open blaze "T21S R11W S5 CS BT".

Orig. 42" now 46" Fir stump bears N.17 1/2°W., 20.1 ft. Has good  
scar, I did not open.

A 36" Cedar bears S.16 1/2°W., 30.1 ft. Tree has open blaze,  
scribing visible "T21S R11W S7 CS BT"

A 40" now 44" Cedar bears N.43°W., 26.2 ft. Tree has open blaze.  
scribing visible "S R11W S6 CS" Tree not scribed BT as recorded.

Renewal - To the 44" Cedar in the NW quadrant, I make a second blaze and  
I add scribing "BT".

Note: Bearings and distances recorded are measured to the center of the  
base of the BT's.

12/13/76

Larry E. Monrean  
Mike Tompkins  
Doug. Co. Surveyors  
Office  
Dec. 13, 1976  
C.S. 59/26

1/4 Corner for Secs. 5 and 4.

88

Found - 1967 County Surveyors Brass Cap, firmly set on a SE slope,  
extending 12" out of ground properly marked. Ren. #39  
and the remains of a 3/4" I.P. badly rusted, firmly set at the  
base of the brass cap as noted in Ren. #39.

We find the rotting remains of a 24" Cedar stump S.88°E., 9.6 ft.  
as described in Ren. #39, however we do not identify it as an  
orig. BT.

We find no evidence of the orig. NW BT.

A 1967 BT, A 12" now 16" Red Alder, alive with scribing "1/4 S"  
visible on partially healed blaze bears S.75°E., 39.1 ft.

1967 BT, a 19" now 22" Red Alder alive with scribing "1/4"  
visible on partially healed blaze bears S.k8°W., 50.3 ft.

New BT - A 24" D. Fir bears S.30°E., 110.7 ft. scribed "1/4" S4 CS Be" on  
a double blaze.

1/18/77

Gary L. Langlitz  
P. L. Earle  
Doug. Co. Surveyors  
Office  
Jan. 18, 1977  
C.S. 59/29

1/4 Corner for Secs. 15 and 16.

89

Set - From the possible orig. 8" Alder BT (now 20") which bears  
N.48°E., 14.5 ft. axe marks but no scribe I SET a 3/4" I.P. from  
which:

A 32" Cedar bears N.20°E., 6.44 ft. mkd. 1/4 S15 BT.

3/9/77

Richard J. Hintz  
For: James Peck  
March 9, 1977  
C.S. 58/140

Section Corner For Secs. 6 and 5; and Secs. 31 and 32 of T20-11.

90

Found - Orig. 42" Fir now a 46" decayed stump. Has well healed blaze,  
which we open. Find good scribing "T21S R11W S6 BT".

Orig. 27" Fir now a 34" tip ou (root hole well defined). Tree  
has well healed blaze which we open, find good scribing T20S  
R11W S32 BT". Tree is decayed.

Possible Orig. BT to the SE recorded as a 36" Fir. Found a  
badly decayed stump, no scribing, approx. 18".

NW BT an alder not found.

Set - A 1" x 36" I.P. with brass cap attached 30" deep at sec. cor.  
mkd. "Douglas County Surveyor T20S R11W S31 S32 S6 S5 T21S 1977

From which:

46" Fir stump, bears S.22°W., 13.2 ft. to face.

Stump hole bears S.27°E., 23.1 ft. to center (Rec. S.29 1/2°E.,  
23.1 ft.).

New BT's - A D. Fir 14" bears S.39°W., 16.5 ft. Tree double blazed and  
scribed "T21S R11W S6 CS BT"

A D. Fir 14" bears S.62 1/2°E., 4.6 ft. Tree double blazed &  
scribed "T21S R11W S5 CS BT".

A W. Fir 9" bears N.34 1/2°W., 14.2 ft. Tree double blazed &  
scribed "T20S R11W S31 CS BT"

A D. Fir 18" bears N.7°E., 25.2 ft. Tree double blazed & scribed  
"T20S R11W S32 CS BT".

Note: This corner falls on the top of a ridge running S.35°W.,

3/2/77

Larry E. Monrean  
P. Earle  
K. Cheney  
Douglas County Sur-  
veyor's Office  
March 2, 1977  
C.S. 59/31