

Douglas County Surveyor's Record of
Government Corners Renewed

21 T. S. 12 R. W. W. M.

CONT. - - A Spruce 36" diam., bears S. 47°W. 235 ft. marked #8
 1/3. 16 S. S. B.T.
 A Spruce 30" diam., bears N. 80 1/2°W. 308.6 ft. marked
 1/3. 15. C. S. B.T.

✓ N. 7. CORNER ADDISON GIBBS D.L.C. #37 **9**
 Set from 1/2 Cor. tie as recorded in original Government field
 notes. Set a Cedar Post 4" x 4" x 36" and drove an iron
 pipe alongside, from which
 A Spruce 18" diam., bears S. 40 1/2° W. 56.5 ft. marked
 D. L. C. 37 C. S. B.T.
 A Spruce 8" diam., bears N. 70° W. 30.5 ft. marked.
 D.L.C.37 C. S. B.T.

✓ COR. SECS. 9, 10, 15, 16 **10**
 Location identified from an old fir stake & bearing tree.
 Set a post 7" x 7" x 50" for corner, from which
 A Fir 36" diam., bears S. 5 1/2° W. 87° ft. (slope)
 This tree had been previously marked but was not an original.
 Marked T. 213. R. 12. S. 15. C. S. B.T.
 A Fir 40" diam., bears S. 59° E. 105.0 ft. (slope)
 Marked T. 213. R. 12. S. 15. C. S. B.T. **34**
 A Fir 50" diam., bears N. 46° W. 60.5 ft. (slope)
 Marked T. 213. R. 12. S. 15. C. S. B.T.
 This tree had been previously marked.
 A Fir 60" diam., bears N. 32° E. 19 lks. This is an
 original B.T. & was remarked.

MEANDER COR. BET. SECS. 15 & 16 **11**
 Right Bank of Umpqua River. Location identified from two
 bearing tree apparently marked about 35 to 40 years ago -
 A 72" spruce S. 83° E. 6.8 ft. marked S. 15 M.P.
 A 54" Spruce same N. 20° W. 100.7 ft. marked S. 16 M.P.
 Set a Cedar post 4" x 4" x 48" for Corner 7 drove a 1" x 48"
 iron pipe along side, from which **33**
 A Spruce 24" diam., bears N. 46° W. 65 ft. Marked
 T. 213. R. 12. S. 15. M.P. C. S. B.T.

1/2 CORNER BETWEEN 13-18 (T 21 S, R 11 W.) **12**
 Set a 1 1/2 in. iron pipe (computed by proportional measurement)
 12" Alder bears N 21° W 6.2 ft.
 14" Alder bears S 89° E 14.0 ft.

See 40/169

1/2 sec. corner to sec. 34, T 21 S, R 12 W., and sec. 3, T 22 S, R 12 W. **13**
 Position of corner established from tie shown on amended plat of
 R. R. Addition and monument at 10th and Winchester used for control. **37**
 Corner falls in street & no monument set.
 Bearing objects are chiseled " + " in concrete on East abutment of bridge,
 and bear S. 35° 16' W., 191.1 feet; S. 55° 28' W., 159.0 feet.
 Northwest corner of Texaco Service Station bears N. 59° 22' E., 236.3 feet.
 Note - Co. Surveyor's Brass Cap Set in 1956 - Recorded in November, 1967.

Sec. corner to secs. 34 & 35, T21S, R12W., and 2 & 3, T22S, R12W. **14**
 Position of corner determined by tie (N. 15° W., 253.3 feet) shown on
 amended plat of R. R. Addition and ties made on Winchester Ave.
 Set an iron pipe with brass cap at corner point mkd. 34/35 T21S R12W.,
 County Surveyor's Office, 1956. 3/2 T22S
 Blazed and scribed:
 14 inch Cedar, N. 20° 28' 30" E., 283.83 feet mkd. S 35, T21S, R12W., CS B. T.

1/2 Section Corner to Sections 34 and 35
 Found - 2" I. Pipe, Rusted out.
 Set - 1/2" x 36" Iron Rod

August 8, 1962

Ben P. Irving D. C. S.
 Witness
 H. E. Richardson
 Loren Weber
 7/16/62

Ben P. Irving D. C. S.
 Witness
 H. E. Richardson
 Loren Weber
 7/16/62

Harry Higdon
 Surveyor
 Jan. 15, 1949

James W. Byron, Deputy County
 Surveyor
 Aug. 9, 1956
 C. S. File No. 47/129.

Bruce A. Shaner
 For Housing Authority
 Doug. Co. Oregon
 Aug. 8, 1962
 RM 2-2
 1-32

RE-RENEWED, SEE CORNER NO. #87 15