

**Douglas County Surveyor's Record of
Government Corners Renewed**

T 21 S T. S. R 12 W R. W. W. M.

ROSE CHAPMAN CO., EMBERS, ONE, EISEN

Robert Ward, L.S. 1091
For: Siuslaw Nat. Forest
& Tahkenitch Tree Farm
Partnership
April 1995
M 122 - 3 A

Cor. Secs. 33, 34 & 3, & 4 T21-12
Found - 30" Rotted Spruce mound with a pitched slab scribed "BT"
with chaining notch below (Rec. N.43'W., 25.1')
50" D.Fir, stump with what appears to be a X chopped across
the healed blaze, I did not open (Rec. S.30'W., 16.5')
Set - At intersection of record distances as determined from where
the orig. face would have been, I set a 2 1/2"x30" Aluminum
corner monument w/cap stamped: T20S R12W

110

S33	S34
8 4	8 3
T21S	
1994	
LS 1091	

BTs - 30" Rotted spruce mound, bears N.46 1/2'W., 27.7'
50" D.Fir stump, bears S.27 1/2'W., 16.9'
22" Hemlock stump, bears N.47 1/2'E., 22.9'
16" D.Fir stump, bears S.48 1/2'E., 8.7'
Note - I drove a 5/8"x30" rebar with cap marked LS 1091 into the
center of each stump.

111