

Douglas County Surveyor's Record of
Government Corners Renewed

T 21 T. S. R 12 R.W.W.M.

CONT. 39

C O N T.

Gary Langlitz
P. Earle
C.S. 57/12
11/29/74

To preserve this location, we note the following bearing objects:
The SW corner of a house, (Jones residence), bears N.25°E., 22.15 ft.
The NW corner of a two-car garage bears S.65°E., 36.58 ft.
A bolt, set flush in the southerly edge of the driveway bears
S.14°E., 8.0 ft.

Note: Ren. #36 mistakenly deals with the wrong corner.

FD OK R. Dodge 10/03/94 M121-12

Nov. 29, 1974

Section Corner for Secs. 3, 2, 10 and 11.

Found - 70" Spruce Alders missing.

Reset - Corner with 1-1/2" I.P. & 3"x3"x5' Spruce post #69
From which bears: Orig. 70" Spruce S.21°W., 37.32' to nail S10 T21S R12W BT.
5" Spruce N.19°E., 45.7 ft. to nail crayon mkd: RP BT.

4/17/43

40

Meander Corner for Secs. 3 and 4.

W.G. Corbitt followed blazed line 25 yrs. old, south from corner, Secs. 33,
34, 3 and 4 to edge of lake. Looked for M.C. at 24.51 chs.

Found - 20" Hemlock and 30" Fir, blazed and fallen over the bank. Dug into
Hemlock & found scribe marks S 3 /. As corner comes under trees

I set - 1 1/2" I.P. on top of bank North of where BT's stood from which bears

14" Fir, N.18°30'E., 24.8 ft to nail crayon mkd: RP

24" Spruce N.66°30'W., 18.2 ft. to nail crayon mkd: RP

Orig. 8" Hemlock, S.34°30'E., 8 ft. S 3

4/28/43

41

1/4 Corner for Sec. 3 and Sec. 34 of T20-12.

Found - Orig. Spruce BT with scribe marks.

Reset - 1 1/2" I.P. & 3"x3"x5' Spruce post crayon mkd: $\frac{S34}{S3} \frac{1}{4}$ T20S R12W
T21S R12W 1943.

From which bears:

Orig. 30" Spruce stump, S.44°E., 12.54 ft. to nail scribed 1/4S
BT marks are covered.

Orig. 18" Hemlock has been pulled out in construction of cat road.

I marked: 36" Spruce stump, N.58°E., 27.4 ft. to nail in blazed face crayon
mkd: 1/4 S34 RP BT.

NE corner about 25 ft. east of Cat Road.

4/2/43

42

Meander Corner, Secs. 4 and 33 of T20-12.

Found - Orig. 10" Fir BT and from it,

Reset - Corner as 8" Fir is dead & down in the lake. Set - 1 1/2" I.P. and
3"x3"x5' Post - crayon mkd. WGC $\frac{S33}{S4}$ M.C. 1943

From which bears:

Orig. 10" Fir, now 30" N.68°W., 31.68 ft. to nail scribed S33, rest
covered.

5' Fir S.55°45'W., 28.3 ft. to nail crayon mkd: S4 RP BT. No cruisers
marks here.

4/26/43

43

Section Corner for Secs. 4, 3, 9 and 10.

Found - BT's at corner about 200 ft. W. of old road, where a white & blue
auto license plate is nailed on 5 ft. Spruce mkd: X.

Set - 1 1/2" Pipe & 2"x2"x4' Fir post crayon mkd: $\frac{S4 S3}{S9 S10}$ T21S R12W

From which bears:

Orig. 24" Hemlock, really a 3' Fir, S.43°E., 14.52 ft. to nail
scribed 2, rest covered.

Orig. 36" Spruce, now 4 ft. S.36°W., 69.1 ft. to nail in overgrowth.
A hole has been cut into this tree but the scribed face is
not uncovered.

Orig. 30" Spruce now 5 ft. N.30°E., 24.7 ft. to nail in overgrowth.
The scribed face has never been uncovered.

Orig. 40" Spruce, now 4 ft. N.39°E., 44.7 to nail in overgrowth.
The scribed face has never been uncovered. Cruiser's Marks.

Ran North to Lake & found 20" Alder with scars but it stands near cabins so
may not be the orig. BT for MC. This line 13 west of RR trestle about 150'.

4/28/43

44

W. G. Corbitt
C. Boatman, J. K. Elliott for
Crown Zellerbach Corp.
1941 - 43
C.S. 52/91

RE-RENEWED NO. 69