

Douglas County Surveyor's Record of  
Government Corners Renewed

T 21 T. S. R 12 R. W. W. M.

HOVE-CHAPMAN CO. EUGENE, ORE. 97381

56

Section Corner for Secs. 24 & 25; and Secs. 19 & 30, T21-11

Set - 5/8" Iron rod

From which:

- FD OK 11/90  
M 111-9
- A 34" Cedar, bears N.71°E., 36.7 ft. scribed.
  - A 26" Hemlock, bears S.82°E., 23.6 ft. scribed.
  - An 18" Hemlock, bears S.5°E., 22.7 ft. scribed.
  - A 16" Cedar, bears N.58°W., 58.1 ft. scribed.

Corner is on top of ridge which bears NW & SE.

Richard J. Hintz  
For: International  
Paper Co.  
Sept. 1976  
M 62 - 1

57

1/4 Corner for Sec. 25; and Sec. 30 of T21-11 11/90

Set - 5/8" Iron Rod.

From which:

- FD OK 11/90  
M 111-9
- A 60" Fir, bears N.45°W., 1.8 ft. to an aluminum nail in face, bark scribed.
  - 18" Spruce, bears S.9°E., 31.5 ft. scribed corner is approx. 120 ft. north of USFS road.

9/76

58

Section Corner for Secs. 10, 11, 15 and 14.

Found - A 6" x 10" x 13" Sandstone rock with a chisled 5" high "X" and 1916 (not of record), next to a squared wooden post.

A 18" now 38" Fir stump uprooted with orig. stump hole bearing approx. N.72°E., 9.2 ft. We open well healed scar and find a chopped out blaze.

A stump hole bears approx. S.63 1/2°E., 9.2 ft.

A 24" now 22" (Barked) Cedar stump bears N.88°W., 13.2 ft. with a double (rotted out) blaze.

A 30" now 36" cedar stump bears S.69°W., 13.9 ft. with scribing "R" in badly rotted double blaze.

Set - A 1" x 36" I.P. with brass cap set at ground level marked: "Douglas County Surveyor" T21S R12W S10 S11 S15 S14 1978.

New BT's - A 6" D. Fir bears N.13°W., 11.6 ft. with scribing "T21S R12W S10 CS BT" in double blaze.

A 10" D. Fir bears N.50°E., 15.3 ft. double blazed and marked S11 T21S R12W CS BT".

A 6" D. Fir bears S.12°E., 14.5 ft. double blazed and marked "T21S R12W S14 CS BT"

A 8" D. Fir bears S.32°W., 32.1 ft. double blazed and marked "T21S R12W S15 CS BT" I do not disturb rock, the "X" bears N.W. 0.7 ft.

Note: From Schafer's mill on old Smith River Rd. 1 mile north along railroad tracks to line crossing tag, then west 300 ft. +

2/8/78

59

Section corner for Secs. 13 and 24; and Sec. 18 & 19 of T.21-11

Found - An iron pipe 2 inches diam. 17 inches high set by F.C. Frear in 1940. Ren. #5

A 7" now 8" Fir, is tipped out, bears S. 70 3/4°E., 7.4 ft. Tree partially rotted. Scribing visible "19 BT". Ren. #5

An 8" Fir now a 10 foot high stump, bears N.49 1/2°W., 18.2 ft. Tree partially rotted, has healed over blaze. Ren. #5

A Fir, 10" now 12" bears N.64°E. 21.8 ft. Has healed blaze.

A 16" now 21" D. Fir bears S.8°W., 8.4 ft. Has well healed blaze. Ren. #16

A 14" now 18" D. Fir bears S.60°E., 24.7 ft. Has well healed blaze. Ren. #16

A 13" now 18" D. Fir bears N. 72 1/2°E., (Rec. N.77°E.) 26.6 ft. Rec. 27.2 ft.) Ren. #16

A 12" now 14" Hemlock, bears N.67°W., 26.4 ft. Tree has partially healed blaze. Ren. #23

No new monument or accessories set.

11/15/78

Larry E. Monte  
Doug. Co.  
Surveyors C  
K. Reed  
P. Earle  
S. Flauser  
F. Silagy  
Nov. 15, 1978  
C.S. 60/17

R. B. Kimberling  
P. L. Earle  
Doug. Co. Sur-  
veyors Office  
Feb. 8, 1978  
C.S. 59/46