

Douglas County Surveyor's Record of
Government Corners Renewed

T 21 T. S. R 12 R. W. W. M.

ADRE-SHAPMAN CO. SURVING, ORE. 11881

Richard J. Hintz
For: International
Paper Co. - Menasha
U.S. Forest Service
Nov. 1980
M 84 - 24 A&B

Section corner for Secs. 28, 27, 33 and 34.
Found - 1" I.R. 3" below ground, Ren. #35 from which:
SE corner of brick chimney bears N.50°45'W., 178.7 ft. formerly
given as N.41°W., 162.3 ft.
50d nail on west side of pole AE 34 D bears S.36°15'W., 75.9 ft.
1
formerly given as S.36°30'W., 76.6 ft.
Set - Steel fence post 1 ft. North of corner.

RE-RENEWED SEE CORNER NO. #94 85

11/80

Gregory E. Quibell
Deputy, Douglas Co.
Surveyor
Stephen J. Flause
June, 1981
C.S. 61 / 24

NE Cor. DLC # 37.
Found - Unrecorded 3/4" I.P. protruding 6" above ground.
Burned & rotted remains of probable orig. 12", now 30" Spruce
stump. Stump has been chopped on recently, & shows no
scribing or blazed face. Stump bears N 33° W, 6.6-ft. of
found 3/4" I.P. Stump has new International Paper BT tag.
Uprooted & burned 60" Fir stump probably from Ren. # 2B. No
face or scribing visible. Approx. center of stump hole
bears S 15° E, 27.5-ft. (Rec. 25.1').
Set - Since I could not find any scribing or any other positive
evidence, I DID NOT set Brass Cap, but left 3/4" I.P.
in place.
New accessories - Spike in 36" Spruce stump, stamped "B O 2" bears
N 45° W, 76.5-ft.
Spike in 18" Spruce stump, stamped "B O 1" bears
S 68° W, 44.3-ft.
16" exposed Spruce root growing vertically over an
old stump, bears N 27° E, 38.1-ft., scribed "NE
CL 37 CS BT" in bark. (Bearing & dist. taken to
center of scribed portion of root). Above Spruce
is growing out of old stump with scribed root
growing down on the SW side.

86

RE-RENEWED SEE CORNER NO. #95

Gregory E. Quibell
Deputy Doug. Co.
Surveyors Office
1979
C.S. 61/30
(Filed: 3/17/82)

1/4 Corner common to Secs. 34, & 35. Ren. # 15.
CORNER REPORT ONLY.
Found - Station mark is an Army Corps of Engineers Brass Cap marked:
"T21S R12W 1/4 S34 S35 1966". Monument is 3-1/2" dia.
and flush with grnd. Cap is marked & oriented to the East.
A witness post & sign bears 1-ft. South. Station mark is
in fill area on South side of Hwy.101 at Westerly end of
bridge over the Umpqua River at Reedsport.
Note - See C.S. # 61/30 for supplemental information.

87

1979

Andrew T. Blachly
For: Cole & Hongell Logging Co. and
International Paper Co.
Oct. 1986
M 102 - 71

For Corner Report,
See C.S. 63/46

1/4 Corner for Section 32 and Sec. 5 of T.22-12
Found - Rotten 30" high stump (24" Spruce) N.36°W., 22.2 ft. to center
21.1 ft. to face (N.36°W., 32 lks.=21.1 ft.) with weathered
mkd. "BT". Ren. No. 3
1 1/2" I.P. with fitting, flush in marsh with white plastic cap
mkd. "Thompson RE 3683" in center. Ren. No. 38
14" red alder stump (18") N.14°E., 18.5 ft. (N.8°30'E., 18.5
with scribes "1/4S...3683BT".
14" red alder snag (17") S.72°W., 51.4 ft. (S.71 1/2°W., 51.4 ft.)
with scribes "1/4S5 3683".
New BTs - 16" Sitka spruce N.26°E., 24.0 ft. mkd. "T21S R12W S32 1/4 BT"
13" Sitka spruce S.88°E., 33.6 ft. mkd. "T22S R12W S5 1/4 BT".

88

Section corner for Secs. 32 and 33; and 5 and 4 of T.22-12
(Did not find original evidence)
Set by single proportion: 18" alum. rod with cap mkd. "T21SR12WS32S33T22S
S5S4" 8 ins. below surface of rock road.
New Accessories:
38" Sitka spruce N.46°E., 90.4 ft. mkd. T21S R12WS33 BT".
24" D. fir S.68 1/2°E., 33.7ft. mkd. "T22S R12W S4 BT"
19" D. fir, S.54°W., 81.7 ft. mkd. "T22S R12W S5 BT".
28" Sitka spruce N.49°W., 77.2 ft. mkd. "T21S R12W S32 BT".
Inlet of corrugated metal culvert bears S.54°W., 18 ft.

89