

Douglas County Surveyor's Record of  
Government Corners Renewed

T 21 T. S. R 12 R.W.W.M.

ROSE-CHARMAN CO., EUGENE, ORE. 97801

90

Andrew Blatchly  
For: Cole & Hongell  
Logging and  
International  
Paper Co.  
Oct. 1986  
M 102 - 71

FA 9/93  
M117-64

1/4 Corner for Section 33; and Sec. 4 of T22-12  
(Did not find original evidence)  
Set by single proportion: 36" alum. rod 1" high by Spruce root in draw  
with cap mkd "1/4T21SR12WS33T22SS4".  
New Accessories:  
12" Sitka Spruce N.80°E., 2.8 ft. mkd. "BT"  
16" D. fir S.46°E., 29.7 ft. mkd. "BT".  
Edge of golf course green ± 40 ft. easterly; Northmost corner  
of second story of large house overlooking golf course bears  
S.46°W., 122 ft.  
Note: Due to proximity to residences and golf course these trees were  
only marked with lower faces and did not have back tags or red painted  
bands.

10/86

\* See M 103 - 79 for Amended  
Survey and Bearing Tree info.

\* Witness Point to Meander Corner., between secs. 21 and 28, west side  
Set : A 5/8" x 76" aluminum rod with 3" International Paper Co.  
aluminum cap stamped "L.S. 1978"  
BT's: A 12" Spruce bears N57 1/2°E, 92.4 ft. Scribed "WP S21 BT".  
A 17" Hemlock bears S32°E, 99.4 ft. Scribed "WP S28 BT".  
Witness point bears N.89°14'01"E., 141.7 ft.

91

\* 1/4 Corner Sections 21 and 28.  
Set : A 5/8" x 42" aluminum rod with 3" International Paper Co.  
aluminum cap stamped "L.S. 1978"  
BT's : 13" Hemlock bears N.5 1/2°E., 11.2 ft. Scribed "1/4 S 21 BT".  
26" Hemlock bears S59°W, 23.6 ft. Scribed "1/4 S28 BT".

92

Witness Point for Section Corner 21,22,27,and 28  
Set: 5/8" x 42" Aluminum rod with 3" International Paper aluminum  
cap stamped "L.S. #1978".  
BT's A 32" White fir bears N 9°W, 14.2 ft. Scribed WP S21 Bt".  
S 28" White fir bears S 83°E, 3.2 ft. Scribed "WP S28 BT".  
Section Corner falls in river. W.P. bears S.89°14'01"W., 12.88.9 ft.)

93

Section Corner for Secs. 27, 28, 33 and 34  
Found - 1" iron rod, 4" below ground and under car. Ren. #85  
Southeast corner of chimney, N.40 3/4°W., 178.8 ft.  
Broken power pole, S.38°W., 76.0 ft. (Rec. per M84-24 S.36 1/4°W.,  
75.9 ft.)  
Set - Spike in new power pole, AE 34D / 1 bears S.39°W., 61.1 ft.

94

END OK 12/92 BY BAKER M116-46

Northeast Corner, DLC #37  
Found - 3/4" iron pipe. See Renewals #2B and 86  
16" spruce root, N.28°E., 38.0 ft.  
60" uprooted fir, S.14 1/2°E., 27. ft.  
40" rotten spruce stub, N.35°W., 6.6 ft.  
Set - 3/4" x 30" alum. rod with I.P. Co. alum. cap and marked  
"Baker 1978".

95

11/87

Robert Ward Jr.  
For: International  
Paper Co.  
Jan. 6, 1988  
M 105 - 64

Section Corner for Secs. 13, 21 and Secs. 18 and 19 of T.21-11  
Found - 2" iron pipe extending 16" out of ground. Ren. #59 #102  
16" hemlock bears N.68°W., 27.0 ft. with healed face.  
24" fir bears S.6 1/2°W., 8.4 ft. with healed face.  
20" fir stump bears S.62 3/4°E, 24.6 ft. with healed face.  
20" fir stump bears N.72 1/2°E., 26.8 ft. with healed face.  
Set - Replaced 2" iron pipe with 3 1/2" alum. cap mkd. LS 1091.  
1/6/88

96

Daniel Baker  
L.S.# 1978  
For: International Paper Co.  
M 103 - 32