Douglas County Surveyor's Record of Government Corners Renewed

R. W. 22 T. S. 4 R. W. W. M.

CORNER OF SECS. 33,34,3,4 renew corner. S.LINE T22S R4W
Tree in Sec. 34 standing. others down
Remark A Ceder 16"in dia. S.51°15' W. 19 lks. (Sec. Ren # 49 T22-4)
A Fir 18"in dia. N. 25° 50' W. 55 lks. 1
A Double Maple 14 in. in dia. S. 75° 45' E. 55 lks.

old Cor Ren. Vol. 1 Pg 17.

1/4 COR. BET. SECS. 33-34
No evidence of old witness trees. marked SEARCHED FOR-NOT FOUND Dec. 1964 W.R. C.S. 62/101
A Maple 24" in dia. S. 74½° W. 83 lks.
A ~~Maple~~ WHITE OAK 8" in dia. S. 49° E. 62 lks. 2
Rd. Yew Post M104-59, 7/88 M104-59 4/90

1/4 CORNER BET. 28-33
Renew Corner. marked new Pipe
RE-RENEWED. SEE CORNER NO. #100
A Maple 20" in dia. S. 84° E. 45 lks.
A Oak 20" in dia. bears N. 46° E. 122 lks. 3

1/4 CORNER SOUTH SIDE 33
Renew corner with Pine Stake from original trees still standing
RE-RENEWED. SEE CORNER NO. 50 3A

4

1/4 COR. SEC. 32 & 33
Set 4" x 36" Oak Post from which
A 14" W. Oak bears N. 202° W. 796.0 ft.
A 20" W. Oak bears N. 225°10' E. 852.0 ft. 104
RE-RENEWED. SEE CORNER NO.

1/4 COR. BET. SECS. 30 & 31 101
Sandstone 6" x 16" x 10" above ground & marked ¼ on south face.
O. B. T. not chopped out 36" Fir, Bears S. 63° E. 26 lks. 5
Reblazed & scribed in the bark ¼S. S. 31 C. S. B.T.
B. T. 36" Fir bears N. 77° E. __ lks. blazed in bark & marked ¼S. 30. C. S. B.T.
This tree may be an old B.T.
RE-RENEWED. SEE CORNER NO.

Ben B. Irvine G. A. McHenry Flood Cole Deputy
Sept. 18. 1928 H. L. Irvine P. D. Whitney Witness C. A. Andrew
N. E. Richardson G. Johnson Witness Witness C. A. Parker
Jim Cox Joe Jackson
EM Toland, F. L. Sandy
J. Jesperson
Witnesses
Dep. Co. Surv.
Sept. 18. 1921 April 5, 1915
Jan. 30, 1939 Book of Records #2, pg. 202-4
Field book 40. PAGE 14
Renewed Cor. Vol. 1 Pg 17
Renewed Cor. Vol. 1 Pg 17
C.S. 24/32
OLD Cor Ren. Vol. 1 Pg 17

SEE CORNER 16-17-20-21 S60°W
Position identified by one O.B.T. S.6°W. 84lks. Old scribe marks visible. Remains of old B.T. S.62E. 36 lks. rotted and burned more portion of old scar visible & also old stump checks for O.B.Ts. N. 4½° W. 148 lks.
Set for corner 4" x 6" 48" Ceder post scribed
T. 22S. R. 17 on W. face
R. 4 W. S. 16 on W. face
S. 21 4.S. on S. face
S. 20 S.W. face
8" Fir N.61°10'E. 41 lks.
30" Fir S. 71°40' E. 11 lks.
36" Fir W. 29° 5'W. 306 lks.
60" Fir S 58°25' W. 84 lks.
RE-RENEWED. SEE CORNER NO. 70
RE-RENEWED. SEE CORNER NO. 70

1/4 SEC. COR. 16-17
Position identified by O.B.T. 64" Fir N.50°W. 84 lks. 103
Set gun barrel for corner and 4" x 6" x 5' Rock based post.
Blazed and scribed O.B.T. ¼S. 16 C. S. B.T.
Blazed and scribed 8" Fir N.80° W. 22.3 ft. ¼S. 17 C. S. B.T. 7
RE-RENEWED. SEE CORNER NO.

COR. SECS. 17-18-19-20
Position identified from O.B.T. 60" Oak S.45°E. 122 lks. and O.B.T. 30" Oak N.68° W. 74 lks. This latter tree recorded original field notes N. 63° W. Scars very plain and in excellent condition so did not chop out. 8
Set 1" x 6 ft. Iron pipe for corner driven 5½ft. in ground.
Remarked O. B. T. S.45°E. 122 lks. T.22S. R.4W. S.20 C.S. B.T.
12" Fir N.87½°E. 45 lks. T.22S. R.4W. S.17 C.S. B.T.
30" Fir N. 44½° W. 30 lks. T.22S. R.4W. S. 18 C.S. B.T.
14" B. O. S.63½° W. 39 lks. T.22S. R.4W. S. 19 C.S. B.T.
RE-RENEWED. SEE CORNER NO. 66

OLD Cor Ren. Vol. 1 Pg 17