

Douglas County Surveyor's Record of
Government Corners Renewed

T. 22 S. T. S. R. 4 W. R. W. W. M.

BRUCE SHAWMAN CO. EUGENE, ORE. 97101

103

$\frac{1}{4}$ Section Corner to Sections 17 and 16. *ren #7*
Found - Gun Barrel at Corner *Also Haines' "T" Iron, not recorded.*
8" Fir N.80°W. 22.3 ft., now stump, checks for bear. & dist.
6" Fir N.84°W. 5.3 ft., no trace.
15" Yew N.14°W. 20.7 ft. Mkd: $\frac{1}{4}$ S17 BT by Haines (not recorded)
Scribed - 23" Maple N.32°E. 22.0 ft. Mkd: $\frac{1}{4}$ S16 CS BT.
Corner is in Fence Corner N. & W.

104

Wit. Corner to $\frac{1}{4}$ Corner to Sections 32 and 33.
Found - 14" W.Oak N.20 $\frac{1}{2}$ °W. 776.0 ft., true bear. N.21 $\frac{1}{2}$ °W., shows *Ren #4*
old scribing "BT".
20" W.Oak N.22°E. 852.0 ft., true bear. N.23 $\frac{1}{2}$ °E., now rotten
stump, chopped out, found scribing.
Record bearings and distances didn't come together, so Set $\frac{3}{4}$ " I. Rod
at Intersection of the distances.
Set - Brass Cap 30 ft. South Mkd: T22S R4W $\frac{1}{4}$ S32/S33 Co. Surveyor's
Wit. Cor. 30' N. to Corner. Office, 1965
Corner is 3.0 ft. N. of centerline Road #8.
B.O. - Guy Pole 4C-32A S3.3 ft. - Power Pole 4C-32 N.3°E. 60. ft.
FD OK - Dec 24 - W. Ruppert 1975-00174-C

105

$\frac{1}{4}$ Sec. Corner to Sec. 31, T22-4W. & Sec. 36, T22-5W.
Found - 8" x8" x 12" Stone at Corner Mkd: X $\frac{1}{4}$ S on top.
50" Fir S.24°W. 36 ft., now 60", bark scribing visible $\frac{1}{4}$ S31 CS.
44" Fir, now stump, N.45°E. 96 ft., bark scribing "4 S31 CS".
Set - Brass Cap along North Side Stone Mkd: T22S
R5W $\frac{1}{4}$ S36/S31 R4W
County Surveyor's Office, 1965 *FD OK 12/85
M 95-11
L Smith*
New BT's: 11" W.Oak N.38°E. 33.1 ft. Mkd: $\frac{1}{4}$ S31 CS BT.
12" Fir N.80°W. 22.0 ft. Mkd: $\frac{1}{4}$ S36 CS BT. *FD OK 10/92
R. HOFFINE M 116-2*
Corner is in Fence Corner.

106

$\frac{1}{4}$ Corner to Sections 2 and 11.
Found - 9" Fir (Orig. BT), now 40", N.30°E. 5.9 ft., chopped out, fd. scribing.
8", now 30" Fir (Orig. BT.) S.79°E. 11.9 ft.,
Rescribed: $\frac{1}{4}$ S11 CS BT.
Set - Brass Cap at Cor. Mkd: County Surveyor's T22S R4W $\frac{1}{4}$ S 2
Office, 1965 S11
New BT: 12" White Fir N.25°W. 56.5 ft. Mkd: $\frac{1}{4}$ S2 CS BT.

107

$\frac{1}{4}$ Corner to Sections 10 and 11.
Found - Orig. 40" Fir, now stump S. 10° E. ^{20'} shows bark scribing.
Original Stone has been disturbed. - No trace of S. W. BT.
Set - Brass Cap at Cor. Mkd: County Surveyor's T22S R4W $\frac{1}{4}$ S 10/S 11
Office, 1965
New BT's: 18" Cedar S.31°E. 29.0 ft. Mkd: $\frac{1}{4}$ S11 CS BT.
14" Cedar S.41°W. 26.5 ft. Mkd: $\frac{1}{4}$ S10 CS BT.

108

Sec. Corner to Sections 10 - 11 - 14 - 15.
Found - $\frac{3}{4}$ " Alum. Pipe at Corner, set by Weyerhaeuser from Orig. BT's.
Set - Brass Cap in place of pipe which was bent.
Mkd: County Surveyor's S 10 | S 11 T22S R4W
Office, 1965 S 15 | S 14
New BT's: 8" Fir N.58°E. 96.3 ft. Mkd: T22S R4W S11 CS BT.
12" I. Cedar N.11°W. 69.7 ft. Mkd: T22S R4W S10 CS BT.
12" Fir S.79°W. 38.0 ft. Mkd: T22S R4W S15 CS BT.
48" Fir S.48°E. 44.6 ft. Mkd: T22S R4W S14 CS BT.
Note - See C. S. File No. 53/105 $\frac{1}{4}$ Pg. 32 for Weyerhaeuser Notes & Corner. *#168*

109

$\frac{1}{4}$ Corner to Sections 15 and 14.
Found - $\frac{3}{4}$ " I. Pipe, set by Weyerhaeuser.
60" Fir Stump N.32°E. 47.5 ft., "W" brass plate mkd. Eng. #2149.
40" Cedar Snag N.27°W. 3.9 ft., "W" " " " "
No trace of Original BT's.
New BT: 15" Cedar S.88°W. 10.5 ft. Mkd: $\frac{1}{4}$ S15 CS BT.
Note - See Affidavit for this corner, C. S. File 53/105, Page 35.

Bruce R. Rogers, Deputy
Wm. Stoffel & Mke Stone
Dec. 1964 & Jan. 1965
C. S. File No. 53/101

RE-NEWED CORNER NO. #168