

**Douglas County Surveyor's Record of
Government Corners Renewed**

T 22 T. S. R 4 R. W. W. M.

POPE, CHAPMAN CO., EUGENE, ORG., 5181

Donald Peel
LS# 752
For: Weyerhaeuser Co.
Jan. 22, 1990
M 109 - 58

FD. OK BY HOFFME 8/94 M121-7

150

Center 1/4 Sec. 16,
Set - A 2" x 42" iron pipe with brass cap stamped "T22S R4W C 1/4 S16
PLS 752 1990".
New BT's - A 11" fir bears N42°E, 4.6 ft. scribed "C1/4S16BT".
14" fir bears S 66°E, 10.3 ft. scribed "C1/4S16BT".
13" fir, bears S 23°W, 12.8 ft. scribed "C1/4S16BT".
12" fir, bears N 7°W, 19.2 ft. scribed "C1/4S16BT".
A 6' steel fence post 1 ft. south.

Donald Peel
LS#752
For: Weyerhaeuser
Feb. 1991
M 111 - 66

151

1/4 Corner between Sections 21 & 28.
Set - 2" X 41" iron pipe with brass cap stamped "T22S R4W 1/4 S21, S28
PLS 752 1991"
BT's - 24" cedar bears N.18½°E., 127.9 ft.- previously marked "1/4S"
22" fir bears N.60°E., 167.2 ft. scribed "1/4 S21 BT"
29" fir bears S.89½°E., 245.6 ft. scribed "1/4 S28 BT"
Power Pole bears S.20¾°E., 40.3 ft.
Note - Corner lies 18 ft. east & 29 ft. south of creek.
FD OK 2/1993 BY NESS M116-60 2/91

Donald Peel
LS# 752
For: Weyerhaeuser
Feb. 1991
M 111 - 75

152

1/4 Corner between Sections 5 & 8.
Set - 2" X 41" iron pipe with brass cap marked "T22SR4W ¼ ⁵/₈ PLS 752 1991"
BT's - 17" fir bears N.4°W., 14.7 ft. scribed "1/4 S5 BT"
13" white fir bears S.73°W., 15.7 ft. scribed "1/4 S8 BT"
15" white fir bears N. 83½°E., 18.3 ft. scribed "1/4 S5 BT"
17" white fir bears S. 2½°W., 26.3 ft. scribed "1/4 S8 BT"

Donald Peel
LS# 752
For: Weyerhaeuser
May 1991
M 113 - 17

153

1/4 Corner between Sections 19 & 20
Found - 2½" iron pipe with B.L.M brass cap dated 1963.
20" fir stump, bears N.36°E., 81.1 ft. closed face Ren. # 131
14" rotted fir stump, bears N.75½°W., 25.8 ft., some reverse scribe
visible.
New BTs- 20" fir, bears S.70°W., 20.5 ft. scribed "1/4 S19 BT"
15" fir, bears S.44½°E., 22.6 ft. scribed "1/4 S20 BT"
5/31/91

Douglas County
Surveyors Office
Larry Monrean, Deputy
T.F. Franssen
S. Flause
July 30, 1991
C.S. File 64/17

154

Sec. Cor. for 35 & 36; and 2 & 1 of T.23-4
Found - 12" R.Cedar, now a 12" stump 7 ft. high with Weyerhaeuser nail
& tag bears N.35°E., (Rec. N.32°E) 22.0 ft. Ren. No. 47
50" Fir now a 38" stump 5 ft. high with Weyerhaeuser nail & tag
bears S.77°E., 41.6 ft. (Rec. S.79°E., 39.9 ft.)
32" Cedar stump 4 ft. high with Weyerhaeuser nail & tag bears
S.1°E., 32.2 ft. (Rec. S.2°W., 31.4 ft.)
66" Fir now a stump 6 ft. high with Weyerhaeuser nail and tag
bears N.43½°W., 28.6 ft. (Rec. N.45°W)
Set - A 1" x 36" Iron Pipe with brass cap marked "Douglas County Surveyor
T 22 S R 4 W
S 35 | S 36
S 2 | S 1
T 23 S
1991

*FD. OK 10/92
D. PEEL
M115-77*

New Accessories:
4" Fir marked "X BT" on double blaze bears N.77°E., 40.5 ft.
5" I.Cedar marked "X BT" on double blaze bears s.3½°E., 43.6 ft.
7" Post, fence corner, fence runs South & West bears S.68°W., 4.8'.
Monument set along northerly edge of power pole service road.
7/30/91

Douglas County
Surveyors Office
Randall Smith
Stephen Flause
November 18, 1991
C.S. File 64/21

155

Section Corner for 1 and 2; 35 and 36 of T.21-4
Found - 3½" dia. BLM brass cap on a 2½" O.D. iron pipe protruding 7"
above ground. (1958 BLM)
8" now rotted D.Fir stump of indeterminate size, no marks
visible, bears N.11°E., 46.9 ft. (agrees w/rec) Orig. BT.
20" now 18" dia. 2½ ft. high rotted D.Fir stump, no marks visible.
bears S.62°E., 79.2 ft. (agrees w/rec) Orig. BT.
56" I.Cedar BT noted as "not of record" in 1958 BLM survey, is
gone. (road construction)
29" dia. D.Fir with a fully healed double blaze, and a "W" nail
driven through the center of a 3" dia. bronze disk marked
"Reg. Engineer No. 2149" bears S.65½°E., 6.6 ft. (agrees with
1958 BLM record) Wey. BT)