

Douglas County Surveyor's Record of  
Government Corners Renewed

T 22 T. S. R 4 R.W.W.M.

KOKECHAPMAN CO. KURENE ONE 21881

155

cont. - - -

Douglas County  
Surveyors Office  
Randall Smith  
Stephen Flause  
November 18, 1991  
C.S. File 64/21

- 60" dia. 25 ft. high I.Cedar snag, bears S.7°E., 29.5 ft. (Rec. S.4½°E., 25.7 ft. 1958BLM) (No "W" nail found) Wey. Co. BT.
- 32" dia. D.Fir with a fully healed single blaze and a "W" nail driven through the center of a 3" dia. bronze disk marked "Reg. Engineer No. 2149" bears S.69°W., 42.2 ft. (agrees with record) Wey. Co. BT Ren. #77
- 26" dia. D.Fir with a fully healed single blaze and a "W" nail driven through the center of a 3" dia. bronze disk marked "Reg. Engineer No. 2149" bears N.54°W., 12.2 ft. (agrees with 1958 BLM) Wey. co.
- 12" now 31" dia. D.Fir with a fully healed single blaze, bear. N.77½°E., 73.9 ft. (Rec. N.79 3/4°E., 73.9 ft.) 1958 BLM
- 16" now 24" dia. tipped out D.Fir with a fully healed single blaze, root hole bears S.74½°E., 44.9 ft. (agrees w/rec) 1958 BLM BT.
- 7" now 12" dia. 7 ft. high cedar snag with an open blaze, scribing visible, "T22S R4W" bears N.79°W., 38.6 ft. (Rec. N.80°W., 38.6 ft.) 1958 BLM BT.
- 12" Fir bearing N.27°W., in 1958 BLM is gone.

1/4 Corner for Sections 23 and 26

156

- Found - A 3/4" I.D. iron pipe protruding 10" above ground. Ren. No. 41  
Orig. BTs looked for, none found.
- 8" now 15" dia. D.Fir with a fully healed double blaze bears West, 17.0 ft. (Rec. S.86½°W., 17.0 ft.)
- 8" now 20" dia. D.Fir with a fully healed single blaze bears N.81½°E., 26.2 ft. (Rec. N.73°E., 25.2 ft.)
- Set - 3/4" I.D. Iron pipe is referenced and removed; measured 44" long. Set a 1 3/8" O.D. x 32" long Iron pipe with a 2 3/8" dia. brass cap is set at referenced position of 3/4" I.P. Brass cap/I.P. protrudes 6" above ground. Cap is marked:  
Douglas County Surveyors Office  
T 22 S R 4 W  
    ½ S 23  
    S 26  
    1991
- 3/4" I.P. is placed along West edge of BC/IP, protrudes 4" above ground.
- New BTs - 17" dia. D.Fir double blazed and scribed "½ S23 CS BT" bears N.20°W., 20.8 ft.
- 12" dia. D.Fir double blazed and scribed "½ S26 CS BT" bears S.0½°E., 51.5 ft.
- Corner lies approx. 50 ft. East of a gravel road.

11/14/91

157

Center 1/4 Corner for Section 26

- Found - ½" Iron rod with plastic cap marked "Weyer Co.", protrudes 12" above a 2 ft. x 4 ft. long mound of stone. Ren. No. 141
- 3/4" I.D. x 35" long Iron pipe found loose in ground, protruding 2 ft. above ground. I.P. bears S.20°E., 1.0 ft. from iron rod. (source unknown)
- 37" now 37" dia. I.Cedar with a fully healed single blaze bears S.75½°E., 29.9 ft. (Rec. S.72°E., 29.9 ft.) Ren. 141
- 27" now 28" dia. D.Fir with a fully healed single blaze bears S.24½°W., 39.4 ft. (Rec. S.28½°W., 39.4 ft.)
- Distances taken to center at base, rec. dist. from Ren. No. 141 taken to "W" nail.
- Set - Position of ½" I.R. is referenced, (measures 28½" long. A DCSO 2 3/8" dia. brass cap on a 1 3/8" O.D. x 32" long iron pipe is set at referenced position. BC/IP protrudes 12" above a 4 ft. long x 2 ft. wide 1 ft. high mound of stone. 3/4" I.D. iron pipe is set along North edge of BC/IP, protruding 18" above ground, ½" I.R. is set along South edge of BC/IP, protruding 11" above ground. At corner, solid rock was hit approx. 6" below ground surface. Cap is marked: Douglas County Surveyors  
T 22 S C 1/4 . S 26 R 4 W 1991 Office
- New BTs - 13" dia. D.Fir double blazed and scribed "C 1/4 S26 CS BT" bears N.88½°E., 15.6 ft.
- 7" dia. D.Fir double blazed and scribed "C½ S26 CSBT" bears N.57°W., 5.3 ft.

11.14.91

Douglas County Surveyors Office  
Randall Smith - Stephen Flause  
November, 1991  
C.S. File 64/21