

Douglas County Surveyor's Record of  
Government Corners Renewed

22 T. S. 4 R. W. W. M.

ROSS CHAPMAN CO., SUGDEN, ORE. 5151

18" R. Cedar N.72°E. 8.5 ft. scribed T22S RAW S7 CS BT.  
16" R. Cedar S.48°E. 5.2 ft., found scribing 5 to 10 yrs. old  
on this tree "T22S RAW S18 BT, I added "C S".

C.S. File 49/59

Note - The Maple growing out of stump of old Maple BT., was also scribed  
5 to 10 yrs. ago. Scar was mostly covered but could see scribe  
marks. Bearing N.40°W. 21.1 ft.

35

1/2 Section Corner to Sections 8 & 9.

Found - Now 60" R. Fir bears N.10°W. 52.8 ft. I find no scribing, but  
old axe scar faces to corner & I find clump of White Oak  
that checks bearing & distance for Orig. N.W. BT.

Also find bottom Section of old charred Stake 24" under surface  
at Corner. - REN #18 NO #20

Set Brass Cap at Corner Mkd.: 1/2 S8/S9 T22S RAW County Surveyor's Office,  
1958.

New BT's: 24" R. Fir bears N.77°E. 65.0 ft. scribed S9 CS BT.

24" R. Fir bears N.19°W. 30.2 ft. scribed S8 CS BT.

Note: I find 1/2" I.P. at Corner and Laurel BT. as recorded, 1955.

36

1/2 Section Corner to Sections 4 & 9.

Found - Orig. 9", now 40" Cedar N.13°E, 9.9 ft., has good scribing  
on old face "1/2 S", record dist. is 1510 chains, should be 15 chs.  
Rotted Base of Large Fir that would check for Orig. S.W. BT.,  
no scribing found.

There is a 4"x 4" Sq. Stake with scribing at Corner.

Set Brass Cap at Corner Mkd.: 1/2 S4/S9 T22S RAW County Surveyor's Office,  
1958.

New BT's: 5" <sup>WHITE</sup> Fir bears S.29 1/2°W. 25.0 ft. scribed S9 CS BT. #164

I rescribe Orig. now 40", Cedar N.13°E, 9.9 ft.,  
scribed S4 CS BT.

Note: This area has many large trees near that were standing at the  
time of the Orig. Survey. There may be error in recording  
distance to original N. E. BT.

*OR. & B.T. STILL IN GOOD CONDITION  
OCT. 23, 1962 (AFTER BIG WINDSTORM)*

*Wilo C. Godfrey*

37

Section Corner to Sections 4, 5, 8, & 9.

Found - 1/2" I.P. at Corner & Orig. 21", now 26", R. Fir, has open face,  
good scribing. - REN #21

Now 60" Fir that checks bearing & distance for Orig. S.W. BT.,  
has old axed face, for bark scribing & I find faint line.

No trace of S. E. BT.

Find 60" Stump that checks bearing & distance for N.E. Orig. BT.

New BT's: 18" W. Fir bears S.50°E. 22.1 ft. scribed S9 T22S RAW CS BT.

16" W. Fir bears N.35°E. 59.0 ft. scribed S4 T22S RAW CS BT.

60" R. Fir bears S.80°W. 35.0 ft. bark scribed S8 T22S RAW CS BT.

I rescribed Orig. N.48°W. 42.2 ft. BT. S5 T22S RAW CS BT.

38

1/2 Section Corner to Sections 9 & 10.

Found - Orig. 12", now 36" Cedar N.58°E. 12.5 ft., has good reverse  
scribing on large chip cut out 2 or 3 years ago.

I find hole in ground that checks bearing & distance for  
Orig. S. W. BT.

Set Brass Cap at Corner Mkd.: 1/2 S9/S10 T22S RAW County Surveyor's  
Office, 1958.

New BT's: I rescribe, now 36", Cedar N.58°E. 12.5 ft. 1/2 S10 CS BT.

13" R. Fir S.41°W. 47.1 ft. scribed 1/2 S9 CS BT.

39

Section Corner to Sections 9, 10, 15, & 16.

Found - Orig. 8", now 26" Fir N.78°W. 14.5 ft., I open & find good  
scribing "RS".

The Orig. N.E. & S.E. BT's. down & I find hole in ground for  
Orig. S.W. BT., all check for bearing & distance.

Set Brass Cap at section corner mkd: S 9/S10 T22S RAW County Surveyor's  
S16/S15 Office, 1958. - Co. C.K.

New BT's: Rescribed Orig. N.78°W. 14.5 ft. BT., S9 T22S RAW CS BT. Jan. 1965

10" W. Fir S.36°W. 60.6 ft. scribed S16 T22S RAW CS BT. B.S.R.

24" Cedar N.15°E. 68.3 ft. scribed S10 T22S RAW CS BT.

12" Ewood East 60.6 ft. scribed S15 T22S RAW CS BT.

James W. Byron, Deputy County Surveyor  
Chairman: M. Godfrey  
S. Blaw  
May 12, 1958  
C. S. File 49/59

Block  
2/9/1911-75

RE-NEWED SEE CORNER NO. #164

RE-NEWED SEE CORNER NO. #142