

Douglas County Surveyor's Record of
Government Corners Renewed

22 T. S. 4 R. W. W. M.

James W. Byron
May 12, 1958
C.S. File No. 49/59

Search For $\frac{1}{4}$ Section Corner to Sections 9 & 16.
Found - $\frac{3}{4}$ " I. P. set by McReynolds, see U.S. File No. 41/340.
I do not find the BT., nor can we find either Orig. BT.
The tree used by McReynolds is now 60" Fir, record 30",
it shows real old axe marks. I open old scar, but
do not find scribe.

RE-RENEWED, SEE CORNER NO. #120 40

James Jones
For Woodard lbr,
July, 1958
C.S. # 42/385

$\frac{1}{4}$ Section Corner to Sections 23 & 26.
Set $\frac{3}{4}$ inch Iron Pipe.
Scribed BT's as follows:

Scribed $\frac{1}{2}$ S. Fir N. 73°E. 25.2 ft.
Scribed $\frac{1}{2}$ S. Fir S. 96°E. W. 17.0 ft.

RE-RENEWED, SEE CORNER NO. #156 41

Nick Juliano
Dec. 22, 1958
C.S. File ---
Map File
M 13 - 55

$\frac{1}{4}$ Section Corner to Section 22 & 23.
Set $\frac{1}{2}$ " Iron Pipe in a Mound of Stone,
& Two Aluminum Section Plat Markers;
16" Madrone N. 89°W. 29.0 ft.
16" Madrone S. 50°E. 67.3 ft.

(SEE ALSO H. EN. 6)
Jan. 1965 - CORNER D.K. B.B.R.

42

Section Corner to Secs. 6 & 7, T22S R4W, & Secs. 1 & 12, T22S R5W.

Found - Scribed Stake & 1" Axle at Corner. = REN # 13
Orig. 20", now 40", down & partly rotted, previously opened,
shows good scribing "111" S. 18°E. 44.9 ft. #127
Orig. 35", now 44" Shell of rotted Fir S. 68°W. 35.0 ft.,
shows old scars.
Orig. 20", now 40", down & partly rotted Fir N. 68°W. 42.2 ft.,
shows old scars, no scribing left.
Orig. 30", now Stump Hole only, N. 70°E. 33.7 ft.
Set Brass Cap at Corner Mkr. County Surveyor's Office, 1959
S1 | S6 T22S
R5W | S7 R4W
This corner renewed several years ago, but not recorded. I use
same BT's, in N.E. & S.E. I destroy scribing on BT's. to NW. & SW.
New BT's: 20" Cedar bears N. 16°E. 46.8 ft. scribed T22S R4W S6 BT,
(I add CS.) - Sec 211-40
18" Chinquipin bears S. 30°E. 14.8 ft. scribed Tp22S R4W
S7 BT (I add C.S.)
6" R. Fir bears N. 64°W. 13.0 ft. scribed T22S R5W S1 CS BT.
6" Hemlock bears S. 77°W. 30.8 ft. scribed T22S R5W S12 CS BT.

RE-RENEWED, SEE CORNER NO. #127 43

James W. Byron, Lepuy
S. A. Bilow
April 22, 1959
C. S. File No. 49/59

Section Corner to Sections 19 & 30, T22S R4W, & Secs. 24 & 25, T22S R5W.
Found - Original 10", now 28" Fir Stump. I open & find good scribing,
"S", N. 52°W. 21.8 ft. I find no Trace of other Orig. BT's.
This corner was renewed years ago by Theil, not recorded.
Theil set 5"x 6"x 15" Stone with + on top at Corner & bark
scribed Orig. N.W. BT. "24".

Theil also scribed B. Oak bears S. 16°W. 27.7 ft.

Note - Corner is under E.W. Fence.

Set Brass Cap at Corner & alongside Corner Stone, Mark Cap, County
Surveyor's Office, 1959

	S24	S19	
R5W	S25	S30	R4W T22S

New BT's: 5" R. Fir bears N. 25°W. 31.0 ft. scribed S24 T22S R5W CS BT.
8" R. Fir bears N. 20°E. 49.5 ft. scribed S19 T22S R4W CS BT.
10" B. Oak bears S. 16°W. 27.7 ft., Theil's BT., partly grown
over, I add scribe CS.
6" R. Fir bears S. 30°E. 26.1 ft. scribed S30 CS BT.

RE-RENEWED, SEE CORNER NO. #74 44

Section Corner to Secs. 30 & 31, T22S R4W, & Secs. 25 & 36, T22S R5W.
Found - Orig. 36", now 44" Fir N. 52°W. 27.1 ft., shows good bark
scribe near base "BT".
Orig. 30", now 40" Fir Stump S. 16°W. 30.4 ft. I open & find
good scribe "6".
Orig. 24", now 30" Stump shows good scar, I do not open,
S. 37°E. 26.0 ft. record S. 37°E. 21.8 ft.
No trace of Orig. N.E. BT. (continued over)

45