

Douglas County Surveyor's Record of
Government Corners Renewed

T. 22 S. T. S. R. 4 W. R.W.W.M.

Milo E. Godfrey, Deputy County Surveyor
Vernon Tracy and Mike Stone
September 1962
C. S. File No. 49/42

FOOK
LE Robert
12/194 4/21-26
FOOK
2/197 11/17-75
FOOK-D. Rees
11/15-77
9/92

*FOOK Robert's
12/194 4/21-26* **60**
 1/2 Corner to Sec. 6, 22-4W. & Sec. 31, T21-4W.
 Found - Iron Bolt, 1" diam., with square head, at corner.
 36" Fir, uprooted & down, S.10°E. 32.3 ft. This tree shows an old
 face, now charred & with no scribing visible, which would have
 faced corner when tree was still standing. See Affidavit in file
 by Mr. Glen Coons, which he swears he saw scribing on this tree
 while it was still standing, (Cole, 1914).
 No trace found of either Original Bearing Tree.
DID NOT SET BRASS CAP.
 New BT's: 16" W.Fir S.32°E. 63.6 ft. Mkd: 1/2 S6 CS BT.
 24" D.Fir N.24°W. 34.5 ft. Mkd: 1/2 S31 CS BT.
 Corner lies 4.5 ft. North of E. & W. Fence Line.

61
 Sec. Cor. to Secs. 6 & 5, T22-4W. & Sec. 31 & 32, T21-4W.
 Found - Old Fir Stump, now 42" diam., N.60°E. 52.8 ft. Found traces of
 old bark scribing, probably 50 yrs. old or more. "CS" is all that
 is legible. I believe this to be the Orig. N.E. BT. which was later
 bark scribed.
 No trace found of the other 3 Orig. BT's. A fir tree, approx.
 10 ft. North of Corner has N. & S. line blazes approx. 20 yrs. old.
 Set - Brass Cap at Cor. Mkd: County Surveyor's

S31	S32	T21S
S 6	S 5	T22S

 R4W
 Office, 1962
 New BT's: 14" W.Fir N.32°E. 18.0 ft. Mkd: T21S R4W S32 CS BT. *121*
 18" D.Fir N.50°W. 15.3 ft. Mkd: T21S R4W S31 CS BT.
 9" W.Fir S.30°E. 30.8 ft. Mkd: T22S R4W S5 CS BT.
 13" D.Fir S.17°W. 58.4 ft. Mkd: T22S R4W S6 CS BT.
 A Fence Corner, fences West & S.E., bears S.65°W. 4.5 feet.

62
 1/2 Corner to Sections 14 and 23.
 Found - Dead Fir Snag, now 38", S.60°W. 25.7 ft., cut open & fd. good scrbing.
 I. Cedar, now 36", N.8°W. (instead of N.8°E.) 23.8 ft., shows good
 axe scar. Tree alive & looks in good condition.
 Set - Brass Cap at Cor. Mkd: Doug. County Surveyor's T22S R4W 1/2

S14
S23

 Office, 1962
 New BT's: 14" D.Fir N.66°W. 11.3 ft. Mkd: 1/2 S14 DCS BT.
 14" D.Fir S.70°W. 51.5 ft. Mkd: 1/2 S23 DCS BT.
 A 1/2" aluminum pipe bears S.66°E. 2.0 feet from corner.
 New BT: 5" Fir S.32°W. 83.6 ft. Mkd: 1/2 S23 CS BT. (Marked Dec. 14, 1964)

63
 Section Corner to Sections 5 - 6 - 7 - 8.
 Found - Fir Stump, now 48", S.82°E. 22.4 ft., cut open (to 6" diam.) &
 find good scribing "8".
 Fir Stump, now 48", S.89 1/2°W. 21.8 ft. No scars or scribing found.
 Rotted remains of Fir, uproot, N.51°W. 58.7 ft. Too far gone to
 show scars or scribing.
 No trace found of N. W. BT.
 Set - Brass Cap at Cor. Mkd: County Surveyor's T22S R4W

S6	S5
S7	S8

 Office, 1962
 New BT's: 10" W.Fir S.9°W. 80.8 ft. Mkd: T22S R4W S7 CS BT,
 12" D.Fir S.20 1/2°E. 34.8 ft. Mkd: T22S R4W S8 CS BT.
 No other trees available.
 Scribe 30" Fir Stump N.15°E. 35.8 ft. Mkd: T22S R4W S5 CS BT.
 A 1/2" aluminum Pipe bears N.75°E. 2.0 feet from corner.

64
 Section Corner to Sections 14 - 15 - 22 - 23.
 Found - Haines' "T" Iron & Cap at Corner. (SEE H. ON 6)
 Dead Fir Snag, now 36", N.47°W. 11.9 ft. Cut open & fd. good
 scribing "T" on small portion of old face.
 36" Fir S.77°W. 14.5 ft., uprooted & down.
 Fir, now approx. 30", S.52°E. 33.0 ft., uprooted & down.
 No trace of Orig. N.E. BT., Recently scribed 22" D.Fir N.75°E.,
 approx. 25 feet, not chained, scribed T22SR4W S14 BT. in wood & "363".
DID NOT SET BRASS CAP.
 New BT's: 12" D.Fir S.68°W. 50.3 ft. Mkd: T22S R4W S33 CS BT.
 19" D.Fir N.42°W. 87.6 ft. Mkd: T22S R4W S15 CS BT.
 No trees available in S.E. quadrant.

Jan. 1965 - CORNER O.K. B.E.R.