

Douglas County Surveyor's Record of
Government Corners Renewed

T. 22 S. T. S. R. 4 W. R.W.W.M.

KOKE-CHARMAN CO., EUGENE, ORE. 97101

75

$\frac{1}{4}$ Sec. Cor. to Sec. 30, T22-4W. & Sec. 25, T22-5W.
Found - 40" Fir Stump N.53°W. 19.8 ft. Opened by Haines,
scribing "4S" visible on old face.
Remains of Laurel Stump with Laurel Sprouts growing out of it,
S.67°E. 25.1 ft., not enough of stump left to find scars.
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1963
T22S R5W $\frac{1}{2}$ S25/S30 R4W
New BT's: 18" D.Fir S.32°E. 37.0 ft. Mkd: $\frac{1}{2}$ S30 BTCS.
10" D.Fir N.45°W. 51.3 ft. Mkd: $\frac{1}{2}$ S25 CS BT.
Note - Fence line running approx. N. & S. bears West 65.0 ft.

Milo E. Godfrey, Deputy
V. Tracy and M. Stone
July and August 1963
C. S. File No. 49/59

76

Sec. Cor. to Secs. 27 - 28 - 33 - 34.
Found - Badly rotted old Oak Stump S.69°E. 183.5 ft., portion of
stump lying alongside shows good rev. scrbing. Ray Miller
remembers chopping this piece out of stump about 10 yrs. ago,
when corner was found & renewed by O.Thiel. (not recorded)
Remnants of old Oaks to NE. & N.W. which approx. fit bear. &
dist. for Orig. N.E. & NW. BT's. No marks found.
No trace of Orig. SW. BT.

Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1963
T22S R4W S28/S27
S33/S34

Rescribe Thiel's Trees approx. 10 years ago for BT's:
26" W.Oak S.16°W. 39.9 ft. Mkd: T22S R4W S33 CS BT.
24" B.Oak S.49°E. 121.2 ft. Mkd: T22S R4W S34 CS BT.
33" W.Oak N.13 $\frac{1}{2}$ °W. 127.5 ft., shows good scars, healed over.
Didn't remark.

58" D.Fir N.10°E. 175.4 ft. Mkd: T22S R4W S27 CS BT.
A 1 $\frac{1}{2}$ " Iron Rod & sq. Fir Stake bears S.36°W. 4.2 feet.
Corner lies on very steep, grassy south slope, evidence of old slide
area.

Sec. Cor. to Secs. 1 & 2, T22-4W. & Secs. 35 & 36, T21-4W.
GLO Survey Record Post, not found.

7" Fir S.80°W. 16 lks., no evidence
8" Fir N.11°E. 71 lks., rotted remains of a fir stump.
20" Fir S.62°E. 120 lks., rotted remains of a fir stump.
12" W.Oak N.70°W. 45 lks., no evidence.

Set - Monel Pipe for Cor. from rotted Stump N.11°E. 71 lks.
and from rotted stump S.62°E. 120 lks.

Referenced by Glen McChesney (Weyerhaeuser Method) Decl. 20°

12" Fir S.67°E. 6.5 ft.
53" I.Cedar S. 6°E. 25.8 ft.
35" Fir S.69°W. 42.2 ft.
47" Fir N.55°W. 12.0 ft.

$\frac{1}{4}$ Cor. Common to Sec. 2, T22-4W. & Sec. 35, T21-4W.

It appears from the study of the GLO plats that this is
a common corner.

GLO Survey Record Post, not found.
36" Fir N.30°E. 4 lks., now 58" Fir, bark scribing visible.
30" Fir S. 4°W. 24 lks., now 48" Fir, bark scribing visible.

Set Monel Pipe for Corner

Referenced by Glen McChesney (Weyerhaeuser Method) Decl. 20°

47" Fir S. 4° W. 15.1 ft., Orig. BT.
58" Fir N.29°E. 1.7 ft., Orig. BT.

$\frac{1}{4}$ Cor. common to Sec. 1, T22-4W. & Sec. 36, T21-4W.

GLO Survey Record Post, not found.
18" Fir N.31°E. 20 lks., faces plain, not chopped out.
40" Cedar S.10°W. 73 lks., down cedar with roots located to fit notes.
Set Post for Corner.

Referenced by Glen McChesney (Plates & "W" nails only) Decl. 20°

28" Fir N.32°E. 12.6 ft. Orig. BT.
18" Fir S.35°W. 21.2 ft.

See Thiel's
Book 20 Pg. 1

RECORDED & INDEXED NO. 155

RECORDED & INDEXED NO. 95

Weyerhaeuser Co.
Glen McChesney
Lane County Records
Sec. C. S. File No. 53/1

78

79