

Douglas County Surveyor's Record of
Government Corners Renewed

T. 22 S. T. S. R. 4 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 9181

97

Section Corner to Sections 15 - 16 - 21 - 22.
Found - Haines' "T" Iron & $\frac{3}{4}$ " I. Pipe at Corner. (See Ren. #68)
44" Fir S. 28° E. 76.3 ft., scribing visible. Orig. BT.
54" Fir N. 72° W. 133.4 ft. Orig. BT. Remarkd.
28" Fir N. 31° E. 37.7 ft., pushed out by loggers.
12" Fir S. 12° W. 14.7 ft., pushed out by loggers.
New BT's: 8" Fir S. 15° W. 128.6 ft. "T22S R4W S21 CS BT."
13" Fir N. 84° E. 64.0 ft. Mkd: T22S R4W S15 CS BT.
FO OK 3/1993 By NESS M110-60 Dec. 14, 1964

Section Corner to Sections 28 - 29 - 32 - 33. 98
Found - $\frac{3}{4}$ " Iron Bar at Cor. and $\frac{3}{4}$ " I. Rod., not recorded.
24" W. Oak S. 88 $\frac{1}{2}$ ° W. 202 ft., found scribing "BT". #171
(now dead 32" W. Oak)
N. W. & N. E. BT's, not found. No S. E. BT.
New BT's: 16" B. Oak S. 42° W. 88.0 ft. scribed T22S R4W S32 CS BT.
11" W. Oak N. 33° W. 58.5 ft. Mkd: T22S R4W S29 CS BT.
28" Fir N. 7° E. 52.7 ft. Mkd: T22S R4W S28 CS BT.
No S. E. Bearing Tree.

See Thess's
Book on Pg. 5

RE-RENEWED, SEE CORNER NO. #171

$\frac{1}{2}$ Corner to Sections 17 and 18. 99
Found - Brass Cap at Corner. (See Ren. #31).
20" Maple S. 82° W. 80.8 ft., down, scribing visible.
18" Maple S. 11° W. 96.3 ft., cut down in highway R/W.
28" W. Oak N. 49° E. 225 ft., cut " " #132
New BT's: 14" B. Oak S. 5° W. 131.8 ft. Mkd: $\frac{1}{2}$ S18 CS BT.
8" B. Oak S. 2° E. 138.8 ft. Mkd: $\frac{1}{2}$ S17 CS BT.

$\frac{1}{2}$ Corner to Sections 28 and 33. 100
Found - 12" W. Oak S. 39 $\frac{1}{2}$ ° W. 43 lks., opened & found scribing, REN. #3
" $\frac{1}{2}$ S CS (now 24")
18", now 24" W. Oak N. 46° E. 122 lks., good scar.
Note - Corner falls in Creek, therefore set Witness Corner
Set - Brass Cap Mkd: T22S R4W 1964 County Surveyor's
Wit. Corner WC $\frac{1}{2}$ S 28 Office, 1964
S33 Corner 40' West.
New BT's: 18" W. Oak N. 57° E. 52.0 ft. Mkd: WC $\frac{1}{2}$ S 28 CS BT.
20" W. Oak S. 45° W. 50.6 ft. Mkd: WC $\frac{1}{2}$ S 33 CS BT.

FO. OK
2/9/91 M110-60

$\frac{1}{2}$ Corner to Sections 30 and 31. 101
Found - 6" x 16" x 10" Stone, $\frac{1}{2}$ on N. face, has been disturbed. (See Ren. #5)
10" Orig. Fir S. 63° E. 17.2 ft., now 36", opened & found
Scribing " $\frac{1}{2}$ S"
36", now 43" Fir N. 77° E. 58.7 ft., bark scribed. #145
Set - Brass Cap at Cor. Mkd: County Surveyor's T22S R4W $\frac{1}{2}$ S 30
Office, 1964 S 31
New BT's: 9" Fir N. 62° W. 7.6 ft. Mkd: $\frac{1}{2}$ S30 CS BT.
16" W. Fir S. 52° W. 16.2 ft. Mkd: $\frac{1}{2}$ S31 CS BT.
Note - Fence E. & W. 4 ft. South.

Sec. Cor. to Secs. 32 & 33, T22-4W. & Secs. 4 & 5, T23-4W. 102
Found - 1" plum Pipe at Corner, not recorded.
40" Fir S. 20° E. 30.4 ft., now burned stump.
16" Fir S. 30° W. 51.5 ft., now stump, good scar.
18" Fir N. 10° W. 50.8 ft., open, shows scribing "BT".
16" Fir N. 54° E. 11.9 ft., not found.
New BT's: 9" Fir S. 80° E. 25.0 ft. scribed T23S R4W S4 CS BT.
8" Fir N. 52° E. 40.4 ft. Mkd: T22S R4W S33 CS BT.
19" B. Oak N. 12° W. 15.6 ft. Mkd: T22S R4W S32 CS BT.
Note - Fence N. & S. 4.4 ft. West.

Wm. S. Storfel
Mike Stone
December 1964
C. S. File No. 53/101

Jan. 1965