

Douglas County Surveyor's Record of  
Government Corners Renewed

22 T. S. 5 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

SEE FILE ?

Center corner of section 14.  
Set 1" x 36" iron pipe at intersection of mid-section lines  
from which

A 32" Fir, N. 50° W., 25.8 feet. (nail in tree)  
A 12" Fir, S. 50° E., 28.0 feet. (nail in tree). # 206

25

Section corner to sections 13, 14, 23 and 24.

Found:

Junction of board fence going East on wire fence going North and South.  
Evidence of old bearing trees in NW, NE, and SE quadrants.

Set 2" x 24" iron pipe at intersection of fences from North, South and East.

Fir burned out stub, N. 53° W., 14 feet.

Fir burned out stub, S. 82° E., 33 feet.

Fir burned out stub, S. 19° W., 53 feet.

F. D. McMichael disposes to say that he has always accepted said fence corner as above mentioned.

26

B. H. McCallicuddy

March, 1955.

C. S. File No. 42/33.

Wilford N. Haines

March, 1955.

C. S. File No. M2-63.

1/4 corner to sections 4 and 9.

Found scribed stake.

ALSO SEE THOMAS'S BOOK 5 PG 45

Set angle iron with brass cap inscribed - Survey point - Wilford N. Haines.

27

ALSO SEE M 95-64 A & B

1/4 corner between secs. 23 & 26.

Found:

32 inch Fir, S. 42° W., 29.0 feet.

50 inch Fir, N. 2° E., 52.0 feet. (Both original B. T.s)

Set 1 inch iron pin.

28

Gilbert A. Gardner

Sept., 1956

C. S. File 42/179.

Reset Corner post for Sections 31 & 32. SEE ALSO #1

On Stan. parallel from which:

R. Fir 8 ft. diam. bears N 75° 20' E 43 lks. (Old BTs in evidence)

R. Fir 12 inch diam. bears N 33° 38' W 1.48 lks. 49

Corner of Section 16, 17, 20, & 21.

Marked R. Fir 16 inch diam. from which:

R. Fir 10 inch bears N 59° 00' E 16 lks.

R. Fir 13 inch bears S 26° 00' E 23 lks.

R. Fir 13 inch bears S 53° 40' W 34 lks.

R. Fir 10 inch bears N 40° 45' W 34 lks.

SEARCHED FOR NOT FOUND  
FEB. 1965 C.S. 53/101 B.B.R.  
JUNE, 1973 NOT FOUND - WOOLEY LOGGING

29

1/4 Section Corner to Sections 8 & 9.

Found - Original 6" now 43" W. O. S. 30° E. 25.7 ft. This opened by Richardson 1948 Original Scribe "BT" visible. Brass Cap set by Richardson Not found. High fill now covers this area. Chinquapin scribed in 1948 not found. - REN. # 19

Set Brass Cap at Corner marked 1/4 S8/S9 T22S R5W Co. Surveyor's Off., 1957.

New Bearing Trees: I rescribe original 43" W.G. S. 30° E. 25.7 ft.

1/4 S9 CS BT.

6" R. Fir bears N. 56° E. 156.1 ft. scribed 1/4 S9 CS BT.

30

Renew N. E. Corner D. L. C. No. 40. REN. # B

Found - Stone monument with good chisled cross. Also 1 1/2" Steel

Shaft alongside Stewart's BTs. Have been cut. Check bearings & distances to low cut stumps.

New Bearing Trees: 7" R. Fir bears S. 80° W. 12.5 ft. scribed N.E.

CL 40 CS BT.

13" B. Oak bears N. 51° E. 39.8 ft. scribed N.E.

CL 40 CS BT.

31

James W. Byron, Dep. Co. Surveyor

M. Godfrey

S. Billow

Oct. & Nov. 1957

C. S. File No. 49/19

Volume 2 Page 264