

Douglas County Surveyor's Record of
Government Corners Renewed

22 T. S. 5 R. W. W. M.

KOEE-CHAPMAN CO., EUGENE, ORE. 97196

James W. Byron, Deputy County Surveyor
M. Godfrey
S. Bilow
Jan. 27, 1958
C. S. File No. 49/59
SEE R.M. 1-40 - 1952 Sur.

(cont'd from preceeding page)

(#35 CONT.)

Set Brass Cap at Corner marked, $\frac{1}{4}$ S11 T22S R5W County Surveyor's
S14 Office, 1958

New BTs: 34" Cedar bears S.39°E. 73.0 ft. scribed $\frac{1}{4}$ S14 CS BT.
7" R. Fir bears N.16°E. 51.2 ft. scribed $\frac{1}{4}$ S11 CS BT.

Renew Section Corner to Sections 11, 12, 13, & 14.

Found - Stake & part of Iron Bed Frame at corner. - *See RM 1-40*
40" W. Fir that bears S.78°W. 7.5 ft. Has partly open face,
good scribing "22 S R" is visible on scribed face 12" in
from surface.

Old Rotted Stump that check record bearing & dist. No scribing
left for N.W. & N.E. BTs.

Note - From Corner check record dist. to Creek going North & going West.

Set Brass Cap at Corner marked S11|S12 T22S R5W County Surveyor's
S14|S13 Office, 1958.

New Bearing Trees:

14" Cedar bears North 53.0 ft. scribed S11 T22S R5W CS BT.
30" Cedar bears N.49°E. 94.5 ft. scribed S12 T22S R5W CS BT.
40" W. Fir bears S.78°W. 7.5 ft. scribed S14 T22S R5W CS BT.
6" R. Fir bears S.69°E. 168.0 ft. scribed S13 T22S R5W CS BT.

1902 D.F. THIEL
MCD BT CS 64/49 Pg 15

36

FD. OK 12/87
D. PEEL
M105-27

Section Corner to Sections 1, 2, 11, & 12.

Found - Orig. 10" now 30" W. Fir S.43°E. 28.4 ft. I open & find good
scribing " / \".

Orig. 40" now 50" Fir Snag N.19°W. 29.7 ft. This BT. has
been burned, bark damaged, no scribing found. Checks
record bearing & distance.

Note: I find 3" x 3" scribed Sq. Stake & mound of Stones bears
N. 44°E. 68.4 ft. from Brass Cap. I set for Section Corner.
Also find BTs. scribed for Sq. Stake Corner. I believe this
corner established less than 5 years ago. I can find no
trace of any original BTs. at Sq. Stake Corner. - *SEE REN. #83*

Set Brass Cap at corner mkd: S 2|S 1 T22 S R 5W County Surveyor's
S11|S12 Office, 1958

New BTs: 17" W. Fir bears S.87°W. 24.8 ft. scribed S11 T22S R5W CS BT.
12" Hemlock bears N.32°W. 1.5 ft. scribed S 2 T22S R5W CS BT.
24" R. Fir bears N.72°E. 36.0 ft. scribed S 1 T22S R5W CS BT.
I rescribed Original now 30" W. Fir S.43°E. 28.4 ft.
S12 T22S R5W CS BT.
8/72 - *SEE SHANER'S SURVEY M 42-68*

Section Corner to Sections 14, 15, 22, & 23, *FO. OK 8/94 BY BAKER*
M 119-39
Found - Orig. 40" now 52" B. O. N. 9°E. 13.9 ft. I open & find good
scribing "2 S".

Rotted Base of Large Fir Stump that checks bearing & distance
for Orig. N. W. BT.

1" Angle Iron with 1" Brass Cap mkd, 239 Survey Point.

6" x 2" Sandstone 14" above ground alongside angle iron at
4 way fence corner which is at section corner.

I Scribe New BTs: 18" R. Fir bears N.68°E. 24.5' S14 T22S R5W CS BT.
7" R. Fir bears S.42°E. 17.5ft. S23 T22S R5W CS BT.
14" R. Fir bears N.11°W. 22.9ft. S15 T22S R5W CS BT.
10" R. Fir bears S.16°W. 30.7ft. S22 T22S R5W CS BT.

Search for $\frac{1}{4}$ Corner to Sections 15/14.

Found - $\frac{2}{4}$ " I.P. & Post.

56" Fir N.15°W. 33.8 ft. - New scribed $\frac{1}{4}$ S BT.
I can find no trace of original BTs.

James W. Byron, Deputy County Surveyor
M. Godfrey
S. Bilow
Jan. 29, 1958
C. S. File No. 49/59
SEE R.M. 1-40 - 1952 Survey

37

SEE
NOTE
IN FILE

38

39

139