

Douglas County Surveyor's Record of
Government Corners Renewed

22 T. S. 5 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 97196

Search for Section Corner 10, 11, 14, & 15. 138⁴⁰
 Found - 3" x 3" Sq. Scribed Post 2 or 3 years old and 3" x 3" Sq. Scribed Stake 10 years old.
 1½" Iron Pipe 16" above ground. These monuments set record distance & bearing from now 40" R. Fir which was partly open. I open to center, no old face or scribing found. - SEE Cor. #84
 No trace of any original BTs. found.
 I believe this corner has not been renewed in proper place.
 I find scribing & faces on following trees scribed about 10 years or less.
 30" R. Fir N.24½°E. 26.0 ft.
 38" R. Fir S.29°E. 48.7 ft.
 27" R. Fir S.29°W. 42.8 ft.

Section Corner to Sections 2, 3, 10, & 11. 41
 Found - Orig. 48" now 60" Cedar Stump shows old face & faint scribing "T R /" N.78°E. 17.2 ft. (SEE REN. # 96 1952 VISIT)
 Bases of Orig. S. W. & N. W. BTs. Check bearing & distance.
 ½ Iron Pipe & 3" x 3" Sq. Scribed Stake at Corner.
 Set Brass Cap at Corner Mkd. S 3/S 2 T22S R5W County Surveyor's Office, 1958. #189
 See Sketch in File for exact location of corner.
 New Bearing Trees: 10" R. Fir N.34°E. 39.5 ft. scribed S 2 T22S R5W CS BT.
 11" R. Fir N.13°W. 21.2 ft. scribed S 3 T22S R5W CS BT.
 6" R. Fir S.6½°E. 120.8 ft. scribed S11 T22S R5W CS BT.
 8" R. Fir S. 8°W. 54.2 ft. scribed S10 T22S R5W CS BT.

Section Corner to Sections 28, 29, 32, 33. 42
 Found - Original 18" now 36" rotted stump N.71°E. 41.6 ft. This BT. opened years ago, now has small section of orig. face in place with good scribing "S28 22".
 Also find 30" Fir that checks record dist. & bearing for orig. 3" Fir S.66°W. 27.5 ft. I do not open.
 At corner I find mound of Stone & 12"x12"x12" Stone with chisles +.
 Set Brass Cap at corner & alongside Mound of Stone Marked: S29/S28 T22S R5W County Surveyor's Office, 1958. S32/S33 FO. D.C. OK. 10/24 S. BLOOM 179.64
 New Bearing Trees: 24" R. Fir bears S.86°W. 18.8 ft. scribed S33 T22S R5W CS BT.
 7" R. Fir bears N.32½°E. 14.3 ft. scribed S23 T22S R5W CS BT.
 8" W. Fir bears N.40½°W. 51.5 ft. scribed S29 T22S R5W CS BT.
 33" R. Fir bears S.29.4 ft. scribed S32 T22S R5W CS BT.
 CORNER FOUND O.K. Feb. 1965 - B.B.R.

¼ Section Corner to Sections 27 & 26. 43
 Found - 12"x8"x5" Stone with shisled + on top.
 15" now 24" R. Fir., I open lower scar & find good scribing "BT". Stone & Fir BT from Theils Book = 14. I find Base of old Oak stump that checks original distance & bearing for S.E. BT. I find no trace of orig. N.W. BT.
 Set Brass Cap alongside Corner stone marked ¼ S27/S26 T22S R5W County Surveyor's Office, 1958.
 New BT.: 10" Fir N.48°W. 24.0 ft. scribed ¼ S27 CS BT. FO. O.K. Feb. 1965 LL.

¼ Section Corner to Sections 34 & 35. 44
 Found - Both BTs. as recorded by Theil (1942-?) Ren. # 15
 12" B.O. now 14", old face partly open scribing visible, checks bearing & distance.
 8" W.O. now 8" closed face, checks dist. Bearing Should be S48°W. Both BTs. partly dead. I scribe new BT's.
 Set Brass Cap alongside corner Stone marked County Surveyor's Office, 1958, S34/S35 ¼ T22S R5W.
 New BT's: 14" R. Fir bears N.86°W. 7.0 ft. scribed ¼ S34 CS BT.
 13" R. Fir bears S. 3°W. 10.0 ft. scribed ¼ S34 CS BT.

James W. Byron, Dep. Co. Surv.
 M. Godfrey
 S. Bilow
 Jan. 31, 1958
 C. S. File No. 49/59
 See RM. 1-40-1952
 BUNNEY

James W. Byron, Deputy
 M. Godfrey
 S. Bilow
 Jan. 21, 1958
 C. S. File No. 49/59

James W. Byron, Deputy
 M. Godfrey
 S. Bilow
 Feb. 24, 1958
 C. S. File No. 49/59