

Douglas County Surveyor's Record of
Government Corners Renewed

22 T. S. 5 R. W. W. M.

Section Corner to Sections 19, 20, 29, & 30. 50
Found - Both Orig. BT's.
Orig. 18" now 32" W, Oak N.85°E. 298.3 ft., I open & find good scribing.
Orig. 30" now 7' B. Oak, shows good old face, now rotted. Checks bearing & dist. S.65°E. 412.5 ft.
Find 6" x 12" x 4" Stone that bears North 8.0 ft. from Corner. I do not find the mound of stone nor the 12" x 14" Stone as recorded at Original Corner.
Set Brass Cap at Cor. Mkd. $\frac{S19}{S30} / \frac{S20}{S29}$ T22S R5W County Surveyor's Office, 1958
New BT's: 5" W. Oak bears N.29°E. 95.4 ft. scribed S20 CS BT.
16" W. Oak bears S.81°E. 113.0 ft. scribed S29 T22S R5W CS BT.
6" W. Oak bears S.80°W. 24.4 ft. scribed S30 CS BT.
7" W. Oak bears N.25°W. 64.2 ft. scribed S19 CS BT.

FD OK, JAN. '95, M121-46

$\frac{1}{4}$ Section Corner to Sections 29 & 28. 51
Found - Orig. 16" now 24" W. Oak Snag N.72°E. 56.1 ft. I open upper section & find good scribing " "
No trace of Orig. N.W. BT.
I use Orig. N.72°E. W. Oak Snag to renew Corner.
Set Brass Cap at Corner Mkd: $\frac{1}{4}$ S29/S28. T22S R5W County Surveyor's Office, 1958
New BT's: 6" W. O. bears N. 6 $\frac{1}{2}$ °E. 18.5 ft. scribed $\frac{1}{4}$ S28 CS BT.
14" R. Fir bears N.22 $\frac{1}{2}$ °W. 15.7 ft. scribed $\frac{1}{4}$ S29 CS BT.
Note: This Corner was renewed by Eppstein, 1927. I find 1" I.P. at his corner which bears N.20°E. 8.0 ft. from brass cap. Also find both BT's which are now stumps only. I open S.59°E. 64.0' BT. & find good scribing " $\frac{1}{4}$ S". I do not open S.W. BT., shows good scar. The different positions for the location of this corner is due to the fact that I now find positive proof the W. Oak Snag is one of the Orig. BT's. - REN.#12
See Sketch in file for exact location of Brass Cap & Eppstein's Corner.

FD B.C. OK 12/10/58 M79.64

$\frac{1}{4}$ Section Corner to Sections 19 & 20. 52
Found - Orig. 24", now 42" Fir Stump S.70°E. 94.4 ft., Butt Section of Log on ground. I open old scar & find good scribing " $\frac{1}{4}$ S". Also find rotted Stump that checks bearing & distance for Orig. N. E. BT.
Set Brass Cap at Corner Mkd: $\frac{1}{4}$ S19/S20 T22S R5W, County Surveyor's Office, 1958
New BT's: 18" Maple bears N.68 $\frac{1}{2}$ °E. 64.0 ft. scribed $\frac{1}{4}$ S20 CS BT.
24" R. Fir bears N.44°W. 59.5 ft. scribed $\frac{1}{4}$ S19 CS BT.
See Sketch in file for exact location of $\frac{1}{4}$ Corner.

Section Corner to Sections 4, 5, 8, & 9. 53
Found - W. Oak N.25°W. 147.8 ft. Old BT., marks visible, center decayed, blaze not grown over.
Set 3"x3"x3' Oak Stake.
Remarked: 20" Fir S.40°E. 8.4 ft.
20" Fir S.63 $\frac{1}{2}$ °W. 26.9 ft.
20" Fir N.40°W. 32.3 ft.
12" Fir N.18°E. 24.8 ft.

RE-RENEWED, SEE CORNER NO. 66

Center of Section 4. 54
Set Lot marker at Intersection of N. & S. and E. & W. Center Lines.
The 16" scribed W. Fir bears N.39°44'E. 62.4 ft.
Scribed - 2 ft. D. Fir S.39°36'E. 34.6 ft.

SEE ALSO C/4 AS SET IN 1924 - Vol 2 Pg. 176 P.B. 30052 R. 20 & M 83-16 - 1980 SURVEY BY R. DEAN

$\frac{1}{4}$ Section Corner to Sections 3 & 4.
Set Lot Marker:
Found - Orig. 30" Fir N.43°21'E. 138 lks.
12" Fir by Cole, down, S. 6°57'W. 12.0 ft. - REN #11
Scribed: 12" B.Oak S.57°07'E. 8.7 ft. and 16" Fir N.34°13'W. 40.4 ft.

RE-RENEWED, SEE CORNER NO. #156

James W. Byron, Deputy County Surveyor
M. Godfrey
S. Blouw
June 20, 1958
C. S. File No. 49/59

Eppstein - Bowker
For J.O. Craie
Oct. 14, 1926
C.S. File # 3/60

Wilford N. Haines
For Harold Woolley
February 1959
Rolled Map # R/ - 29

54A