

Douglas County Surveyor's Record of
Government Corners Renewed

22 T. S. 5 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

James W. Byron, Deputy County Surveyor

Milo Godfrey

S. A. Bilow

April 13, 1959

C. S. File No. 49/143

Section Corner to Sections 18 & 19, T22S R5W, & Secs. 13 & 24, T22S R6W. **55**
Found - Orig. 18", now 22" Partly Rotted Oak Stump N.15°E. 150.5 ft.
I open near base & find good scribing "BT".
Orig. 24", now 30" Partly Rotted Oak Snag N.48°W. 115.5 ft.,
I open near base & find good scribing "BT".
30" Down Oak checks bearing & distance for Original SE BT.
No trace of Original SW. BT.

*Fd. OK 12/91
C. GUILLE
1992-0079 A/B*

*Fd. OK by
S.A. SHANER
8/81
M 90-2*

Set Brass Cap at Corner Mkd: County Surveyor's Office, 1959

S13	S18
S24	S19

 T22S R6W R5W

New BT's: 9" Double W.Oak bears N.28°E. 12.0 ft. scribed S18 T22S R5W CS BT.
9" W.Oak bears S.57°E. 7.9 ft. scribed S19 T22S R5W CS BT.
22" R.Fir bears N.25½°W. 19.4' scribed S13 CS BT.
Note - This BT. scribed on one face & scribed high, above fence.
10" W.Oak bears S.25°W. 32.0 ft. scribed S24 T22S R6W CS BT

Note - I find ¾" Iron Rod thus:



Section Corner to Secs. 19 & 30 T22S R5W, & Secs. 24 & 25 T22S R6W. **56**
Found - Orig. 14", now 30" W. Oak S.60°W. 66 ft., shows good scars,
I do not open.

*Fnd. O.K.
6/81 E. Bloom
M 79-79*

*6/22/92
J. BEAUCH
M 116-29, CS 63/149*

*Fd OK
2/8/60
E. Bloom
M 100-25*

Orig. 10", now 20", B. Oak Snag N.4½°W. 47.5 ft., I open & find good scribing "BT".
Orig. 20", now 44" W. Oak N.89°E. 47.5 ft., shows good scars, I do not open.
Orig. 20", now 26" W. Oak, previously opened, shows good scribing "S30" S.74°E. 32.3 ft.
Find Scribed Stake at Corner.

Set Brass Cap at Corner Mkd: County Surveyor's Office, 1959

S24	S19
S25	S30

 T22S R6W R5W

New BT's: 8" W. Oak bears N.37°W. 8.7 ft. scribed S24 T22S R6W CS BT.
12" R.Fir bears S.57°E. 55.7 ft. scribed S30 T22S R5W CS BT.

Section Corner to Secs. 1 & 12, T22S R5W, & Secs. 6 & 7, T22S R4W. **57**
Bound - Scribed Stake & 1" Axle at Corner. - *REN # 81 (GADDER REN. RECORDED AT A LATER DATE)*

Orig. 20", now 40", down & partly rotted, previously opened, shows good scribing " " S.18°E. 44.9 ft.
Orig. 35", now 44" Shell of Rotted Fir S.68°W. 35.0 ft., shows old scars.
Orig. 20", now 40", down & partly rotted Fir N.68°W. 42.2 ft., shows old scars, no scribing left.
Orig. 30", now Stump Hole, only, N.70°E. 33.7 ft.

Set Brass Cap at Corner Mkd: County Surveyor's Office, 1959

S 1	S 6	T22S
S12	S 7	R4W

This Corner renewed several years ago, but not recorded.
I use same BT's. in N. E. & S. E. I destroy scribing on BT's. to N. W. & S. W.

New BT's: 20" Cedar bears N.16°E. 46.8 ft. scribed Tp22S R4W S6 BT. (I add CS.)
18" Chinquipin bears S.30°E. 14.8 ft. scribed Tp22S R4W S7 BT (I add CS.)
6" R. Fir bears N.64°W. 13.0 ft. scribed T22S R5W S1 CS BT.
6" Hemlock bears S.77°W. 30.8 ft. scribed T22S R5W S12 CS BT.

James W. Byron, Deputy

S. A. Bilow

April 22, 1959

C. S. File No. 49/59

Section Corner to Secs. 24 & 25, T22S R5W, & Secs. 19 & 30, T22S R4W. **58**
Found - Orig. 10", now 28" Fir Stump. I open & find good scribing, "S", N.52°W. 21.8 ft. I find no trace of other Orig. BT's.

This Corner was renewed years ago by Theil, not recorded.
Theil set 5"x 6"x 15" Stone with + on top at Corner & bark scribed Orig. N.W. BT. "24".
Theil also scribed B. Oak bears S.16°W. 27.7 ft.
Note - Corner is under E. W. Fence.

*SEE COB. # 78
FOR NEW BT.*

Set Brass Cap at Corner & Alongside Corner Stone, Mark Cap:
County Surveyor's Office, 1959

S24	S19
S25	S30

 R5W R4W T22S (continued over)