

Douglas County Surveyor's Record of
Government Corners Renewed

22 T. S. 5 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

(continued)

James W. Byron, Deputy
S. A. Bilow
April 22, 1959
C. S. File No. 49/59

New BT's: 5" R. Fir bears N.25°W. 31.0 ft. scribed S24 T22S R5W CS BT.
8" R. Fir bears N.20°E. 49.5 ft. scribed S19 T22S R4W CS BT.
10" B. Oak bears S.16°W. 27.7 ft., Theil's BT., partly
grown over, I add scribe CS. *See Cor. #98 for New BT.*
6" R. Fir bears S.30°E. 26.1 ft. scribed S30 CS BT.

*DOWN
JULY 22, 1963
M.E.G.*

59

Section Corner to Secs. 25 & 36, T22S R5W, & Secs. 30 & 31, T22S R4W.
Found - Orig. 36", now 44" Fir N.52°W. 27.1 ft., shows good bark
scribe near base "BT".
Orig. 30", now 40" Fir Stump S.16°W. 30.4 ft. I open
& find good scribe "6".
Orig. 24", now 30" Stump, shows good scar, I do not open,
S.37°E. 26.0 ft., record S.37°E. 21.8 ft.
No trace of Orig. N. E. BT.

*FD 12/183
M 95-74
L Smith*

Set Brass Cap at Corner Mkd: County Surveyor's Office, 1959

S25	S30	
R5W	S36	S31 R4W T22S

New BT's: 62" R. Fir bears N.15°E. 130.0 ft. scribed S30 T22S R4W CS BT.
12" Cedar bears S.13½°E. 92.0 ft. scribed S31 T22S R4W CS BT.
6" R. Fir bears S.78°W. 39.2 ft. scribed S36 CS BT.

*FND. OK 2/92 BY PEEL 60
M 114-60*

Renewed Corner

S36	S31	T21S
S1	S6	T22 S

R6W R5W

Found - Orig. 20", now 40" W. Oak S. 7½°E. 95.7 ft., shows good
scar, I do not open.

Orig. 24", now 40" Oak Stump S.13°W. 138.6 ft., I open
near base & find good scribe marks "D 1".

Also find Stone with + on top at Corner Set by Haines, 1943.

RE-RENEWED CORNER NO. 197

*SEE REN.
#1 T.22-6*

New BT's: 10" R. Fir bears S.21°E. 31.0 ft. scribed S 6 T22S R5W CS BT.
8" R. Fir bears N.72°E. 56.0 ft. scribed S31 T21S R5W CS BT.
10" B. Oak bears S.28°W. 18.8 ft. scribed S 1 T22S R6W CS BT.
8" W. Oak bears N. 2°W. 10.0 ft. scribed S36 T21S R6W CS BT.

61

¼ Section Corner to Sec. 7, T22S. R5W., & Sec. 12, T22S R6W.
Found - ¾" Iron Pipe at Corner.

Orig. 20", now 48" Fir Stump S.83°W. 14.5 ft. This BT.
windblown & Stump section now downhill about 50', shows
good old scars. Now in such position I cannot open.
W. Haines states this BT. showed good scribe marks
several years ago.

Also find remains of Laurel that may have been Original

S. E. BT.

New BT's: 12" Maple bears S.83°E. 46.0 ft. scribed ¼ S 7 CS BT.
72" R. Fir bears S. 3°E., scribed in wood "BT", scribed
in bark "¼ S7".

RE-RENEWED

#73

James W. Byron, Deputy
Milo Godfrey & S. A. Bilow
Done for W. E. Clevenger
June 19, 1959
C. S. File No. 49/158 - 18
Map File M 15 - 18

62

Renew Section Corner

S12	S 7	T22S
R6W	S13	S18 R5W

Found - Orig. 24", now 48" Partly Rotted Fir Stump, I open & find
good scribing, "BT", N.69½°E. 72.6 ft.

Rotted Fir Stump that checks bearing & dist. for Original
S. W. BT., no scribing found.

No trace of Orig. S. E. Or N.W. BT's. Found.

Set Brass Cap at Corner Marked

S12	S 7	T22S
R6W	S13	S18 R5W

County Surveyor's Office, 1959

New BT's: 14" R. Fir bears S.16°E. 22.1 ft. scribed S18 T22S R5W CS BT.
10" R. Fir bears S79°W. 16.0 ft. scribed S13 T22S R6W CS BT.
12" R. Fir bears N.35°E. 15.7 ft. scribed S 7 T22S R5W CS BT.
12" R. Fir bears N.42°W. 20.8 ft. scribed S12 T22S R6W CS BT.

Note - I find Stake Marked approximate Sec. Cor. bears N.42°W. 30.0 ft.
from Sec. Cor. *See Sketch in File.*

*FD OK 6/16/64
W. Haines
C.S. 58/124*