

Douglas County Surveyor's Record of
Government Corners Renewed

T. 22 S. T. S. R. 5 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

Milo E. Godfrey
V. Tracy &
M. Stone
July 5, 1962
C.S. File
No. 49/59

$\frac{1}{4}$ Corner to Sections 35 and 36.
Found - Badly rotted Oak S.87 $\frac{1}{2}$ °E. 42.2 ft. Stump hole clearly defined. Found good reverse scribing "BT".
Badly rotted Oak S.33°W. 31.0 ft. Down, but stump hole clearly defined. Open & find good scribing "S".
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1962
T22S R5W $\frac{1}{4}$ S35/S36
New BT's: 12" D. Fir S.18°W. 8.4 ft. Mkd: $\frac{1}{4}$ S35 CS BT.
7" D. Fir N.88°E. 24.0 ft. Mkd: $\frac{1}{4}$ S36 CS BT. (all in one blaze)
Fence Corner - Fences E. & S. - bears S.85°E. 36.3 ft.

#191
FD. 8/90
C.S. 63/126

RE-RENEWED, SEE CORNER NO.

Wilford N.
Haines.
Oct. 1962
M 24 - 23

$\frac{1}{4}$ Corner to Sections 17 and 18.
Found - 1 $\frac{1}{2}$ " Iron Pipe as shown on survey by Irving, May 1946.
(See C. S. File 52/131) not previously posted.
Pipe has been covered by a rock fill.
Original Ash BT. S.35°E. 57 lks. has been rescribed
Set - Iron Rod $\frac{3}{4}$ " diam. x 3 ft. long for $\frac{1}{4}$ S18/S17 T22S R5W.

124
F.O.K.
Feb. 1965
S.C.R.

RE-RENEWED, SEE CORNER NO.

W. Haines
M 24 - 23

S. W. Corner Of W. N. Goodell D. L. C. No. 40.
1 $\frac{1}{2}$ " Iron Pipe knocked down by farming operations.
Set - 1" x 1" x 36" T. Iron

RE-RENEWED, SEE CORNER NO.

Milo E. Godfrey
May 15, 1963
C. S. File
No. 49/59

$\frac{1}{4}$ Corner to Sections 23 and 26.
Found - 1 $\frac{1}{2}$ " Reinfrng. Rod stamped $\frac{1}{4}$ S23 26 on top. - REN # 28
36" Fir Stump S.42°W. 30.0 ft. (record 29.0 ft) Sliver extending up from near center of stump shows old scribing "S", at approximately 4" diam.
Fir Slab, only portion of large down fir remaining standing, N.2°E. 52.0 ft. No marks found. Tree probably bark scribed & bark has been burned & is flaking off badly.

DID NOT SET A BRASS CAP

New BT's: 11" D. Fir N.30°W. 21.5 ft. Mkd: $\frac{1}{4}$ S23 CS BT.
21" D. Fir S. 3°E. 89.5 ft. Mkd: $\frac{1}{4}$ S26 CS BT.

Section Corner to Secs. 24 and 25, T22-5W. & Secs. 19 & 30, T22-4W.
Found - County Surveyor's Brass Cap & Thiel's Rock at Corner. Ren. No. 58
5" D. Fir N.25°W. 31.0 ft. Alive and in good condition.
8" D. Fir N.20°E. 49.5 ft. " " " " " "
6" D. Fir S.30°E. 26.1 ft. " " " " " "
The S. W. BT. is now down.
New BT: 7" D. Fir S. 6 $\frac{1}{2}$ °W. 41.0 ft. Mkd: T22S R5W S25 CS BT.

$\frac{1}{4}$ Section Corner to Secs. 25, T22-5W. & Section 30, T22-4W.
Found - 40" Fir Stump N.53°W. 19.8 ft. Opened by Haines, scribing "4S" visible on old face.

Remains of Laurel Stump with Laurel Sprouts growing out of it, S.67°E. 25.1 ft. Not enough of stump left to find scars or scrhg.

Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1963
T22S R5W $\frac{1}{4}$ S25/S30 R4W

New BT's: 18" D. Fir S.32°E. 37.0 ft. Mkd: $\frac{1}{4}$ S30 CS BT.
10" D. Fir N.45°W. 51.3 ft. Mkd: $\frac{1}{4}$ S25 CS BT.

Note - A fence line running approximately N. and S. bears West 65.0 feet.

N. W. Corner Jesse Applegate D.L.C. No. 38.
Found - Old BT., N.5°W. 47.5 ft. - See Ren. No. 18 M 16 - 67
16" Fir N.44 $\frac{1}{2}$ °W. 35.5 ft.
24" Fir S. 61°W. 28.0 ft.

RE-RENEWED, SEE CORNER NO. #161
Rock as mentioned in Ren. No. 18, is gone.
Set - 1" x 1" x 36" T. Iron flush with ground.

Wilford N. Haines
For Woolley Log.
Dec. 1963
Map File M 27 - 17

December 1963

Milo E. Godfrey, Deputy County Surveyor
Vernon Tracy and Mike Stone
July 1963
C. S. File No. 49/59