

Douglas County Surveyor's Record of
Government Corners Renewed

T. 22 S. T. S. R. 5 W. R.W.W.M.

ROKE-CHAPMAN CO., EUGENE, ORG., 91891

B.H. McGillicuddy, Corner to Sections 15 and 16. **SEE CORNER NO. 107** -- 90
For Whipple. Post, Iron Pipe Original
RM 1 - 40 Fir 10" S.80°E. 33 lks., now stump. 36" Fir S.48°W. 57 lks., now 50".

1/4 Corner to Sections 26 and 35. -- 91
Found - 20" Fir N.30°W. 200 lks., now stump, lower 2/3 of "S" plain.
48" Fir S.5° E. 191 lks., now rotted & burned stub, no scrib.
Note - 1/2" Iron Pipe N.76°30'E. 19.5 ft. (See C. S. File No. 42/179)
Set - 1" x 1" x 36" T. Iron and Scribed:
30" D. Fir S.48°W. 19.5 ft.
10" D. Fir N.38°E. 11.2 ft. (This tree also scribed 1948 (approx.)
on East Side.)

Section Corner to Secs. 25 - 26 - 35 - 36. *From BLM BC 10/92* -- 92
Found - 3 Original Bearing Trees. *K. Hoffman M116-2*
Set - 1" x 1" x 36" T. Iron.

Center 1/4 for Section 26. -- 93
Set - 1" x 1" x 36" T. Iron and Scribed :
18" D. Fir N.25°E. 67.2 feet
8" D. Fir S.34°E. 40.0 feet.

1/4 Corner to Sections 26 and 25. -- 94
Found - 20" Fir N.22°E. 85 lks., now 48", good scribe.
Set - 1" x 1" x 36" T. Iron for Corner.

Section Corner to Sections 23 - 24 - 25 - 26. -- 95
Found - Stumps of 3 Original Bearing Trees.
Set - 1" x 1" x 36" T. Iron for Section Corner.

TOWNSHIP CORNER
T21S
R5W S 36 | S 31 R6W
S 1 | S 6
T22S

Found - 40" Fir (burned stub) S.11°30'W. 200 links. *SEE ALSO T21S Book 5 Pg 18*
Orig. S.14°W., old scribed post. BT's destroyed.
Set - 3" I. Pipe & Scribed New BT's; **SEE CORNER NO. #131**
24" Fir N.42°30'E. 26.4 ft. Mkd: T21S R4W S31 BT.
28" Fir N. 9°30'W. 51.7 ft. Mkd: T21S R5W S36 BT.
28" Fir S.21°10'W. 60.7 ft. Mkd: T22S R5W S 1 BT.
26" Fir S.25°30'E. 5.0 ft. Mkd: T22S R4W S 6 BT.
Corner set by McGillicuddy, 1953. Found Pipe & 4 BT's. in good condition
Oct. 1964 by M.E. Godfrey. See C. S. File No. 49/68

Sec. Corner to Secs. 3 & 4, T22-5W. & Secs. 33 & 34, T21-5W. -- 97
Found - 1" Alum. Pipe set by Calder, 1960. (See Ren. #70)
Stump of 24" D. Fir N.40°W. 104.0 ft., scribing still visible, "BT".
Rotten Fir Stump S.15°E. 169.0 ft., No marks visible, Orig. BT.
Stump of 8" Alder S.30°E. 244.7 ft. (faces visible but scribing
rotted away)
Stump of 4" I. Cedar S.37°E. 36.8 ft. (Calder's BT).
8" D. Fir S.70°E. 82.2 ft., blaze & scribe, "T22S R5W S3 CS BT"
8" D. Fir S.78°W. 44.2 ft., blaze & scribe, "T22S R5W S4 CS BT."
New BT's: 8" D. Fir N.86°E. 57.2 ft. Mkd: T21S R5W S34 CS BT.
8" D. Fir N.54°W. 34.6 ft. Mkd: T21S R5W S33 CS BT.
Alum. Pipe extends approx. 12" above ground. DID NOT SET BRASS CAP.
Nov. 30, 1964

Wilford N. Haines
For Woolley Logging Co., Drain, Ore.
April, 1964.
Map File M 27 - 65

B. H.
McGillicuddy
July 1953
See Map in
C. S.
File
No. 41/182

Milo E. Godfrey, Deputy
Wm. Stoffel & Mike Stone
November 1964
C. S. File No. 49/68

FO ok
10/88
D. Wellman
M107-26