

Douglas County Surveyor's Record of  
Government Corners Renewed

T. 22 S. T. S. R. 5 W. R. W. W. M.

ROKE-CHAPMAN CO., EUGENE, ORE. 21881

Wilford N. Haines  
For James Lhaman  
August, 1967  
C.S. M. 34 - 44

Interior Angle Corner D. L. C. No. 38.  
Found - 30" Oak, down, S. 89° E. 583 lks.  
Set - 5/8" x 36" Steel Rod, from which:  
Scribed - 8" Oak, one of clump of three, N. 39° E. 120.7 ft.  
10" Maple N. 79° E. 91.0 ft.

119

South - S.W. Corner Claim (D.L.C. No. 43).  
Found - Stone Post - unrecorded.  
A plow share in a buried mound of stones.  
Set - Drove a steel Fence Post by Stone Post.  
Note - Fence is about 3 ft. west.

120

S. E. Corner D. L. C. No. 43.  
Found - 24" Fir, now 48" Stump, S. 68° W. 32 lks.  
Set - 5/8" Steel Rod, from which:  
Scribed - 9" Fir S. 62° W. 8.4 ft.  
12" Fir N. 31° W. 8.8 ft.

121

MICROFILM TO HERE 10/67

Center 1/4 Corner for Section 35.  
Set - 5/8" Steel Rod for Center of Section.  
No Bearing Trees.

122

Wilford N.  
Haines  
M 35 - 10

December, 1967

S. W. Corner of D. L. C. No. 40.  
Found - 2" Iron Pipe, See Ren. #27-76  
"T" Iron gone.  
Drove 5/8" x 60" Steel Rod in center of Pipe.

123

Wilford N.  
Haines  
M 35 - 16

FD-2 "PIPE - J. Dix  
713-84 O.S.H.D.  
C.S. 63/9  
FD OK 12/92  
BY HOFFMAN  
1993-49

Dec. 30, 1967

SEPT. '68

1/4 Corner to Sections 17 and 18.  
Found - 3/4" Iron Rod at 1/4 Corner, See Ren. #75.  
Orig. Ash, now 25", S.35°E. 32.6 ft., some scribe marks visible.  
Mkd. Bearing Objects:  
2" Cross (+) on S.W. corner of Concrete Slab for diesel Pump S. 37.50 ft  
2" Cross (+) on S.W. corner of concrete Slab for Transformers,  
N.81°E. 63.30 ft.

124

John M.  
Powell &  
Crew  
C.S. File  
No. 53/101

This corner falls in gravel area approx. 70.0 ft. North of road and south of log pond. SEE HAINES' SKETCH C.S. 55/216

FD OK 7/94 M 120-47

11/12/70

Std Sect. Cor. to Sec. 31, T22S R4W, & Sec. 6 T23S R4W & Sec. 1, T23S R5W  
Found - Orig. 14" now 34" W. Oak N.80°W. 1091.0 ft. Theil rescribed this BT. years ago. I open back of his scribing & find orig. scribing "WR"  
Also find 2" Iron Pipe at corner. Turpin says Theil set this pipe for cor.  
Closing Corner 4.59 ch. West, not found.  
New BT: 26" Maple bears N.80 1/2°W. 475.0 ft. scribed S36 T22S R5W CSBT.  
No other trees near.  
3/4" Iron Rod with 4" x 4" White Post bears S.55°E. 88.2 ft.,  
Post marked SHRW L PT 722+72.44 Jan. 25, 1960  
Fd. OK Dec. 1964 CS 53/101

125

James W. Byron Deputy Co.  
Surveyor  
M. Godfrey-C. Putnam  
C.S. File No. 49/42

North 1/4 Corner Section 6. (T. 23 - 5)  
Found - Both Original Bearing Trees:  
Orig. 16" now 34" B. O. S.89 1/4°E. 387.2 ft. This BT. rescribed about 25 years ago, I open back of this face & find good scribing on Original face.  
Orig. 36" Fir now 40" rotted stump S.22 3/4°E 708.4 ft., good scribing visible on section of old face.  
Set Brass Cap Marked: County Surveyor's Office, 1958 N. 1/4 S6 T23S R5W  
New Bearing Tree: 3" W. O. Bears S.65°E. 49.2 ft. scribed 1/4 S6 CS BT.  
No other trees near.  
Found OK Feb. 1965 -B.B.R

126

James W. Byron Deputy Co.  
Surveyor  
M. Godfrey  
S. Bilow  
March 4, 1958  
C. S. File No. 49/59