

Douglas County Surveyor's Record of
Government Corners Renewed

T. 22 T. S. R. 5 R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

166

Center 1/4 corner for Sec. 29.

Set - 5/8" x 30" rebar.

BT's - 10" D. Fir bears N.51°W., 13.8-ft., scribed C 1/4 S29 BT .
8 1/2 " D. Fir bears S.22°E., 7.5-ft., scribed the same.

(NOT FOUND 5/15/89 L. ROBERTS C.S. 43/91 M. 108-23) - 6/81

167

1/4 corner common to Sec. 19 and Sec. 24 of T.22-6.

Found - 26" W. Oak (orig. BT), well defined old face, partially covered with new growth of proper age, no scribes visible, bears S.74°W., 15.2-ft. See M 90 - 2 for additional notes.

Set - Brass Cap marked "T22S R6W R5W, WM 1/4 S24 S19 RLS 430, 1981" from which, the above BT bears.

New BT's-28" W. Oak, I scribed "1/4 S 19 BT", bears S.79°E., 26.3-ft.

6" D. Fir, I scribed "1/4 S 24 BT", bears N.67°W., 26.5-ft.

Note - 24" W. Oak (orig. BT) that was N.57°E., 81.2-ft. is now gone.

8/81

168

1/4 corner common to Sec. 8 and 9.

Found - 1" I. Pipe with Brass Cap stamped: County Surveyors Office T22S R5W 1/4 S8|S9 1957. Cap is found badly bent and laying flush with ground. Ren.# 30.

note- As indicated in Ren.#'s 19 & 30, this monument set with original BT at S30°E. (Rec. S35°E.). We are unable to find any information to clarify this discrepancy. We agree with position of the true corner determined by Robert Dean...C.S. File 58/207, from which the monument set by Byron Ren.#30 bears N.43°E., 2.93-ft.

BT's- 48" W. Oak (orig. 8") with open face scribing BT visible, bears S.35°E., 25.7-ft.

16" R. Fir (orig. 6") with faint double blaze, bears N.55 1/4 °E., 158.0-ft. (Rec. N.56°E., 156.1-ft. from Ren.# 30 position).

Orig. 48" Fir BT not found.

Chinquapin from Ren.#19 not found.

Set - At true corner, we set a 1" x 30" I. Pipe with Brass Cap attached, stamped: Douglas County Surveyor T22S 1/4 S8|S9 1981 R5W We obliterate marking on cap set by Byron in Ren.#30.

New BT's-We blaze an X in bark of the aforementioned 16" R. Fir.

9" Fir, scribed 1/4 S8 CS BT in double blaze, bears S.9 1/2 °W., 100.9-ft.

16" Fir, scribed 1/4 S8 CS BT in double blaze, bears S.40 1/2 °W., 202.7-ft.

9/24/81

169

1/4 Corner common to Secs. 25 & 36.

(Reference notes C.S. 59/30 now attached to this renewal.)

Found - 5/8" x 40" I.R. in North edge of Rd., buried by small Ren. #164. a small slide. (1/4 Cor.)

1973 BLM B.C. Reset by Haines as witness corner in Ren. #164, bears N.60°E., 17.0-ft. from I.R. 1/4 Cor., with Haines added marks: "WT ← 17FT"

5/8" x 40" I.R. set by Haines bears N.46°W., 12.0-ft. Ref. notes. from the 5/8" I.R. 1/4 Cor.

BTs - These found BTs. bear from 5/8" I.R. 1/4 Cor.:

34" Cedar bears N.46°W., 34.3-ft. (Rec. N.42°W.), Ren. #164. alive with good scar & nail.

54" Fir, now stump buried by road const. bears Resurvey. S.56°E., 52.1-ft. (Rec. S.57 1/2 °E.).

26" Fir, now 18", & alive with scribed "1/4 S25 239 BT" visible in unhealed blaze, bears N.60°E., 38.0-ft.

Set - At the exact location of 5/8" x 40" I.R. in road shoulder, I set a 1" x 22" I.P. with Brass Cap stamped: Douglas Co Surveyor T22S 1/4 S25 S36 R5W 1981". I put metal fence post with a survey marker sign 1.0-ft. North of Cor.

New BTs - 13" Fir scribed "1/4 S25 CS BT" in dbl.blaze bears N.55°W., 13.7-ft.

17" Fir scribed "1/4 S25 CS BT" in dbl.blaze bears N.84°E., 61.1-ft.

This same 17" Fir bears S.87°E., 46.8-ft. from the 1973 BLM B.C.. which is now a Wit. Cor.

Note - See C.S. file 61/29 for sketch & Ref. notes.

12/1/81

Eugene Bloom
For: Feather Hill
Farm

June 1981

M 79 - 79

C.S. 58 / 217

Bruce A. Shaner
RLS 430

For: Eagles View
Management Co.

August, 1981

M 90 - 2

Larry E. Monrean
Deputy Douglas Cou.

Surveyors Office
Terrie Plouff,

notekeeper

Sept. 24, 1981

C.S. 61/27

Gregory E. Quibell

Deputy Douglas Co.

Surveyors Office

Teresa Buley, witness

December 1, 1981

C.S. 61/29