

**Douglas County Surveyor's Record of
Government Corners Renewed**

T 22 T. S. R 5 R. W. W. M.

KONE-CHAPMAN CO. - EUGENE, ORE. 21881

177

C O N T -- --
Doug. Co. Surveyors
Office R. Smith and
S. Flause Jan. 25, 1988
C.S. 62/50

(WC 1/4 Cor. Sec. 24; and 19 of T22-4)
New BTs - A 21" D.B.H. W. fir scribed "WC 1/4 S19 CS BT" on a double blaze
bears N.36°E., 9.5 ft. distant.
A 14" DBH D. fir scribed "WC 1/4 S19 CS BT" on a double blaze
bears S.75½°E., 27.8 ft. distant.
Monument is located on high south bank of Elk Creek at Boswell Co. Rd. #54
bridge approx. 80 ft. west from the road centerline.

1/25/88

1/4 Corner for Sections 13 and 24

178

Found - A 5/8" iron rod with "+" on top protruding 1 inch above
ground. Ren. #146
6" now 47" dia. R. cedar with a possible fully healed single
blaze, bears N.45°E., 23.1 ft. Agrees with record. (Orig. BT)
Original southwest BT not found.
Original Elk Creek call checked and position agrees well with
original record. (West, 80.5 ft.)
Set - A 2 3/8" brass cap on a 1½" outside dia. x 31" I.P. that protrudes
6" above ground. Cap mkd. "Douglas County Surveyors T22S 1/4
S 13 S 24 R5W 1988"
5/8" I.R. per Ren. No. 146 referenced and BC/IP set in its place.
5/8" x 40" I.R. is set along north side of BC/IP protruding
4" above ground.
New BTs - 17" alder bark scribed "1/4 S24 CS BT" bears S.34°W., 26.0 ft.
11" hardwood tree double blazed and scribed "1/4 S24 CS BT" bears
S.46½°E., 5.9 ft.
13" Ash double blazed and scribed "1/4 S24 CS BT" bears S.82¼°E.,
24.0 ft.

Corner lies near an east-west fence line and Elk Creek on east side of creek.
Jan. 20, 1988

179

Section Corner for Secs. 15, 16, 21 and 22

Set - 2" x 42" iron pipe with brass cap mkd. T22S R5W S16 | S15 PLS 752
S21 | S22
1988

New BTs- 10" Oak, East, 63.3 ft. scribed "T22S R5W S15 BT"
13" Fir, S.12 3/4°E., 240.3 ft. scribed "T22S R5W S22 BT"
15" maple, S.13¼°W., 218.2 ft. scribed "T22S R5W S21 BT"
12" Oak, N.27½°W., 89.4 ft. scribed "T22S R5W S16 BT"

180

1/4 Corner for Sections 15 and 22

Set - 2" x 42" iron pipe with brass cap mkd. "T22S R5W 1/4 S15 S22 PLS752
1988".
New BTs- 25" Fir, N.27°E., 74.8 ft. scribed "1/4 S15 BT"
34" Oak, S.83°E., 142.1 ft. scribed "1/4 S22 BT"
Note: Distances are center measure, bearing solar.

Donald Peel
L.S. #752
For: Weyerhaeuser
Company
Jan. 1988
M 105 - 54

1/4 Corner for Sections 10 and 15

181

Found - 1" iron pipe, Ren. #87
16" Fir, N.34°E., 23.9 ft. (closed face).
BT at S.12°W., now blown down.
New BT - 19" Fir S.44½°E., 44.6 ft. scribed "1/4 S15 BT".

RE-RENEWED CORNER NO. 194

182

Center 1/4 Corner for Section 15

Set - 2" x 42" iron pipe with brass cap mkd. "T22S R5W C1/4+ S15
PLS 752 1988".
New BTs -23" Fir, N.21°E., 51.0 ft. scribed C 1/4 S15 BT"
25" Fir, N.54°W., 37.9 ft. scribed C1/4 S15 BT".

Section corner for Sections 10, 11, 14 and 15.

183

CORNER REPORT ONLY

Found - 1½" iron pipe with brass cap. Ren. #138
33" Fir N.72½°E., 60.8 ft. (closed face.) NO RECORD
36" Fir stump, S.27¼°E., 50.8 ft.
32" Fir, S.27½°W., 42.7 ft. (closed face) (See also #s40 & 84)
38" Fir stump, N.7°W., 3.8 ft.
30" Fir, N.26°E., 25.5 ft. (Closed face)