

Douglas County Surveyor's Record of  
Government Corners Renewed

22 T. S. 6 R. W. W. M.

Ben R. Irvins, Deputy County Surveyor  
April 16, 19, 1928  
R. L. Irvins  
Jess Widdy  
Witnesses

C. S. File 22/23  
Vol. 3, P. 224  
C. S. 2/49

1/4 SEC. COR. BETWEEN SEC. 10 & 15  
Position determined by proportional measurements between  
Sec. corners. Set 1/2" x 48" pipe driven 48" in the ground  
for corner. from which  
12" Ash on west bank of Jack creek, bears East 152.8  
lks. dist., scribed 1/4 S. P.T.  
16" Locust, bears N. 88° 10' W., East 5 lks. dist.,  
scribed 1/4 S. P.T.  
X 1/4 chisled on top of N. wing wall on old bridge  
Abutment S. 43° 55' E. 230 lks.

RE-RENEWED, SEE CORNER NO. 26

16

WITNESS CORNER TO 1/4 SEC. COR. 15-16  
True corner falls in Elk Creek. Set boulder 6" x 8" x 12"  
marked with X and 1/2" x 24" pipe driven alongside for witness  
corner. from which  
Scribed 18" Fir, S. 24° 45' E., 60 lks. dist. W.C. 1/4 S. 15.,  
C.S. B.T.  
36" Fir., S. 78° 15' W., 216 lks. N.A., 1/4 S. 15. P.T.  
This W.C. is 156 lks., 30° 22' E. of true corner and on the  
West line of Sec. 15.

RE-RENEWED, SEE CORNER NO. 94

17

SEC. CORNER BETWEEN SECS. 12 & 13  
Identified by a 4" Cedar post as set by Surveyor Thiel and  
the O.P.T. a 36" leaning Fir N. 14° E. 33 lks. I did not chop  
out this P.T. as there was no room as to its being the O.P.T.  
Remarked this tree in bark 1/4 S. 15. C.S. B.T. Also marked a 16" W.  
W. Oak for a B.T. South 94.8 ft. 1/4 S. 15 C.S. B.T.

Book 2 Pg 28

RE-RENEWED, SEE CORNER NO. 47

18

SEC. CORNER BETWEEN SECS. 13 & 14  
Identified by a plain sandstone rock set by Thiel and on  
O.P.T. a 32" B. Oak. This Oak had been chopped out and  
John Clayton the owner of adjoining property testified that  
when Thiel chopped out the tree scribe marks were visible.  
Fir bearing tree gone but found old stump burned off level  
with ground which checked both bearing and distances.  
Chisled the rock 6" x 10" 15" with a X and 1/4. Scribed new B.T.  
A 15" Fir, N. 81° E. 55° ft., 1/4 S. 13 C.S. B.T.  
A 30" Fir, S. 60° 12' W. 266 ft., 1/4 S. 14 C.S. B.T.

RE-RENEWED, SEE CORNER NO. 73

19

SEC. COR. BETWEEN SECS. 13 & 24  
I identified the location of this corner by the remains of an  
O.P.T. now a rotted snag. 8' high x marks B.T. reverse  
visible where it had grown into original scribe marks.  
Drove a 2" x 36" pipe for this corner at proper location from  
this tree. Surrounded pipe with a mound of stone. Scribed  
new B.T.'s  
A 15" Fir, N. 47° 30' W. 92.8 ft. 1/4 S. 13 C.S. B.T.  
A 20" Fir, S. 16° E. 145.9 ft. 1/4 S. 24 C.S. B.T.

RE-RENEWED, SEE CORNER NO. 46

20

S.W. COR. THOS. STILLWELL D.E.C. #45  
I identified this corner by a Fir post set by Surveyor Thiel  
also on original O.P.T. S. 10° W. 15 lks. Scribe marks visible  
in the bark. A snag bears S. 15° E. 30 lks. This snag has  
been so badly burned that all marks are obliterated. It  
appears from location however to be the other O.P.T. Set  
a 3" x 36" pipe 30" in the ground for the corner. Remarked  
O.P.T. S. 10° W. 15 lks. Also a 30" Fir N. 19° E. 5 lks. which  
had been previously marked by someone unknown. (Thiel - Sec C.S. 64/48  
Pg 14) D.C.S.O. 11/20/23

RE-RENEWED, SEE CORNER NO. 45

21

Ben R. Irvins, Deputy County Surveyor  
Jan. 1928  
W. S. Crear  
Geo. Montgomery  
Witnesses

C. S. File 2/49  
Vol. 3, P. 284  
Vol. 3, P. 285