

Douglas County Surveyor's Record of
Government Corners Renewed

22 T. S. 6 R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

72

$\frac{1}{4}$ Section Corner to Sections 8 and 9.
Found - $\frac{3}{4}$ " x 18" Iron Rod set by Eppstein, 1924. *-Ren.#8*
 $\frac{1}{2}$ " Iron Pipe alongside Iron Rod.
Rotted Remnant of Stump N.76°W. 18.2 ft.
Rotted Remnant of Stump N.61 $\frac{1}{2}$ °E. 17.0 ft. Both Stumps too far
tone to find any trace of scribing or axe marks.
Set Brass Cap Mkd: County Surveyor's Office, 1961 T22S R6W $\frac{1}{4}$ S8/S9.
New BT's: 6" D.Fir N.28°W. 50.8 ft. Mkd: $\frac{1}{4}$ S 8 CS BT.
6" B.Fir N.46°E. 96.0 ft. Mkd: $\frac{1}{4}$ S 9 CS BT.
Fence Corner, Fences West & South, bears West 23.5 ft.

73

$\frac{1}{4}$ Section Corner to Sections 14 and 13.
Found - Rock as called for in Irving's renewal of 1928. *-Ren.#19*
Fir Stump, now 28", N.81°E. 55 ft., showing good scars. Cut open
& found good scribing "S".
42" Fir Stump S.60 $\frac{1}{4}$ °W. 266 ft., no scribing or scars found.
Set Brass Cap at Corner Mkd: County Surveyor's Office, 1961
T22S R6W $\frac{1}{4}$ S14/S13. & place Mkd. Rock
alongside.
New BT's: 5" D.Fir N.20°E. 10.0 ft. Mkd: $\frac{1}{4}$ S13CS BT.
& 7" Madrone S.82 $\frac{1}{2}$ °W. 11.4 ft. Mkd: $\frac{1}{4}$ S14 CS BT.
Corner is in fence corner. Fences N. S. & E. from corner.

*Fd. 8/81
M.R. Dean
MOS-65*

74

$\frac{1}{4}$ Corner to Sections 28 and 27.
Found - Badly rotted fragments of Maple Stump with reverse scribing " $\frac{1}{4}$ S".
Set - Iron Pipe with Brass Cap N. 1°E. 23.1 ft. from Maple Stump,
Mkd: "County Surveyor's Office, 1961 T22S R6W $\frac{1}{4}$ S28/S27.
Found - 28" R. Cedar S.56°W. 20.0 ft. scribed " $\frac{1}{4}$ S BT S28 239".
(Scribing 5 to 10 years old.)
30" D. Fir N.26°E. 52.2 ft. scribed " $\frac{1}{4}$ S27 BT 239".
(Scribing 5 to 10 years old)

75

Section Corner to Sections 23 - 24 - 25 - 26.
Found - 1 $\frac{1}{2}$ " Bolt with Nut on Top. *Fd Bolt also M110-47*
Fir, now 38", N.30°W. 29.7 ft. with old bark scribing "S2 26 6"
Rescribe this tree in bark "T22S R6W S23 CS BT".
Fir, now 48", N.60°E. 23.8 ft., bark scribing visible,
"S24 T26S BT" (Old scribing)
Fir Stump, 32" diam, S.37°E. 25.7 ft., cut low, no scribing found.
Cedar Snag, 60", whole side facing corner burned off, no scribing.
New BT's: 8" W.Fir N.85°E. 12.3 ft. Mkd: T22S R6W S24 CS BT.
16" W.Fir S.38°E. 49.2 ft. Mkd: T22S R6W S25 CS BT.
8" D.Fir S.49°W. 40.0 ft. Mkd: T22S R6W CS BT. S26.
Note - Did Not Set Brass Cap.

76

Section Corner to Sections 22 - 23 - 27 - 26.
Found - Haines "T" Iron & cap. *(No Rec.)*
Fir Stump, now 20", N.22°W. 9.9 ft., uprooted & down. This
tree previously opened & scribing "22" & "6W" visible in
opened face. Later bark scribing also on stump.
Fir Tree, now 20", S.40°W. 1.3 ft., uprooted & down, shows
good scar. Did not chop open.
Remnants of Cedar Stump S.58°E. 35.6 ft. Too far gone to find
any markings.
Stump Hole N.48°E. 32.3 ft.
New BT's: 10" W.Fir N.55°W. 10.3 ft. Mkd: T22S R6W S22 CS BT.
10" W.Fir N.26°E. 25.4 ft. Mkd: T22S R6W S23 CS BT.
8" W.Fir S.41°W. 21.1 ft. Mkd: T22S R6W S27 CS BT.
No trees available in Section 26.

77

Section Corner to Sections 27 - 28 - 33 - 34.
Found - Maple Tree, now 20", S.72 $\frac{1}{2}$ °E. 12.5 ft. Tree hollow on back.
Reverse scribing visible thru opening "W S34 BT". No trace of other Orig.BT's.
Set - Brass Cap Mkd: County Surveyor's S28 | S27 T22S R6W
Office, 1961 S33 | S34
Found 3 Trees scribed within Past 10 years. (continued Over)

Milo E. Godfrey, Deputy County Surveyor
V. Tracy
C. Putnam
August 1-2, 1961
C. S. File No. 49/143