

Douglas County Surveyor's Record of
Government Corners Renewed

22 T. S. 6 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

(continued)

- 10" Hemlock S.62°W. 12.0 ft. scribing visible,
"S33 T22 R6W BT 239".
- 16" R.Cedar N.14°E. 13.0 ft. scribing visible "27 22
6 BT 39"
- 10" Hemlock N.62°E. 25.4 ft. scribing visible
"S27 T22S R6W BT 239".

 $\frac{1}{4}$ Section Corner to Sections 27 and 34. 78
 Found - Fir Tree, now 32", N.10°W. 5.9 ft. Has been opened
 previously, good scribing visible " $\frac{1}{4}$ S".

$\frac{1}{2}$ " Pipe at Corner.
 Fir Tree, now 20", S.82°E. 14.5 ft. Tree uprooted, down
 & dead. shows good scar. Did not chop open.
 Set Brass Cap Mkd: County Surveyor's Office $\frac{1}{4}$ S27 T22S R6W
 (alongside Iron Pipe) S34
 New BT's: 14" D.Fir S.42°E. 93.8 ft. Mkd: $\frac{1}{4}$ S34 CS BT.
 15" D.Fir N.60°W. 35.3 ft. Mkd: $\frac{1}{4}$ S27 CS BT.

FD. B. C. 6/92
 M 115-23
 J. BRANCH

 $\frac{1}{4}$ Section Corner to Sections 26 and 35. 79
 Found - Cedar Stump, now 20", South 4 ft. Opened & found good
 scribing " $\frac{1}{4}$ S".

Set - Brass Cap Mkd: County Surveyor's Office, 1961 T22S R6W $\frac{1}{4}$ S26
 S35
 New BT: 12" Maple S.70°W. 44.5 ft. Mkd: $\frac{1}{4}$ S35 CS BT.
 No other Live Trees near.

FD. B. C. 8/30
 M 110-91
 M 115-26

Milo E. Godfrey, Deputy County Surveyor
 V. Tracy, H. C.
 Clete Putnam, R. C.
 August 1961
 C. S. File No. 49/143

 Closing Corner to Sections 20 and 29. 80
 At Corner Found Haines "T" Iron & Cap. Also Fir Snag, now 34",
 N.70°W. 66.0 ft. Has been previously opened & good scribing "S20"
 visible. No trace found of S.W. BT.
 New BT's: 9" W.Fir N.63°W. 31.7 ft. Mkd: T22S R6W S20 CS CC BT.
 14" R.Cedar N.75 $\frac{1}{2}$ °E. 35.9 ft. Mkd: CC S20 S29 CS BT.

 West $\frac{1}{4}$ Corner to Section 28 only. 81
 Found - 24" Hemlock S.20°E. 22.4 ft., opened scar & fd. good
 scribing " $\frac{1}{4}$ S" (Orig. notes call for Fir)
 30" Cedar N.22°W. 26.4 ft., scar had been opened previously
 & face rotted away.
 Corner Stone not found, has obviously been destroyed by
 Logging, Pt. for Corner falls in Cat Road.
 Set - Brass Cap Mkd: County Surveyor's Office, 1961
 T 22S R6W W $\frac{1}{4}$ /S28 only.
 Reblazed & Rescribed Hemlock S.20°E. 22.4 ft. $\frac{1}{4}$ S28 CS BT.
 Blaze & Scribe 40" R.Cedar N.87°W. 54.1 ft. Mkd: W $\frac{1}{4}$ S28 CS BT.

 $\frac{1}{4}$ Section Corner to Sections 33 and 34. 82
 Found - Stone set by Nicklin with " $\frac{1}{4}$ " on West Face.
 R.Cedar, now 34", N.31°W., instead of S.31°W., 7.3 ft. to #133
 center of tree. Has been previously opened, scribing " $\frac{1}{4}$ S"
 plainly visible. ~~SEE CORNER NO~~
 Hemlock, down & dead, N.45°E. 10.6 ft. No scar or scribing fd.
 Alongside Rock Set Iron Pipe with Brass Cap Mkd: County Surveyor's
 Office, 1961 T22S R6W $\frac{1}{4}$ S33/S34.
 Blaze & Scribe: 8" W.Fir S.39°E. 12.5 ft. Mkd: $\frac{1}{4}$ S34 CS BT.

 $\frac{1}{4}$ Section Corner to Sections 28 and 33. 83
 Found - 22" Cedar S.50°W. 50.2 ft., shows good scars.
 48" Fir N.48°W. 42.2 ft., uprooted & down. Cut into scars
 & found good scribing "S".
 Set - Brass Cap Mkd: County Surveyor's Office, 1961 T22S R6W $\frac{1}{4}$ S28
 S33
 New BT: 18" I. Cedar N.26 $\frac{1}{2}$ °E. 32.0 ft. Mkd: $\frac{1}{4}$ S28 CS BT.

SEE F.B.
 H-106 FOR
 A HAINES
 STEEL SHAFT
 7/10/61

 CORNER DETERMINED NOT COMMON BY GIS INVESTIGATION
 PER F.L.I. 3/11/92 (Fritz Ingram)