

Douglas County Surveyor's Record of
Government Corners Renewed

22 T. S. 6 R. W. W. M.

ROKE-CHAPMAN CO., EUGENE, ORE. 21881

Section Corner to Sections 18 - 17 - 19 - 20. 90

Found - Haines "T" Iron & cap and Standstone Rock with notches as described. Rock unearth & Fallen over.

Cedar Tree, 48", N.10°E. 14 ft. (to face). Portions of old scribing fd. on badly rotted face. Tree hollowed out by fire, nearly dead.

Badly burned Cedar Snag S. 2°W. 23.8 ft. No scars or scribing. No trace of N.W. Or S.E. BT's.

24" Maple S.37°W. 60.3 ft. scribed, recently; T22SR6WS19BT 363.
50" D.Fir N.31°E. 94.8 ft. scribed in wood, scrbing covered with pitch, except "363".

New BT's: 12" Cedar S.68°E. 28.5 ft. Mkd: T22S R6W S20 CS BT.
17" Maple N.14½°W. 91.2 ft. Mkd: T22S R6W S18 CS BT.

~~Closing Corner to Section 24 and 25. 91~~

~~Found - Haines "T" Iron & Cap - Maple Tree, now 10", S.68°W. 31.0ft., previously opened, old scribing visible in opened face.~~

~~New BT's: 28" R.Cedar N. 8°E. 26.3 ft. Mkd: CC S24 S25 CS BT.
12" Maple S.39°E. 13.5 ft. Mkd: CC S24 S25 CS BT.~~

Section Corner to Sections 16 - 15 - 21 - 22. 92

Found - Irving's Rock with "X" on top & 3 notches on N. S. E. & W. faces. 1" Pipe with elbow driven alongside. - REN. # 13

Fir Tree, now 22", N.21°W. (instead of N.40°W.) 27.1 ft., tree badly burned and face rotted away.

Fir Stump, 22", N.88°E. 32.3 ft. (instead of N.85°E. 38.3 ft.) Cut open scar & fd. good scribing "R6".

Fir Stump, 30", S.12°E. (Instead of S.15°E.) 31.7 ft., shows good scar. - No trace of S.W. BT.

Do Not Set Brass Cap -

New BT's: 12" D.Fir S.27°E. 23.5 ft. Mkd: T22S R6W S22 CSBT.
14" D.Fir N. 9°W. 34.3 ft. Mkd: T22S R6W S16 CS BT.
15" D.Fir N.11°E. 53.3 ft. Mkd: T22S R6W S15 CS BT.
No trees near in S.W.

Section Corner to Sections 17 - 16 - 20 - 21. 93

Found - Fir Tree, now 45", S.32°E. 45.5 ft. Has been chopped open & good scribing "6W" visible on exposed face.

Fir Tree, now 32", N. 5°E. 16.5 ft. shows good scar.

No trace of S.W. BT. A 26" W.Fir stands at location for

Corner - Set Iron Pipe with Brass Cap alongside Mkd: S17 S16
County Surveyor's Office, 1961. S20 S21 T22S R6W

New BT's: 8" Fir S.22°E. 20.5 ft. Mkd: T22S R6W S21 CS BT.
9" Chinquapin N.10°W. 25.8 ft. Mkd: T22S R6W S17 CS BT.
7" Fir N.50°E. 49.0 ft. Mkd: T22S R6W S16 CS BT.
10" Hemlock S.16°W. 45.2 ft. Mkd: T22S R6W S20 CS BT.

Witness Corner to Sections 16 & 15. 94

Found - 36" Fir Stump S.78½°W. 142.6 ft. Stump badly burned but fd. fragments of scribing "SC" on burned face.

Burned remnants of Fir Stump S.24¾°E. 39.6 ft. These two trees were marked by Ben Irving in 1928.

No trace of Rock or Pipe set by Irving: Wit. Cor. as set by Irving falls in center of logging road. - REN. # 17

Set - Wit. Cor. farther South out of logging road, Brass Cap Mkd: County Surveyor's Office, 1961 T22S R6W W.C. ¼ S16/S15.
N. 131.5 ft. to Corner.

New BT's: 13" D.Fir S.37½°W. 7.0 ft. Mkd: WC ¼ S16 CS BT.
8" D.Fir S.18½°E. 18.2 ft. Mkd: WC ¼ S15 CSBT.

True Corner falls in Elk Creek, 131.5 ft. North of Witness Corner.

Milo E. Godfrey, Deputy County Surveyor
Vernon Tracy
Clete Putnam
August - Sept. 1961.
C.S. File No. 49/143

(SEE H-120)