

Douglas County Surveyor's Record of
Government Corners Renewed

22 T. S. 6 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

100

Sec. Cor. to Secs. 5 - 4, T22-6W. & Secs. 32-33, T21-6W.
Found - Rock, Top 4"x 8", with "X" on top & 4 notches on W. Face.
Rotted Remains of Fir Tree N.52°E. 31.0 ft. No scars or
scribing found. (Wright's BT's probably).
Rotted Ring of Fir Stump S.75°W. 22.4 ft. (Gordon & Gardner).
Haines found fragments of reverse scribing on this stump,
pieces fastened by wire to our new N.W. BT.
Old remnants of Cedar Stump S.40°E. 11.2 ft., no scribing (G.&G.)
No trace found of any other old BT's.

Alongside Rock Set Iron pipe with Brass Cap Mkd: "County Surveyor's
Office, 1961

T21S R6W S32/S33
T22S R6W S5/S4

New BT's: 8" D. Fir N.85½°W. 14.2 ft. Mkd: T21S R6W S32 CS BT.
12" D. Fir N.6½°E. 23.4 ft. Mkd: T21S R6W S33 CS BT.
19" D. Fir S.21½°W. 22.7 ft. Mkd: T22S R6W S5 CS BT.
17" D. Fir S.20°E. 20.6 ft. Mkd: T22S R6W S4 CS BT.

101

¼ Sec. Cor. to Sec. 5, T22-6W. & Sec. 32, T21-6W.

Found - Fir Tree, 36", N.47°W. 15.2 ft., uprooted & down, shows
good axe scar at bottom. W. Haines says he found scribing
about 6 years ago. (From position this is lying impossible
to chop open now.

Badly burned Fir Stump bears S.27°E. 13.2 ft. Too much gone to
find scars or scribing.

Set - Iron Pipe with Brass Cap Mkd: County Surveyor's Office, 1961

T21S R6W ¼ S32
T22S R6W S5

New BT's: 38" Fir S.23°E. 45.5 ft. mkd: ¼ S5 CS BT., all in one blaze.
30" Fir S.42°W. 47.7 ft. Mkd: ¼ S5 CS BT., all in one blaze.

102

¼ Corner to Section 4 and 3.

Found - ¾" Iron Pipe at Corner & Old Fir Stump, now 48", S.83°W. 54.1 ft.,
shows good scar. Did not open.

Shell of old Maple S.75°E. 64.0 ft., shows old scar but center
of tree all burned away.

Alongside ¾" I. Pipe Set Brass Cap Mkd: County Surveyor's Office, 1961

T22S R6W ¼ S4/S3.

New BT's: 4" D. Fir N.77½°W. 35.2 ft. Mkd: ¼ S4 CS BT.
6" B. Oak N.23°E. 7.9 ft. mkd: ¼ S3 CS BT.

103

Section Corner for Sections 5 - 4 - 8 - 9.

Found - ¾" I. Rod in E. & W. Fence Line. - No trace of old BT's. found.

Note - Old Maple, 33", bears S.23°E. 3.5 ft. Old axe scars on
S.E. face-directly away from cor.-edges of old face
visible in rotten wood in hollow center of tree, but
no scribing found.

Set - Brass Cap Mkd: County Surveyor's Office, 1961

T22S R6W S5/S4
S8/S9

New BT's: 4" D. Fir S. 5°W. 15.4 ft. Mkd: S8 CS BT.
9" D. Fir N.88°E. 24.6 ft. Mkd: T22S R6W S4 CS BT.
3" D. Fir S.59½°E. 23.6 ft. Mkd: S9 CS BT.
4" D. Fir N.11°W. 9.5 ft. Mkd: S5 CS BT.

- SEE REFERENCE -
POINTS BY HAINES
REN. # 118

104

¼ Corner to Sections 5 and 4.

Found - 1" Bolt with 2½" square head. - Fir Tree; now 66", S.85°W.
56.8 ft. No scars or scribing visible.

Badly burned Fir Stump N.74°E. 81.8 ft. Too much burned away to
find any markings.

Set - Bolt at corner, Brass Cap set alongside Bolt Mkd: County
Surveyor's Office, 1961

T22S R6W ¼ S5/S4.

New BT's: 18" I. Cedar S.56°E. 4.5 ft. Mkd: ¼ S4 CS BT.
24" D. Fir S.24°W. 8.5 ft. mkd: ¼ S5 CS BT.

Milo E. Godfrey, Deputy County Surveyor
Vernon Tracy
Clete Putnam
September 1961
C. S. File No. 49/143