

Douglas County Surveyor's Record of  
Government Corners Renewed

T. 22 S. T.S. R. 6 W. R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

123

Township Corner, Sections 3 & 4, T22-6W.  
Secs. 33 & 34, T21-6W.  
Found - C.S. Brass Cap, properly marked in 1961, in  
corner of new fence, see Ren. #109.  
14" D. Fir N.17°E. 10.7 ft. pitched over scribing.  
10" Yew N.48°W. 49.4 ft. scribing visible.  
26" D. Fir (Grand Fir) S.3°W. 37.3 ft., now snag.  
15" G. Fir S.72°W. 30.4 ft. scribe pitched over.  
New Bearing Tree: 8" Maple S.48°E. 10.5 ft., bark scribed  
with knife, " S 3 CS BT".

Powell, John  
Pete Earle  
L. Lewis)  
V. Yates) Wit.  
C. S.  
File No  
56/38

9/14/73

124

1/4 Corner for Secs. 16 and 21.  
Found - BLM Cadastral Brass Cap, 1963, properly mkd., buried  
at toe of road fill, in good condition.  
39" Fir, now a stump, bears N.55 1/2°E., 3.0 ft.  
with partial scribe "S16" visible, upper part  
of stump badly burnt.  
Record SW BT would be positioned under road fill.  
New BT's - 10" D. Fir, bears N.30°W., 69.2 ft. scribed "1/4  
S16 CS BT"  
12" D. Fir, bears N.21°E., 65.2 ft. scribed "1/4  
S16 CS BT"  
Note - Corner will likely be buried by loose material  
from road fill in near future.

Gary Langlitz  
P. Earle  
C.S. 56/43  
1/28/74

Govt. Cor. Rec. Out 6/21/72 - J. Powell - 1/28/74

125

Sec. Cor. Secs. 4 & 5; Secs. 32 & 33, T21-6.  
Found - 1961 County Surveyors Brass Cap with stone alongside. Ren. No. 100  
8" now 12" D. Fir, bears N.85 1/2°W., 14.2 ft. showing healed blaze.  
12" now 16" D. Fir, bears N.6 1/2°E., 23.4 ft showing healed blaze.  
SW BT is now down.  
17" now 22" D. Fir bears S.20°E., 20.6 ft. showing healed blaze.  
New BT - 20" D. fir, bears S.54°W., 34.9 ft. scribed "T22S R6W S5 CS BT".

Gary Langlitz  
P. Earle  
C. Goodwin  
C.S. 56/43  
2/14/74

2/14/74

126

1/4 Corner for Secs. 12 and 13.  
Found - Haines "T" Iron with copper washer cap. Ren. No. 47  
Orig. BT, 36" D. Fir, now 40" N.14°E., 21.8 ft. Has well healed  
scar, which was not opened. Bark scribe visible reading 1/4  
S12 CS. Haines copper cap nailed to tree  
White Oak BT, 16" South 94.8 ft. is now a 26" stump. Inside  
rotted, shows good revers scribe.  
New BT - D. Fir, 25", N.46°W., 25.8 ft. scribed 1/4 S12 CS BT.  
Corner is outside northeast corner of pasture. Fences bear west and south  
from fence corner.

Gary E. Commons  
P. Earle  
G. Langlitz  
Surveyors Office  
Jan. 10, 1975  
C.S. 57/17

1/10/75

127

1/4 Corner for Sections 22 and 23.  
Found - T Iron by Haines at corner. Ren. #51  
20" Fir, S.74°W., 11.2 ft. orig. BT.  
40" Fir, S.55°E., 9.4 ft. Bark scribed faces.  
14" Fir, S.43°W., 13.1 ft. Bark scribed faces.  
Set - 2" Iron pipe with brass cap marked T22S R6W 1/4 S22/S23 1975  
RPLS 377 & place T iron in hole to south.  
Rescribe - 40" Fir, S.55°E., 9.4 ft. 1/4 S23 BT.

William Eimstad  
for: Cone Lumber  
Feb. 1975  
M 55 - 48

2/75

128

South center 1/16, Section 23  
Found - An orig 10" now 14" Fir, alive and well with visible scribe  
(1/16 S BT) and Haines cap nailed on face bears, N.37°W., 13.8 ft.  
No trace of Haines T-Iron or NE BT (both destroyed by old  
skid road). See M 14-23  
Set - At corner point a 1 1/2" x 30" Iron pipe with brass cap marked:  
County Surveyors Office 1976  
T 22 S R 6 W

M. Lenora Ladig  
L. E. Monrean  
Surveyors Office  
2/23/76  
C.S. 59/8

C  
S1/16 | S23  
C

From which:

An 8" Fir, bears S.19°W., 48.0 ft. scribed "SC 1/16 S23 CS BT" in  
double blaze. Compass Dec. 20° East