

Douglas County Surveyor's Record of  
Government Corners Renewed

22 T. S. 7 R. W. W. M.

KORE-CHAPMAN CO., EUGENE, ORE. BLDG.

J. W. Cole, Deputy

L. H. Smick

Wm. Levins

Felix Hudson

Witnesses

Feb. 1921

Vol. 3  
Pg. 155

✓ COR. TO SEC. 28-29-32-33

Renewed this corner from two original B.T.s. The tree S.83°W. checks for distance and about 2° off for bearing tree N.50°W. checks both for bearing and distance. I set a rock 6" x 6" x 12" also an oak post 4" x 4" x 40" and mark new trees

18

~~RE-RENEWED, SEE CORNER NO. #85~~  
An Oak 12" dia. S.32°W. 18.2  
An Oak 12" dia. N.21°45'E. 55.4

✓ COR. BET 28-29

Renewed this cor. from the original B.T. which are alive and standing, chopped out blaze on tree N.45°E. which shows scribe marks. Set a 4" x 4" x 40" oak post.

19

~~RE-RENEWED, SEE CORNER NO. #86~~

✓ CORNER 19-20-29-30.

Stone in place for corner, but witness trees gone except Oak S.14°W. New highway construction cut another witness tree so marked new witness trees as follows -

20

~~RE-RENEWED, SEE CORNER NO. 25~~  
Black Oak 20" N.63°E. 78.3 feet  
White Oak 18" S.12°E. 110.1 feet  
Black Oak 20" N.21°E. 143.3 feet  
Black Oak 30" S.38°E. 186.6 feet.

✓ COR. BET. 17-16

(F.B.34 Page 4)

Set Cedar post marked C.T.  
Fir 12" S.42°W. 27 lks.  
Fir 14" S.49½°E. 32 lks.

21

~~RE-RENEWED, SEE CORNER NO. 89~~

✓ COR. BET. 17-20

W. Oak 8" N.40½°E. 385½ lks.  
W. Oak 6" S.48°W. 220 lks.

22

~~RE-RENEWED, SEE CORNER NO. 95~~

✓ COR. BET. 8-17

Red Fir 16" S.11°W. 40 lks.  
Red Fir 24" N.9°E. 55 lks. Duplicate of Ren.#26

✓ CENTER SEC. 17

W. Oak 10" S.41°E. 31½ lks.  
W. Oak 8" N.60°E. 27½ lks.  
W. Oak 7" S. 82½°E. 36½ lks.  
W. Oak 6" N.24½°W. 10½ lks.

23

~~RE-RENEWED, SEE CORNER NO. 94~~

✓ COR. BET SECS. 19-20

(F.B. 39 P.11)

Set Oak post for corner  
Fir 20" N.91°E. 87 feet  
Fir 40" N.67°W. 79 feet

24

~~RE-RENEWED, SEE CORNER NO. 28~~

✓ COR. 19-20-29-30

Miss Wells wants to cut 3 B.T.s So re-sets with cor. from all 4 trees. Set 1" x 1" x 36" reinforcing bar from which  
A 26" R. Fir bears S.24°50'W. 82.5 ft.  
A 20" R. Fir bears S.77°E. 125.8 ft.  
A 20" R. Fir bears N.21°E. 143.3 Across Hwy. not to be cut.  
(See also - THELL'S Book 3 Pg 33)

25

~~RE-RENEWED, SEE CORNER NO. #100~~

✓ COR. BET. 8-17

Red Fir 16" S.11°W. 40 lks.  
Red Fir 24" N.9°E. 55 lks.

26

~~RE-RENEWED, SEE CORNER NO. 91~~

S.E. COR. D.L.C. 41

Found 1" iron bar. ~~SEE REN. #7~~  
16" Oak standing  
Blazed and scribed new bearing trees  
30" Fir S 67° E 132.2 ft. Marked S.E. D.L.C. 41 C.S.B.T. O.K.

27

~~RE-RENEWED, SEE CORNER NO.~~

✓ COR. BET. SECS. 19-20

Found 40" Fir Bearing Tree N 67° W, 79.0 ft. Remarked B.T.  
Set ½" I.P. for corner - REN. #24  
New Bearing Tree marked ¼ S 6" B. Oak, bears N 79° 49' W, 58.7 ft.

28

~~RE-RENEWED, SEE CORNER NO. #102~~

Sept. 13, 1934

F. C. Frear

Morris Fowler

Geo. K. Guine

Miss Wells

A.R. Evans - D.C.S.

R.L. Matthews - Witness

Feb. 8, 1950

C.S. 44/18

FB. 34 P.5  
Vol. 2 Pg. 257

FB. 34 P.4