

Douglas County Surveyor's Record of
Government Corners Renewed

T. 22 S. T. S. R. 7 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

Milo E. Godfrey, Deputy County Surveyor
Vernon Tracy & Clete Putnam
April and May 1962
C. S. File No. 52/14

Closing Corner Sections 31 and 32. 117
Found - Sandstone Rock 4" x 10", 10" above surface of ground: "SC"
on S. face. (See Renewal No. 46)
Oak Stump, uprooted & south side rotted away N.14°E. 248.5 ft.
(See Renewal No. 46)
No trace of Renewal B.T. to N.W. - Orig. B.T.'s. gone at time of
old renewal
DID NOT SET BLAZE CAP
New B.T.'s: 15" D. Fir N.36°W. 96.2 ft. Mkd: T22S R7W S31 CS BT.
29" B. Oak N.15°E. 234.0 ft. Mkd: T22S R7W S32 CS BT.
Corner lies in fence corner, fences West & North.

RE-RENEWED SEE CORNER NO. #198

South $\frac{1}{4}$ Corner to Section 31 only. 118
Found - W. Oak, now 28", N.48 $\frac{1}{2}$ °E. 64.7 ft. Cut scar open & fd. good
scribing "SC", approx. 50 years old. (See Renewal No. 46)
Oak Stump N.68°W. 119.5 ft., shows good scar.
Set - Brass Cap at Cor. Mkd: County Surveyor's T22S R7W $\frac{1}{4}$ S31 only
Office, 1962 T23S R7W
New B.T.'s: 7" D. Fir N.33°W. 8.7 ft. Mkd: $\frac{1}{4}$ S31 CS BT.
12" D. Fir N.31°E. 9.3 ft. Mkd: $\frac{1}{4}$ S31 CS BT.
Corner lies in East & West Fence Line.

FD OK BY
5-93 BY
Donald Bentz
M117-6

$\frac{1}{4}$ Corner to Sections 25 and 36. 119
Found - 48" Fir bears S.26°W. 40.9 ft. This BT. shows good scar.
Sandstone 9" x 10" x 12" set about 9" in ground & marked
 $\frac{1}{4}$ on North Face. No trace of other Bearing Tree.
Set - Brass Cap at Cor. Mkd: County Surveyor's T22S R7W $\frac{1}{4}$ S25
Office, 1962 S36
New B.T.'s: 18" D. Fir bears N.56°E. 36.1 ft. Mkd: $\frac{1}{4}$ S25 CS BT.
18" D. Fir bears S.33°W. 21.5 ft. mkd: $\frac{1}{4}$ S36 CS BT.
This corner is about 6.0 ft. South of Creek bottom which bears N.80°W.

Sec. Cor. to Secs. 2 and 1, T22-7W. & Sec. 35 & 36, T21-7W. 120
Found - Haines' "T" Iron & Cap & Fir Stump, now 52", S.36°W. 20.1 ft.,
(instead of 21.1 ft.) scribing visible on old face, stump gd. condtn.
24" Maple S.15°E. 13.2 ft., scribing visible on old face.
No other Bearing Trees found. SEE #45 & 47
New B.T.'s: 28" R. Cedar N.34°W. 52.9 ft. Mkd: T21S R7W S35 CS BT, one blaze.
24" D. Fir N.62°E. 53.0 ft. Mkd: T21S R7W S36 CS BT, bark scribe.
No other trees available in Section 2.

North $\frac{1}{4}$ Corner to Section 6, T23S-R7W, on South Boundary of T22S-R7W. 121
Found - W. Oak, now 27", S. 7°W. 79.2 ft. Chopped open & found good
scribing "S".
30" W. Oak S.20°E. 130.0 ft., shows scar.
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1962
New B.T.'s: 20" W. Oak S. 4°W. 62.3 ft. Mkd: $\frac{1}{4}$ S6 CS BT.
21" D. Fir S.33°E. 59.8 ft. Mkd: $\frac{1}{4}$ S6 CS BT.
Corner is in fence corner - fences E.- W.- & S. from corner.

North $\frac{1}{4}$ Corner Section 1, T23S R7W, South Boundary of T22-7W. 122
Found - Haines' "T" Iron & Cap.
Haines' 28" D. Fir S.46°W. 44.2 ft. bark scribed $\frac{1}{4}$ S1 SC 363 BT.
22" D. Fir S.2°E. 59.5 feet, bark scribed $\frac{1}{4}$ S1 SC 363 BT. 202
Corner recorded in Renewed Corner Book; Corner No. 69; T23S-R7W.

Section Corner to Sections 28 - 29 - 32 - 33. 123
Found - "T" Iron set by Haines in 1961 - M 38-69
Both B.T.'s. mkd. by Cole in 1921
W. Oak, now 33", S.32°W. 16.2 ft., shows good scar.
W. Oak, now 34", N.21 $\frac{3}{4}$ °W. 55.4 ft., shows good scar.
Rock set by Cole out of ground, probably dug out when fence built.
Blaze & Scribe One New BT: 29" W. Oak N.17°E. 72.0 ft. Mkd: T22SR7W S28 CS BT.
Note - Corner is in fence corner - Fences N.- S.- E. & W. from corner.

FD. T. ISON
7/81 R. DUGAN
REN # 85 M 88-27
FD. OK 9/90
M 111-26