

Douglas County Surveyor's Record of
Government Corners Renewed

T. 22 S. T. S. R. 7 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

139
 $\frac{1}{4}$ Corner to Sections 4 and 5.
 Found - "X" on Rock outcropping at corner $\frac{1}{4}$ chisled on Rock south of "X".
 Fir, now 48", S.82°W. 30.0 ft. (not 31.0 ft.) shows good scars. Tree alive but in poor condition.
 No trace of S.E. Bearing Tree.
 New BT's: 6" Hemlock N.56°E. 8.2 ft. Mkd: $\frac{1}{4}$ S4 CS BT.
 17" W.Fir S.20°W. 4.9 ft. Mkd: $\frac{1}{4}$ S5 CSBT.
 (on very steep south slope 160 ft. North of Creek)

C.S. File 52/14

140
 Sec. Cor. to Secs. 4 & 5, T22-7W. & Secs. 32 & 33, T21-7W.
 Found - Fir, now 60", S.45°W. 28.4 ft., chopped open & found good scribing on old face.
 Badly burned Cedar Snag S.30°E. 14.0 ft. No scars or scribing found.
 Fir Snag N.55°E. (not N.65°E.) 4.0 ft. Shows very old axe marks on bark, no scribing found.
 No trace found of Orig. Fir B.T. to N.W. No trace found of Nicklin's N.E. or N.W. BT's.
 No trace of Rock set by Nicklin.
 Set - Brass Cap at Corner Mkd: County Surveyor's Office, 1962

S32	S33	T21S
S 5	S 4	T22S

 R7W
 New BT's: 10" Hemlock N.63°W. 11.1 ft. Mkd: T21S R7W S32 CS BT.
 6" W.Fir S.34°W. 14.3 ft. Mkd: T22S R7W S5 CS BT.
 5" Hemlock S.23°E. 14.2 ft. Mkd: T22S R7W S4 CS BT.
 32" D.Fir N.65°E. 57.2 ft. Mkd: T21S R7W S33 CS BT.

Milo E. Godfrey and Crew
 7/10/62
 C.S. File No.

52/14

141
 South $\frac{1}{4}$ Corner to Section 24 only.
 Set 1" x 1" x 36" T. Iron with Brass Cap.
 Scribed: 20" Fir N.33°W. 21.8 ft.
 12" Fir S.63°E. 73.3 ft.

Wilford N. Haines
 Oct. 1957
 C.S. File No. 42/309

142
 $\frac{1}{4}$ Corner to Sections 27 and 34.
 Found - 24" Fir South 50.0 lks., now 54" Stump. Found T in bark. Position for 12" Fir N.38°E. 22 lks. falls in fire trail built by bulldozer. Found parts of scribe in debris at lower edge of trail about 30 ft. S.W. of this point.
 Set - 1" x 1" x 36" T. Iron
 Scribed - 10" Fir S.29°W. 35.5 ft.
 Mark X B. O. on Rock in place (1 ft. ht. x 3 ft. width.) N.65 $\frac{1}{2}$ °W. 123.4 ft.
 This point is N.89°15'E. 2452.1 ft. from Section Corner to Sections 27 - 28 - 33 - 34.

Wilford N. Haines
 June 29, 1962
 C. S. File No. 51/222

143
 $\frac{1}{4}$ Corner to Sections 28 and 33.
 Set Corner at point halfway between Section Corners.
 Set - 1" x 1" x 36" T. Iron for $\frac{1}{4}$ Corner.
 Scribed - 6" Fir N.23 $\frac{1}{2}$ °E. 10.6 ft.
 Drove bridge Spike in $\frac{1}{2}$ Ft. Stump S.18°E. 13.0 ft.

Milo E. Godfrey, Deputy
 Vernon Tracy
 Mike Stone
 July 13, 1962
 C. S. File No. 52/14

144
 Section Corner to Sections 7 - 8 - 17 - 18.
 Found - Haines' "T" Iron & Cap at Corner & following trees: Ren. #92
 Fir, now 52", S.64°E. 51.9 ft. (record S.60°E. 54.1 ft.)
 Tree previously opened & good scribing "S" visible.
 Fir, now 48", N.17°W. 15.0 ft. (record N.13°W. 15.8 ft.)
 has been opened previously, good scribing visible, recently rescribed in bark "S7". Haines metal disc on both trees.
 Fir, now 45", N.51°E. 69.4 ft. (record N.51°E. 77.9 ft.)
 chopped into but not deep enough to find scribing.
 Corner lies on very steep slope & slope distances fit distance calls on trees.
 Also find stump Hole with rotted Fir wood which fits Orig. S.W. BT.
 Blaze & Rescribe 45" Fir N.51°E. 69.4 ft. Mkd: "T22S R7W S 8 CS BT".