

Douglas County Surveyor's Record of  
Government Corners Renewed

T 22 T. S. R 7 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

- C O N T. -

Gary Langlitz  
K. Cheney  
Doug. Co. Surveyor's Office  
Oct. 26, 1976  
C.S. 59/24

bearing object and it's markings "C1 42" face DLC 39.  
We do not find the bearing object located S.80°W., 50.3 ft. (Ren. #17)  
There is no remaining evidence of the original corner stone or it's BT's.  
We do not set a brass cap due to a soil depth of approx. 1 ft. to bedrock.  
New Bearing Objects:

- A chiseled "X BO" in 3" high letters on exposed bedrock at the top of an approx. 30 ft. high cliff overlooking the Umpqua River, bears S.18°E., 13.4 ft.
- A chiseled " Δ BO" in 2" high letters on exposed bedrock approx. 15 ft. North of the top of a 30 ft. high cliff overlooking the Umpqua River, bears S.81°W., 17.2 ft.

10/26/76

174

FD. OK. 9/10  
M III - 26

1/4 Corner for Secs. 28 and 33.

- Found - Both bearing trees as noted by Haines in Ren. #143 as follows:  
An 8" now 16" D. Fir, alive and well with healed double blaze bears N.23 1/2°E., 10.6 ft.
- A 54" D. Fir stump with bridge spike driven in the center, bears S.18°E., 13.0 ft.

We do not find the "T" iron set by Haines.

At the corner point as determined by the record measurements to the above mentioned bearing trees:

- We Set - A 1" x 30" Iron pipe, 26" in the ground with brass cap attached:  
Douglas Co. Surveyor 1976 T 22 S R 7 W

New BT - A 7" D. Fir, bears S.51°W., 5.9 ft.  
scribed "1/4 S33 CS BT" on a double blaze.

A 5/8" Iron rod bears S.47°E., 3.35 ft. Our records indicate a 5/8" I. Rod as being found at the 1/4 corner in 1974, (See M 53 - 42A), but no indication is made concerning when the 5/8" I.R. was set.

Note: This corner is located approx. 100 ft. N.20°W., of a Cascade Utilities Transmitter.

11/2/76

175

Gary L. Langlitz  
Karen Cheney  
Doug. Co. Surveyors Office  
Nov. 2, 1976  
C.S. 59/26

Witness Corner for 1/4 Cor. for Secs. 2 and 11.

- Found - Haines 1" T Iron NOT FOUND. Ren. #76 Corner falls on NW edge of road.  
A R. Cedar 20" now 28" bears S.14°E., 45.5 ft. Large log covers blaze portion of tree.  
A Maple 16" now 18" bears N.25°E., 42.6 ft. Tree is double blazed partially healed, scribing visible "1/4 S2 BT".
- Set - Temporary point at 1/4 corner as determined by Haines per C.S. M 11 - 72, from which we measure west 17.0 ft. to witness corner.
- Set - Brass cap at witness corner marked "Douglas County Surveyor T22S R7W Wit. Cor. East 17.0 ft. to 1/4 S2 S11 1977"
- Set - Witness post and sign 12 ft. west of wit. cor. monument. this monument is set in a mound of stone at the base of cut bank along NW edge of rad.
- New BT's- A D. Fir 30" bears N.25 1/2°E., 14.4 ft. Tree double blazed and scribed "WC 1/4 S2 CS BT".  
Chiseled "WC X in rock on cut bank on NW edge of road. "X" bears S.75°W., 9.8 ft.

4/25/77

176

L.E. Monrean  
R. B. Kimberling  
Doug. Co. Surveyors Office  
April 25, 1977  
C.S. 59/31

South 1/16 Corner for Secs. 25 and 26

- Found - A 18" now 20" D. Fir is uprooted, orig. position approx. bears N.49 1/2°E., 31.5 ft. with a well healed single blaze.  
A 14" now 20" D. Fir bears N.39°W., 20.4 ft. with a single well healed blaze. M 1 - 59
- Set - A 1" x 36" I.P. with brass cap set at ground level in a terraced area and marked "Douglas County Surveyor" T22 S R7 W S 1/16 S26 S25 1978.
- New BT - A 13" D. Fir bears N.77 1/2°., 24.3 ft. I double blaze and scribe "S 1/16 S25 CS BT"

Corner is on a 40° SE slope, 50 ft. north of a small stream.

5/15/78

177

R. B. Kimberling  
Doug. Co. Surveyors Office  
F. C. Silagy  
May 15, 1978  
C.S. 60/11

1-79