

Douglas County Surveyor's Record of
Government Corners Renewed

T. 22 S. T. S. R. 8 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

(continued from other page)

New BT's: 18" D. Fir N. 2°E. 24.0 ft. Mkd: T22S R8W S11 CS BT.
14" D. Fir N. 40°W. 6.7 ft. Mkd: T22S R8W S10 CS BT.
15" D. Fir S. 18°E. 45.6 ft. mkd: T22S R8W S14 CS BT.
An old fence corner (fences East & South) bears N.E. 2 ft. from corner.
Nov. 19, 1962

Interior L. Corner D. L. C. No. 50. 69
Found - 26" Fir Stump N. 67°W. 26.4 ft., shows 2 good scars., REN. #53
Cut open & found scribing. No other BT's. found.
At Corner Drive $\frac{3}{4}$ " Iron Reinforcing Rod, in travelled portion of roadway.
Blaze & Scribe One new Tree: 15" W. Oak N. 53 $\frac{1}{2}$ °W. 96.2 ft. Mkd:
"Int. L. DLC 50 CS BT".

*FD. 4/89
D. BAKER
M 101-54*

Section Corner to Sections 9 - 10 - 15 - 16. 70
Found - 65" Fir S. 89°W. 37.6 ft., old bark scribing visible.
44" Fir Stump S. 38°E. 81.8 ft., shows good scar.
Old Fir Snag, badly rotted, N. 36°W. 88.4 ft. (Record bearing
N. 40°W., dist. is 134 lks., not 154 lks.) Wood scribing visible.
Clump of Maples N. 80°E. 48.8 feet.

Set - Brass Cap at Cor. Mkd: County Surveyor's T22S R8W $\frac{S 9}{S 16} | \frac{S 10}{S 15}$
Office, 1962

New BT's: 20" D. Fir N. 35°W. 67.2 ft. Mkd: T22S R8W S9 CS BT.
18" D. Fir North 35.5 ft. Mkd: T22S R8W S10 CS BT.
15" Maple S. 10°E. 33.7 ft. Mkd: T22S R8W S15 CS BT.
Corner lies on steep N. E. slope approximately 100 ft. North of ridge top.

Milo E. Godfrey, Deputy County Surveyor
Vernon Tracy and Mike Stone
November and December 1962
C. S. File No. 52/14

Section Corner to Sections 3 - 4 - 9 - 10. 71
Found - 36" old Fir Stump S. 38°E. 49.5 ft., cut open & fd. good scrbing.
24" Fir Snag N. 62°E. 31.0 ft., shows very good scar.
35" Fir Stump N. 66°W. (not N. 60°W.) 63.4 ft. Fd. good rev. scrbing.
Portion of badly rotted Fir Stump S. 70°W. 56.1 ft. No marks found.

*FD OR 5/86 BY ROBERTS
C.S. 63/18 & M 101-54 5/89
D. BAKER*

Set - Brass Cap at Cor. Mkd: County Surveyor's T22S R8W $\frac{S 4}{S 9} | \frac{S 3}{S 10}$
Office, 1962

New BT's: 23" D. Fir N. 45°W. 56.8 ft. Mkd: T22S R8W S4 CS BT.
12" W. Fir N 76 $\frac{1}{2}$ °E. 88.6 ft. Mkd: T22S R8W S3 CS BT.
10" W. Fir S. 73°E. 68.0 ft. Mkd: T22S R8W S10 CS BT.
12" W. Fir S. 38 $\frac{1}{2}$ °W. 28.6 ft. Mkd: T22S R8W S 9 CS BT.
Found $\frac{3}{4}$ " Iron Pipe S. 35°E. 1.5 ft. from corner.

*(see #11)
7.22-7*

$\frac{1}{4}$ Corner to Sections 15 and 14. 72
Found - Fence Corner - Fences South - East & N. 33°W.
Old Oak, down & badly rotted, S. 41°E. 121.4 ft. Found old REN. #54
axe marks & fragments of old face., scribing completely
rotted away.

No trace found of Orig. S.W. tree.

Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1962
T22S R8W $\frac{1}{4}$ S15/S14

New BT's: 32" W. Oak S. 31°E. 28.0 ft. Mkd: $\frac{1}{4}$ S14 CS BT.
10" D. Fir N. 25°W. 102.4 ft. Mkd: $\frac{1}{4}$ S15 CS BT.
See Germond's Renewal #54; 1916, and affidavit of Henry Brown on
reverse side of this sheet (field notes in C. S. File No. 52/14).

$\frac{1}{4}$ Corner to Sections 12 and 13. 73
Found - Rock set by Cole in 1913 (top 4" underground). No marks on rock.
38" W. Oak N. 40 $\frac{1}{2}$ °E. 273.2 ft. Cut open & found good reverse
scribing $\frac{1}{4}$ ", center rotted away, tree hollow. REN. #44
Portion of rotted Maple Stump (in place) S. 72°E. 63.1 ft.
Too far gone to find scribing.

No trace of eith Original Bearing Tree.

Set - Brass Cap at Cor. Mkd: County Surveyor's T22S R8W $\frac{1}{4}$ $\frac{S 12}{S 13}$
Set Rock Alongside. Office, 1962

New BT's: 13" B. Oak S. 17 $\frac{1}{2}$ °W. 43.7 ft. Mkd: $\frac{1}{4}$ S13 CS BT.
7" D. Fir N. 9°W. 38.3 ft. Mkd: $\frac{1}{4}$ S12 CS BT.
A fence corner, fences East - West and North bears S. 60°W. 13.0 feet.

*FD OR 9/85
L. ROBERTS
M 99-71 E
M 90-74*