

Douglas County Surveyor's Record of
Government Corners Renewed

T. 22 S. T. S. R. 8 W. R. W. W. M.

ROKE-CHAPMAN CO., EUGENE, ORE. 21881

S 1/16 Sections 13 and 18. 91

Found - Gov't Brass Cap set in 1931.

38" Fir N.0°45'E. 73.3 ft., shows good axe scar.

30" Fir S.61½°W. 29.7 ft. is now down, recent uproot, shows good axe scar.

New BT: 19" D.Fir N.72°W. 77.0 ft. Mkd: "S 1/16 S13 CS BT".

¼ Section Corner to Sections 18 and 19. 92

Found - Gov't. Brass Cap set in 1931, good condition.

40" D.Fir N.36°W. 17.2 ft., shows scar.

30" Fir S.3½°W. 38.9 ft. is uprooted & down-(not recent)-nearly buried. Did not hunt for scars.

New BT's: 19" D.Fir N.52°W. 11.1 ft. Mkd: "¼ S18 CS BT".

6" Hemlock S.29°E. 35.1 ft. Mkd: "¼ S19 CS BT".

Wit. Cor. to Meander Corner R9W S13/S18-R8W T22S (LEFT BANK) 93

Found - Brass Cap set in 1931, now buried 18" below surface of sand.

Dead Alder Snag S.54°W. 50.2 ft. Did not look for scribing, snag badly rotted.

Remains of rotted Alder Stump S.40°E. 48.2 ft. Too far gone to find markings.

Set - 2" Iron Pipe alongside Brass Cap, extends 16" above present level of sand.

New BT's: 16" Maple S.42°E. 48.2 ft. Mkd: WC MC S18 CS BT.

11" Maple S.63°E. 32.0 ft. Mkd: WC MC S18 CS BT.

No trees worth marking west of line.

Section Corner to Sections 18 & 19, T22-8W. & Secs. 13 & 24, T22-9W. 94

Found - Gov't. Brass Cap set in 1931.

10" Hemlock, now 20", N.76°W. 22.4 ft., shows good scar, Did not open.

Shattered Cedar Snag N.51½°E. 56.8 ft., fragmentary scribing visible on badly charred face, none legible.

No trace of either the S.E. or S.W. trees mkd. in 1931.

New BT's: 26" Hemlock N.88°E. 32.6 ft. Mkd: T22S R8W S18 CS BT.

9" Hemlock S.80°W. 33.6 ft. Mkd: T22S R9W S24 CS BT.

18" Alder S.53°E. 6.0 ft. Mkd: T22S R8W S19 CS BT.

Corner lies on very steep north slope, approx. 600 ft. West of Creek, (Gov't. notes, 1931, call for corner 3.54 chains west of creek.).

Section Corner to Secs. 28 - 29 - 32 - 33. 95

Found - Brass Cap set by Cadastral Survey in 1960.

7" W.Fir N.38°W. 29.7 ft., scribing visible in nearly healed scar.

9" D.Fir S.35°W. 67.3 ft., scar pitched over.

30" Madrone S.52°W. 51.5 ft. Blaze & Rescribe this Tree:

"T22S R8W S32 CS BT".

24" Madrone S.61°E. 33.0 ft. Blaze & Rescribe this tree:

"T22S R8W S33 CS BT."

48" D.Fir, (not called for in notes) N.68°E. 44.2 ft. mkd:

T22S R8W S28 BT.

¼ Corner to Sections 5 and 8. 96

Found - 62" W. Oak N.85°W. 419.8 ft., opened & found straight portion of scribe mark, also reverse on overgrowth. Center portion of face had rotted away before healing over.

No trace of S. W. Bearing Tree.

Set - Brass Cap at Cor. Mkd: County Surveyor's T22S R8W ¼ $\frac{S}{S} \frac{5}{S}$ Office, 1963

Cap buried 12" below ground surface in field.

28" W.Oak scribed "¼ S8 BT" by cadastral survey, 1963 bears S.28½°E. 225.7 ft. I add scribing "CS".

New BT's: 14" W.Oak S.14½°W. 359.3 ft. Mkd: ¼ S8 CS BT.

No suitable trees near to north of line.

Brass Cap set by Cadastral Survey, 1963, (top buried 24" below ground surface), bears S.59°E. 89.7 feet.

Milo E. Godfrey, Deputy County Surveyor
James Byron - Mike Stone
August 1963
C. S. File No. 52/14

September 1963