

Douglas County Surveyor's Record of
Government Corners Renewed

T. 22 S. T. S. R. 8 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

104

Witness Corner to South $\frac{1}{4}$ Corner Section 34 only.
(on N. Line Section 3, T22S R8W)

Found - Brass Cap set in 1952.

Sawed Stump of 27" Fir N. $54\frac{1}{2}^{\circ}$ E. 25.7 ft., shows good wear.
No trace of Northwest BT.

Fir Tree at $\frac{1}{4}$ Corner, 2 ft. W. of Wit. Cor., alive & in good
condition, shows good scars.

50" Fir S. $11\frac{1}{2}^{\circ}$ W. 27.1 ft., alive & in good condition. Traces
of bark scribing visible.

Stump of 35" Fir N. $27\frac{1}{2}^{\circ}$ E. 11.2 ft., bark scribing visible.

New BT: 12" Hemlock S. 17° E. 15.2 ft. (from brass cap) mkd: $\frac{1}{2}$ S34 CS BT.

No live trees available north of line.

Note - Corner lies on top of ridge, just south of south edge of logging road.

RENEWED CORNER NO. #165

105

Closing Corner for Sections 4 and 3.
(on S. Line Section 33, T21S R8W)

Found - Brass Cap, 1945 survey, in ground. Had obviously been recently
reset, didn't fit bear. or dist. to old BT's.

Reset Brass Cap in proper position from 2 old BT's.

54" Fir S. 62° W. 25.1 ft., portions of old scribing visible
on badly burned face.

32" Fir Stump, cut off approx. 8 ft. above ground, S. $11\frac{1}{2}^{\circ}$ E.

17.2 ft. Cut open & find good scribing "W" on old face.

Reblaze & Scribe 54" D. Fir S. 62° W. 25.1 ft. Mkd: "T22S R8W CC S4 CS BT".

New BT: 48" Fir Stump N. 32° E. 78.2 ft. Mkd: T22S R8W CC S3 S4 CS BT.

No live trees available.

From Corner as reset by Godfrey, the position where Brass Cap was found
set bears N. $38\frac{1}{2}^{\circ}$ W. 14.5 ft.

RENEWED CORNER NO. #167

Milo E. Godfrey, Deputy County Surveyor
Wm. Stoffel and Mike Stone
September 1963
C. S. File No. 52/14

106

$\frac{1}{4}$ Corner to Sec. 7, T22-8W. & Sec. 12, T22-9W.

Found - Dead Fir Snag 22" diam., & approx. 35 ft. high.

Dead Fir Snag, 18" diam., & approx. 20 ft. high, N. 50° W. 13.2 ft.,
opened & found good scribing "BT".

Rotten piece of Fir Stump S. 30° E. 7.2 ft., too far gone to
find any markings.

Set - Wit. Corner 6 ft. N. of $\frac{1}{4}$ Corner.

Brass Cap for Cor. Mkd: County Surveyor's Office, 1963

T22S R9W W.C. $\frac{1}{4}$ S12/S7 R8W 6 ft. S. to Corner.

New BT's: 27" Fir Stump N. 40° W. 19.0 ft. Mkd: W C $\frac{1}{4}$ S12 CS BT.

27" Fir Snag S. 84° E. 31.6 ft. Mkd: W C $\frac{1}{4}$ S 7 CS BT.

No live trees available.

PAO OK 8/91
H. Wilcox M113-60

107

Section Corner to Secs. 6 & 7, T22-8W. & Secs. 1 & 12, T22-9W.

Found - 1" Iron Pipe extending 18" above ground surface.

45" Dead Fir, N. 45° W. 4.0 ft., bark scribing (not orig) found,
T22S R9W S1. No orig. scribing found, bark badly burned.

60" Dead Fir N. 32° E. 15.8 ft., bark scribing, not orig.,
"T22S R8W S6 BT". No orig. scribng. found, bark badly burned,
yellow tag dated 4/27/54.

24" Fir Stump S. 42° W. 27.7 ft., stump cut low, no marks found.
No trace of S.E. Bearing Tree.

16" Fir Snag, approx. 10' high, scribed in wood "T22S R8W S7"
S. $77\frac{1}{2}^{\circ}$ E. 35.3 ft., yellow tag dated 4/27/54. (not orig. BT)

20" Fir Stump, 5' high, bark scribing, "T22S R9W S12 BT", S. 65° W.
27.0 ft., yellow tag dated 4/27/54. (not orig. BT.)

Set - Brass Cap alongside I.P. Mkd: County Surveyor's Office, 1963
T22S R9W $\frac{S1}{S6}$ $\frac{S12}{S7}$ R8W

Rescribe, in bark, 45" Dead Fir N. 40° W. 4.0 ft. Mkd: T22S R9W S1 CS BT.
No live trees available.